WARNER SOIL & GEOLOGICAL SERVICES, INC.

JOEL B. WARNER, P.G.

6263 Sharewood Forest, Morganton, GA 30560-1411 Phone & Fax: (706) 374-2188

COUNTY: Union DATE: May 23, 2007

OWNER: William & Linda Davis

SITE LOCATION ADDRESS: Hawksclaw Rd.

PHONE NUMBERS: (727) 410-8313 or (727) 376-9354

SUBDIVISION: Hawksclaw Estates LOT NUMBER(S): 5

SCALE: 1" = 100' QUAD MAP: Culberson

INTENSITY LEVEL OF INVESTIGATION: 3 SOIL SURVEY MAP SHEET NO. 5

APPROX. ELEVATION: 2,121 ft. GPS: N34° 58.727' W84° 07.267' Form 1.94

SOIL PROPERTIES

BORING NUMBER	SOIL SERIES SEE SUITABILITY CODES	SLOPE % ranges of the soil type	TOTAL DEPTH OF BORING (Inches)	DEPTH TO BEDROCK (Inches)	DEPTH TO SEASONAL HIGH H ₂ 0 TABLE (Inches)	ABSORPTION RATE AT RECOMMENDED TRENCH DEPTH (Min/Inch)	RECOMMENDED TRENCH DEPTH (Inches)	SUITABILITY CODE (listed below)
B-1	Thurmont	10-12	63*	>63*	>72†	35-40	24-30	A
B-2	Evard	12–15	73	>73	>73	40-45	24–30	A
В-3	Clifton-Evard	8–10	51*	>51*	>72†	45	24	A
B-4	Clifton-Evard	10–12	74	>74	>74	35-40	2430	A
B-5	Evard	2	57*	>57*	>72†	30	24	A

SUITABILITY CODE DESCRIPTIONS AND GENERAL NOTES

(From pages C-18-33 and C-18-34 in GA Manual for On-Site Sewage Management Systems)


- * Auger refusal on rippable, weathered, quartz/quartzite boulder or metaquartzite cobble.
- † From Soil Series Table of Manual For On-Site Sewage Management Systems.
- A These soils are suitable for installation of on-site systems with proper system design, installation, and maintenance. Position of the site or other soil and landscape considerations may require the drain field area to be greater than the minimum and/or the drain field design to require equal distribution or level field installation.

Boring locations illustrated on the soil map were located from an existing corner pin using a hip chain and a Brunton compass. A 3½-inch hand auger was used for soil sample collection. A Munsell Soil Color Chart was used to determine the soil color.

WARNER SOIL & GEOLOGICAL SERVICES, INC.

JOEL B. WARNER, P.G.

6263 Sharewood Forest, Morganton, GA 30560-1411 Phone & Fax: (706) 374-2188



WARNER SOIL & GEOLOGICAL SERVICES, INC.

JOEL B. WARNER, P.G. 6263 Sharewood Forest, Morganton, GA 30560-1411 Phone & Fax: (706) 374-2188

SUPPLEMENT TO SOIL TEST REPORT for William & Linda Davis

COMMENTS


Six soil test holes were hand-augered on the Davis property, Lot 5 of Hawksclaw Estates subdivision, a 3.061-acre parcel bordered on the north by Hawksclaw Rd.

A tentative house site has been flagged, and hole locations were selected in areas that would accommodate an absorption field near the house site, avoid the proposed driveway and remain outside the 100-foot setback from the backup community well.

The State has mapped the soils in this area as Clifton-Evard and Cowee-Evard complexes with nearby area of Thurmont fine sandy loam. Clifton-Evard soils are well drained, moderately permeable and occur on uneven ridges and side slopes of intermountain uplands. The soils form from weathered granite or gneiss and are commonly interbedded with weathered mica schist. Thurmont soil is well drained, moderately permeable and occurs on stream terraces and toe slopes. This soil forms from fine loamy sediments interbedded with gravels and quartzite fragments. No Cowee-Evard soil was encountered by sandy Evard soil was found. Evard soil is very deep, well drained, moderately permeable and occurs on ridges and side slopes of the Blue Ridge. It forms in residuum affected by soil creep in the upper part and weathered from felsic to mafic, igneous and high-grade metamorphic rocks such as mica gneiss. Slopes, typically 15 to 50 percent, can range from 2 to 95 percent.

Hole B-1 was augered to 63 inches in Thurmont soil. Auger refusal was due to a quartz/quartzite boulder. Holes B-2 and B-5 were augered to 73 and 57 inches, respectively, in Evard soils. Auger refusal in B-5 was due to a weathered quartzite boulder. Holes B-3 and B-4 were augered to 51 and 74 inches, respectively, in Clifton-Evard soils. Clifton was added to the classification because of the yellow color and mica content. Auger refusal in B-3 was due to metaquartzite cobbles.

All the borings encountered sandy soils with good absorption rates. A septic tank and absorption field should function satisfactorily if designed, installed and maintained properly.



RENCE PLAT RECORDED IN PLAT BOOK T, PAGE 103, UNION COUNTY RECORDS.
RENCE PLAT BY ROCHESTER & ASSOC. FOR HENRY & ELIZABETH HUTCHENSON
MAY 10, 1995.

RENCE PLAT RECORDED IN PLAT BOOK P, PAGE 134, UNION COUNTY RECORDS.
ENCE PLAT RECORDED IN PLAT BOOK G, PAGE 222, UNION COUNTY RECORDS.
ENCE PLAT RECORDED IN PLAT BOOK N, PAGE 8, UNION COUNTY RECORDS.
ENCE PLAT RECORDED IN PLAT BOOK S, PAGE 238, UNION COUNTY RECORDS.

