Area	Item	Year	Comments
ouse	Air Conditioning	1999	High Efficiency Trane * 200-amp main service, circuit-breaker-panel. Entire house has been rewired with romex.
			* 70-amp service panel to garage
			* 100-amp service panel to out-buildings
	Electrical	1998	* Off-peak electric on A/C, Water Heater, Boiler, and Hot tub
			* Gas fireplace w/ electronic ignition
	Fireplace	2002	* Wireless remote control; temperature, flame control, fan speed; also has delay timer
10000			Limestone brick; 12-inches thick; Does pick up moisture in summer months, but solid as a rock.
			* Water abatement steps taken in 2016. Placed doubled 8-mil plastic around NW corner of house to divert water
	Foundation	1894	away from house. Re-landscaped area and leveled AC unit.
			* White aluminum clad exterior, oak interior
	월 - 2 IP 및 1999 (1996)		* High-efficiency gas-filled panes w/ grids in glass
	and the second second		* French style door w/ access to front porch
	Front door	2002	* In-swing main doors w/ out-swing screens
		2002	Vertical adjusting hinges Kestored tongue-and-groove cedar decking (Recovered from 100-year-old farm house.)
			* Restored oak posts, spindles, scroll-work (Recovered from 100-year-old farm house.)
			* Covered porch w/ bead-board ceiling
			* Porch swing
			* Restyled sunburst designed to match back door, inlayed into the gable end of the porch
A CONTRACTOR	Front Porch	2000	* Repainted and stained 2016.
			* High Efficiency Trane
	Furnace	2003	* April-aire humidifier
	Can	1000	* Home serviced by LP; rented 1000 gal LP tank
	Gas	1999	* All gas lines have been installed and/or checked by local gas company Colonial style Sait Box built in 1694
			* A Dunn Country original that served as a boarding house on a stage-coach line
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		* Primarily stick-built construction; house has been re-decked and wrapped with vapor barrier
			* Oak and maple hardwood flooring throughoutcompletely restored original hardwood
			* Lath and plaster has been removed; entire house has been insulated and sheetrocked
			* R-19 walls, R-40 attic
			* Oak staircase
	House	1894	* Built-in oak cabinets
	Kitchen Appliances	Various	* Kenmore Refrigerator (2000), Dish Washer (2009), Gas Range (2010), Microwaye w/ vent hood (2011).
	Laundry	2005	* Second floor laundry in bathroom; laundry hook-up with built-in floor pan and drain;
	Datio	1000	* 13 x 26 brick patio w/ access walkway out to yard, side porch.
	Patio	1999	Patio is covered by a pergola and surrounded with river-rock. Entire house has been re-plumbed
	Constant States		Copper piping throughout
			Copper piping throughout PVC drain system w/ new main stack
			Easy access to second floor plumbing
	Plumbing	1999	* Whole-house water filters
	. ismenig	1000	Whole-house water inters Wirsbo in-floor heating system in the addition.
	The second second		* Thermostat control in addition only
	Radiant Floor Heat	2003	* Boiler heating on off-peak electric
	Roof	2016	* 25-year shingles
	Septic	1996	* Sized for family of 5; serviced bi-annually
	the second s		* 7 x 16 with stair access to garage
			* Covered and lit entry-way.
	Side Porch	2000	* Antique sun-burst adorns the entry way. (Recovered from 100-year-old farm house.)
			* White vinyl
	Siding	2001	* 4-inch lap siding
	Water Heater	2001	50-gal insulated electric water heater
	Well	1994	* Not much information
	Well Pressure Tank	2016	* July * Crestline
			* Double-hung, grid-in-glass, argon-gas filed, double pane, aluminum clad exterior (white), wood interior.
	A REPORT OF THE		 Solid oak extension jambs throughout entire house
	Windows	2000	* Windows in high-moisture areas are white vinyl
	VVIII dows	2000	
			* River rock is placed around the patio and the back of the house with red bullet-brick edging
andscaping	House	2016	* Many annuals are planted around the house: hostas, rose bushes, etc
			* Built-in flowering beds on South side of house
			* Integrated drain system
			* Area covered in cedar-bark mulch
	Retaining Walls	2005	* Annuals are planted throughout
	Garden	2006	* Currently nothing planted.
	Wild Flower Garden	2006	
	Patio	1999	* Pergola covers the back patio; repainted 2016.
			* 28 x 40 garage; poured slab with reinforcing rebar and liberglass
		ALC: NO.	* 4-stall garage
			* 2 8' x 16' garage doors; 1 door has garage door opener.
Garage		and the second	* Overhead lighting
	Garage	1996	* New roof in 2016
	Apron	2002	* 20 x 40 concrete slab w/ basketball hoop
	Driveway	2002	* 10 x 100 concrete driveway
	and the second		* Pole shed w/ 12-foot sidewalls; poured slab
1 5 3 C		States States	* 30 × 40
Barns	Machine Shed	?	* Needs East wall repair work
		Burn Street and	* Quonset style steel structure w/ second floor hay loft
	Section Section 1	Section States	* 5 oak horse stalls w/ tack room
	Lines De	0	* 40 x 60
	Horse Barn	1	Needs foundation concrete work on one corner Pole chod
	the second s	A State State State State	* Pole shed
	and the second second		* 30 x 40
	Storage Shad	2	* Manufa some autile and and and
	Storage Shed	?	* Needs some gable-end post work
Acreage		?	
Acreage	House	?	* 3 acres
Acreage	House Field	?	* 3 acres * 11 acres
Acreage	House	?	* 3 acres