

HENDRICKSON WELL DRILLING, INC.

77483 SOUTH 6TH STREET COTTAGE GROVE, OR 97424

(541)942-0843 FAX (541)767-9820

CCB# 69957 WWC# 1553 DEQ# 36884

Septic Inspection Report

Client/Realtor Billing Address
Charles & Donna Hudson
77768 Gillespie Road
Dorena, OR 97434

Property Address
77768 Gillespie Road

Cost: \$150.00

Date: 3/9/2010 Condition of Contents: _____

Amount of top cake sludge: 0 "

Amount of bottom sludge: 0 "

Ran Water for 15 minutes in tank:

Yes ☒

No ☐

Tank level change

Yes ☐

No ☒

Baffles in place in tank:

Yes ☒

No ☐

Recommend tank to be pumped:

Yes ☐

No ☒

Tested by: Chet Hendrickson

Comments: *Chet Hendrickson*

Tank in good condition.

Yes ☒

No ☐

Distance from septic tank to well 100+'

Distance from septic tank to drainfield N/A

Distance from well to drainfield 100+'

Based on what we were able to observe and our experience with on-site wastewater technology, we submit this Sewage Treatment System Evaluation Report based on the present condition of the on-site treatment system. Hendrickson Well Drilling has not been retained to warrant, guarantee, or certify the proper functioning of the system for any period of time in the future.

Numerous factors: usage, soil characteristics, previous failures, etc., may effect the proper operation of a septic system and our inability to supervise or monitor the use or maintenance of the system prevent this report from being construed as a warranty by our company that the system will function properly for any particular buyer.

Hendrickson Well Drilling disclaims any warranty, either expressed or implied, arising from the evaluation of the septic system or this report. We also do not ascertain the impact the system is having on the ground water.