TERRANCE MISH
PROFESSIONAL LAND SURVEYOR
NO. 4981
DRAWING NO. SA2014—02478
OCTOBER 21, 2014

HEREBY CERTIFY THAT HIS SUPRY WAS MADE PEPPESENTS THE FOUND AT THE FOR THE COUND THE THE PEPPESENTS THE FAULT THE PEPPESENT AND THAT THERE ARE PURCONCHMENTS APPARENT ON THE GROUND, SCREPT AS SHOWN HEREON, THIS SUPPEY IS SERTIFIED FOR THIS TRANSACTION ONLY.


(SEE ATTACHED METES AND BOUNDS DESCRIPTION)

C.C.L.=DIRECTIONAL CONTROL LINE ECORD BEARING: DOC. NO. 20131619

DRAWN BY: BR

PRECISION SURVEYORS





THIS PROPERTY DOES NOT LIE WITHIN THE 100 YEAR FLOOD PLAIN AS ESTABLISHED BY THE U.S. DEPT. OF HOUSING & URBAN DEVELOPMENT. COMMUNITY/PANEL NO. 48171C 0288 C MAP REVISION: 10/19/2001

A SUBSURFACE INVESTIGATION WAS BEYOND THE SCOPE OF THIS SURVEY

BASED ONLY ON VISUAL EXAMINATION OF MAPS. INACCURACIES OF FEMA MAPS PREVENT EXACT DETERMINATION WITHOUT DETAILED FIELD STUDY

NOTE: MAY BE SUBJECT TO DEED RESTRICTIONS AND/OR NOTIFICAL CONFINANCIAL BUILDING RECOURGEDITS.

NOTE: THIS SURREY WAS PREPARED, WHI FOUR ATTLE COMMITMENT, OTHER BUEDREYS AND/OR BUILDING LINES MAY AFFECT THIS TRACT.