

STATE OF TEXAS WELL REPORT for Tracking #191671

| | | | |
|-------------------------------|--------------------------------------------------------------|-------------------------------|-----------------------|
| Owner: | Royce Wallace | Owner Well #: | 5457412 |
| Address: | 1360 CR 4727 Troup, TX 78759 | Grid #: | 69-26-6 |
| Well Location: | 5 Mi.NorthConCan Big Shades Sub. ConCan, TX 78838 | Latitude: | 29° 34' 17" N |
| Well County: | Uvalde | Longitude: | 099° 45' 21" W |
| Elevation: | 1599 ft. | GPS Brand Used: | Garmin |
| Type of Work: New Well | | Proposed Use: Domestic | |

Drilling Date: Started: **8/11/2009**
 Completed: **8/11/2009**

Diameter of Hole: Diameter: **8.75 in From Surface To 25 ft**
 Diameter: **77/8 in From 25 ft To 240 ft**

Drilling Method: **Air Rotary**

Borehole
Completion: **Open Hole Straight Wall**

Annular Seal Data: 1st Interval: **From 0 ft to 20 ft with 8 Cement (#sacks and material)**
 2nd Interval: **No Data**
 3rd Interval: **No Data**
 Method Used: **Poured**
 Cemented By: **Wilson Well Service**
 Distance to Septic Field or other Concentrated Contamination: **N/A ft**
 Distance to Property Line: **80 ft ✓**
 Method of Verification: **Estimated**
 Approved by Variance: **No Data**

Surface
Completion: **Surface Sleeve Installed**

Water Level: Static level: **168 ft. below land surface on 8/11/2009**
 Artesian flow: **No Data**

Packers: **Rubber 620,640,320,300, Plastic 10**

Plugging Info: Casing or Cement/Bentonite left in well: **No Data**

Type Of Pump: **No Data**

Well Tests: **Estimated**
 Yield: **12 GPM with 0 ft drawdown after 1 hour ✓**

Water Quality: Type of Water: **Fresh**
 Depth of Strata: **168-190 ft. ✓**
 Chemical Analysis Made: **No**
 Did the driller knowingly penetrate any strata which contained undesirable constituents: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for completion and resubmittal.