675 08W 13 BA State

## 413-013802-00 LINDSAY DRILLINGWELL LOG REPORT933-5511 • Fax 406-933-8140

Visit us at www: lindsaydrilling.com



1. WELL OWNER:

John Moylan

2. CURRENT MAILING ADDRESS:

P.O. Box 1411

Dillon. MT 59725-1411

3. WELL LOCATION: Trista Drive

A) COUNTY: Beaverhead

B) TOWNSHIP/RANGE:

1/4 nw 1/4 07s 08w 13 ne

sub: Vailey View Farm Lots 86 KJ

4. USE: Domestic

5. DRILLING METHOD: Air Rotary

6. DIMENSIONS:DIAMETER OF HOLE

SIZE FROM-TO HOLE (FEET)

0 - 181

7. CONSTRUCTION DETAILS:

**CASING SIZE** 

6 5/8#17

+2 - 181

PERF. 115-120; 135-140

SCREEN

GROUTING DEPTH: 20 ft.

**GROUTING MATERIAL: Bentonite** 

8. WELL TEST DATA:

A) TESTING MEANS: Air Lift

B) STATIC LEVEL AT TIME OF DRILLING 70

C) DEPTH OF TEST 181

D) GPM 30

E) PUMPING LEVEL 177

F) PUMPING TIME

l hr.

G) RECOVERY LEVEL:

70

H) RECOVERY TIME

1 hr

9. WAS WELL ABANDONED? no

10. WELL LOG

0-4 Topsoil

4 - 60 Clay & gravel

60 - 115 Clay

115 - 120 Gravel

120 - 135 Clay

135 - 140 Gravel

140 - 180 Clay

180 - 181 Mudstone

11. DATE COMPLETED:

9/26/00

DRILLER/CONTRACTOR CERTIFICATION:

THIS WELL WAS DRILLED UNDER MY **JURISDICTION AND THIS REPORT IS TRUE** TO THE BEST OF MY KNOWLEDGE.

CELEBRATING 51 YEARS IN BUSINESS!! LINDSAY DRILLING:

Montana Department of Natural Resources and Conservation

P.O. Box 201601 \* 21 North Last Chance Gulch \* Helena, Mt. 59601 \* Phone 449-0944

Domestic Water Wells • Pump Sales & Service • Large Commercial & Irrigation Systems

W: 185945

ok