DocuSign Envelope ID: 682E6486-5964-465F-A79B-6062048CE9E6

lood Destroying Insect Inspection Report	Company's Pest Contro	ol Business Lic. N	o. Date of Inspection	n
spection Company, Address & Phone	PBL 247 8/2/2022 Address of Property Inspected			
Kinzie Pest Control - Emporia	Address of Property In:	spectea		
01 Martin Drive	26769 S Ratner			
nporia, KS 66801-8920	Quenemo, KS 66528			
20) 342-4222				
pector's Name, Signature & Certification, Registration, or Lic. # /on Estes - 14146	Bart	Structure(s) In Single family h		
ction II. Inspection Findings This report is indicative of the co	ntestations or wood desire	tified structure(s) o bying insect damag	on the date of inspectinge. Based on a caref	on and is not to be ful visual
spection of the readily accessible areas of the structure(s) inspected	d:			
A. No visible evidence of wood destroying insects was observed.				
B. Visible evidence of wood destroying insects was observed as follow				
1. Live insects (description and location):				
2. Dead insects, insect parts, frass, shelter tubes, exit holes, or sta beneath basement stairs.	ining (description and loc	ation): Termite_m	ud staining in rim jo	oist in closet
			~	
3. Visible damage from wood destroying insects was noted as foll main crawlspace opening in basement.	lows (description and loca	ition):Termite dar	nage in sub-floor as	s seen from
	ked it chould be under	tood that some (	legree of damage. in	cluding hidden
DTE: This is not a structural damage report. If box B above is check mage, may be present. If any questions arise regarding damage indicated	led by this report, it is rec	ommended that th	e buyer or any interes	sted parties contai
mage, may be present. If any questions arise regarding damage indication qualified structural professional to determine the extent of damage and the	ne need for repairs.			
ection III. Recommendations				
No action and/or treatment recommended: (Explain if Box B in Section				
	n II is checked)			
				or
				: or
		ent unless home	is under a contract	
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pr	mmend termite treatme rovided.	ent unless home	is under a contract	e out obstructions
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pr	mmend termite treatme rovided.	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling	e out obstructions mal key: 15. Standing water
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas the following areas of the structure(s) inspected were obstructed or inaccessible Basement 2,3,4,6,9	mmend termite treatme ovided. essible:	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling	e out obstructions of nal key: 15. Standing water 16. Dense vegetation
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas be following areas of the structure(s) inspected were obstructed or inaccessible Basement 2.3.4.6.9	mmend termite treatme ovided. essible:	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering	e out obstructions nal key: 15. Standing water 16. Dense vegetatio 17. Exterior siding
<ul> <li>Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be presented by the presented by the presented b</li></ul>	mmend termite treatme ovided. essible:	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation	e out obstructions nal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be presented by the structure of prior treatment within last 5 years can be presented by the structure of prior treatment within last 5 years can be presented by the structure of prior treatment within last 5 years can be presented by the structure of prior treatment within last 5 years can be presented by the structure of prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be presented by the prior treatment within last 5 years can be prior treatment. The prior treatment within last 5 years can be prior treatment within last 5 years can be prior treatment. The prior treatment within last 5 years can be prior treatment within last 5 years can be prior treatment. The prior treatment within last 5 years can be prior treatment. The prior treatment within last 5 years can b	mmend termite treatme ovided. essible:	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving	e out obstructions inal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas the following areas of the structure(s) inspected were obstructed or inacce Basement 2.3.4.6.9 Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9	mmend termite treatme ovided. essible:	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items	e out obstructions mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe condition
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be precision IV. Obstructions and Inaccessible Areas e following areas of the structure(s) inspected were obstructed or inaccessible Basement_2.3.4.6.9 Crawlspace Could not access main crawlspace, only visual near operative Main Level 1.3.4.6.9 Attic Not inspected	mmend termite treatme rovided. essible: ening. NE crawlspace-13	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings	e out obstructions mal key: 15. Standing water 16. Dense vegetatid 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boa
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be precision IV. Obstructions and Inaccessible Areas  e following areas of the structure(s) inspected were obstructed or inacce Basement_2.3.4.6.9 Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9 Attic Not inspected	mmend termite treatme rovided. essible: ening. NE crawlspace-13	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry	e out obstructions nal key: 15. Standing water 16. Dense vegetatit 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirir
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas e following areas of the structure(s) inspected were obstructed or inacce Basement_2.3.4.6.9 Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9 Main Level 1.3.4.6.9 Attic Not inspected Garage	mmend termite treatme ovided. essible: ening. NE crawlspace-13	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access	e out obstructions of mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boar 23. Synthetic stucco 24. Duct work, wirin and/or plumbing 25. Spray foam
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas the following areas of the structure(s) inspected were obstructed or inacce Basement_2.3.4.6.9     Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9     Attic Not inspected     Garage     Exterior 16.17     Porch	mmend termite treatme ovided. essible: ening. NE crawlspace-13	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access	e out obstructions of nal key: 15. Standing water 16. Dense vegetatio 17. Exterior siding 18. Window well cor 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boar 23. Synthetic stucco 24. Duct work, wirin and/or plumbing 25. Spray foam insulation
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas he following areas of the structure(s) inspected were obstructed or inacce Basement 2.3.4.6.9 Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9 Attic Not inspected Garage Exterior 16.17 Porch Addition	mmend termite treatme ovided. essible: ening. NE crawlspace-13	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition	te out obstructions mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe condition 22. Rigid foam boar 23. Synthetic stucc 24. Duct work, wirin and/or plumbing 25. Spray foam insulation 26. Equipment
<ul> <li>Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be predicted in the following areas of the structure(s) inspected were obstructed or inaccessible Areas</li> <li>Basement 2.3.4.6.9</li> <li>Crawlspace Could not access main crawlspace, only visual near ope</li> <li>Main Level 1.3.4.6.9</li> <li>Attic Not inspected</li> <li>Garage</li> <li>Exterior 16.17</li> <li>Porch</li> <li>Addition</li> <li>Other</li> </ul>	mmend termite treatme ovided. essible: ening. NE crawlspace-13	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition	e out obstructions mal key: 15. Standing water 16. Dense vegetati 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirir and/or plumbing 25. Spray foam insulation 26. Equipment
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas he following areas of the structure(s) inspected were obstructed or inacce Basement_2.3.4.6.9     Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9     Main Level 1.3.4.6.9     Attic Not inspected     Garage     Exterior 16.17     Porch     Addition     Other     Comments and Attachments (these	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition	e out obstructions mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe condition 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirin and/or plumbing 25. Spray foam insulation 26. Equipment in regarding been from
<ul> <li>Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be predicted in the prior treatment within last 5 years can be predicted in the prior treatment within last 5 years can be predicted in the prior treatment within last 5 years can be predicted in the prior treatment within last 5 years can be predicted or inaccessible Areas</li> <li>Basement 2.3.4.6.9</li> <li>Crawlspace Could not access main crawlspace, only visual near ope</li> <li>Main Level 1.3.4.6.9</li> <li>Attic Not inspected</li> <li>Garage</li> <li>Exterior 16.17</li> <li>Porch</li> <li>Addition</li> <li>Other</li> <li>Other</li> <li>Gestion V. Additional Comments and Attachments (these obstructed or inaccessible areas. Could not access main crawlspace opening. Also evidence of termites in joist on south visual prior to the pri</li></ul>	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition	e out obstructions mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe condition 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirin and/or plumbing 25. Spray foam insulation 26. Equipment in regarding been from
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatment within last 5 years can be pre- documentation of prior treatments (these bistructed or inaccessible areas. Could not access main crawlsp- reavispace opening. Also evidence of termites in joist on south v	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition	e out obstructions mal key: 15. Standing water 16. Dense vegetati 17. Exterior siding 18. Window well cc 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirit and/or plumbing 25. Spray foam insulation 26. Equipment in regarding been from
<ul> <li>Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be predicted or prior treatment within last 5 years can be predicted by the structure of prior treatment within last 5 years can be predicted by the prior treatment wit</li></ul>	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th bace, only visual acces vall of closet under bas	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition comment can be made Termite damage se	e out obstructions mal key: 15. Standing water 16. Dense vegetati 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe conditio 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirir and/or plumbing 25. Spray foam insulation 26. Equipment 26. Equipment 26. Equipment 27. Equipment 28. Equipment
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be predicted or inaccessible Areas Retain IV. Obstructions and Inaccessible Areas Retain IV. Obstructed or inaccessible areas Main Level 1.3.4.6.9 Attic Not inspected Garage Attic Not inspected Garage Setterior 16.17 Porch Addition Other Other Other Retain IV. Additional Comments and Attachments (these obstructed or inaccessible areas. Could not access main crawlsp crawlspace opening. Also evidence of termites in joist on south visitructure and drill marks were found in stoop and patio. Retain III marks were found in stoop and patio.	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th bace, only visual acces wall of closet under bas	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition mement can be made Termite damage se	e out obstructions mal key: 15. Standing water 16. Dense vegetati 17. Exterior siding 18. Window well cc 19. Wood pile 20. Snow 21. Unsafe conditic 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirit and/or plumbing 25. Spray foam insulation 26. Equipment the regarding seen from 5 found outside t
<ul> <li>Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be predicted or inaccessible Areas</li> <li>e following areas of the structure(s) inspected were obstructed or inacces</li> <li>Basement_2.3.4.6.9</li> <li>Crawlspace Could not access main crawlspace, only visual near ope</li> <li>Main Level 1.3.4.6.9</li> <li>Attic Not inspected</li> <li>Garage</li> <li>Exterior 16.17</li> <li>Porch</li> <li>Addition</li> <li>Other</li> <li>Other</li> <li>ection V. Additional Comments and Attachments (these obstructure on inaccessible areas. Could not access main crawlspace opening. Also evidence of termites in joist on south visual marks were found in stoop and patio.</li> </ul>	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th bace, only visual acces wall of closet under bas to the Signature of I copy of both page	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition comment can be made Termite damage se	e out obstructions mal key: 15. Standing water 16. Dense vegetati 17. Exterior siding 18. Window well cc 19. Wood pile 20. Snow 21. Unsafe conditic 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirit and/or plumbing 25. Spray foam insulation 26. Equipment the regarding seen from 5 found outside t
Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be pre- ection IV. Obstructions and Inaccessible Areas the following areas of the structure(s) inspected were obstructed or inacce Basement_2.3.4.6.9 Crawlspace Could not access main crawlspace, only visual near ope Main Level 1.3.4.6.9 Attic Not inspected Garage Attic Not inspected Garage Attic Information Other Addition Other Comments and Attachments (these	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th bace, only visual acces wall of closet under bas	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition mement can be made Termite damage se	e out obstructions mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe condition 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirin and/or plumbing 25. Spray foam insulation 26. Equipment the regarding seen from 5 found outside t
<ul> <li>Recommend actions(s) and/or treatment(s) for the control of: Recond documentation of prior treatment within last 5 years can be predicted or inaccessible Areas</li> <li>e following areas of the structure(s) inspected were obstructed or inacces</li> <li>Basement 2.3.4.6.9</li> <li>Crawlspace Could not access main crawlspace, only visual near ope</li> <li>Main Level 1.3.4.6.9</li> <li>Attic Not inspected</li> <li>Garage</li> <li>Exterior 16.17</li> <li>Porch</li> <li>Addition</li> <li>Other</li> <li>Crawlspace opening. Also evidence of termites in joist on south visual rearwlspace opening. Also evidence of termites in joist on south visual marks were found in stoop and patio.</li> </ul>	mmend termite treatme ovided. essible: ening. NE crawlspace-13 e are an integral part of th bace, only visual acces wall of closet under bas to the Signature of I copy of both page	ent unless home	The inspector may writ use the following optio 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabitnet or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition mement can be made Termite damage se	e out obstructions mal key: 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well co 19. Wood pile 20. Snow 21. Unsafe condition 22. Rigid foam boa 23. Synthetic stucc 24. Duct work, wirin and/or plumbing 25. Spray foam insulation 26. Equipment the regarding seen from 5 found outside t

Jack Bowen BC06CA6CB0E14B6... 8/9/2022

Form NPMA-33 (7/01/19) © 2019 National Pest Management Association. All Rights Reserved, No reproduction of this form is permitted without the express permission of NPMA Previous editions are obsolete after 12/31/19. This form is approved for FHA and VA loans.

Page 1 of 3

DocuSign Envelope ID: 682E6486-5964-465F-A79B-6062048CE9E6

## Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.

For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.

- 3. Obstructions and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.

DS ĺЬ

## TERMITE BAITING SERVICE AGREEMENT

Name ("Client") Goldsmith Billing Address				
26769 S Ratner City, State, Zip	www.mckinziepest.com □MANHATTAN 1129 Hayes Dr. Manhattan, KS 66502 • (785) 776-6063 • (800) 332-0124 ⊠EMPORIA 4101 Martin Dr. Emporia, KS 66801 • (620) 342-4222 • (800) 321-0124 (COMPANY)			
Quenemo KS 66528 Phone	Structures(s) Single family house			
E-Mail	Location of Structure(s) Same			

COMPANY agrees to install baited termite stations in the soil around the listed structure(s) for treatment of subterranean termites and maintain baited stations for a period of ONE YEAR from the original installation date according to the terms of this agreement. All stations will contain bait at the time of the installation and will be inspected and serviced no less than once every twelve months. Upon inspection and service of bait stations, COMPANY will ensure sufficient bait is present according to label directions and replace bait when required. Additional services such as spot applications of conventional termiticides and installation of above ground bait stations may be provided to combat termite activity on a localized basis. COMPANY will provide a representative diagram of the structure(s) following the initial installation service. Upon CLIENT'S request, COMPANY agrees to provide an interior inspection of the structure(s) during January or February at no additional charge to CLIENT.

## Upon completion of the initial installation service, CLIENT agrees to pay COMPANY \$ 748.00 PLUS APPLICABLE TAX for the first year.

## Successive one-year renewal of the service agreement Annual Renewal Fee \$ 240.00 PLUS APPLICABLE TAX

At the expiration of the one-year period, this agreement AUTOMATICALLY RENEWS from year to year unless thirty days notice in writing is given by either party to discontinue. COMPANY reserves the right to adjust the annual renewal fee. CLIENT'S failure to pay any billing statements within 60 days of billing notice shall terminate this agreement and relieve COMPANY of further responsibility. CLIENT agrees to pay a finance charge if not paid within thirty (30) days of each agreement anniversary date at a rate of ONE AND ONE HALF (11/2) PERCENT per month on the previous balance which is an ANNUAL PERCENTAGE RATE OF EIGHTEEN (18) PERCENT. The previous balance is that amount which remains due at the beginning of the monthly billing cycle.

ANNUAL PAYMENT OPTION	MONTHLY INSTALLMENT AUTOPAY OPTION
S748.00 plus tax upon completion of the initial service a plus tax annually thereafter.	and \$240.00
Initials (Bank card or bank account information	AUTO PAY OPTION is retained by the credit card processing company and not by McKinzie Pest Control)
I authorize McKinzie Pest Control to charge my cre	edit card or bank account according to the selected payment plan above. Charges will occur on ne initial installation service or annually on the <u>1<sup>st</sup></u> day of the agreement anniversary month life of this agreement and any renewal thereof. <b>Charges occurring prior to cancellation</b>
<ul> <li>of this agreement, the COMPANY and or Corteva AgroSc components contained therein for appropriate disposition.</li> <li>Alterations or additions to the premises may result in an adju</li> <li>Correcting above ground moisture sources, which may susta</li> <li>COMPANY will exercise normal care but will not be respons</li> <li>COMPANY shall not be responsible for any past, presencosts or expenses incurred by the CLIENT as a result of</li> <li>COMPANY'S obligations are contingent upon weather, strike</li> <li>The Service Agreement may be transferred to subsequent subsequent renewal thereof remains current. Failure of Configuration of the COMPANY under this Agreement is current bill shall cancel this Agreement in its entirety and discharge</li> </ul>	m are and will remain the property of Conteva Agrocounces. In Addition, open senses all stations and other increas or its representative is authorized to retrieve from the CLIENT'S premises all stations and other strenet of the maintenance fee. ain a termite colony, is the responsibility of CLIENT. ible for damage that results from hidden hazards, such as service lines under concrete or soil. it, or future damage to the structure(s) or its contents caused by wood destroying insects, or any any such damage. es, accidents, delays of carrier, and any and all-unavoidable delays beyond the COMPANY'S control. owners of the property <u>provided the initial 1 year service agreement has been paid in full or any</u> LIENT to notify the COMPANY in writing within 30 days of the sale of the property shall result in termination proditioned upon payment in full of the Agreement prices as set forth above and failure to pay the same in the COMPANY of any and all liability and any amounts paid shall become the property of the COMPANY
FOR THE COMPANY By: Bryon Estes	FOR THE CLIENT
By: Bryon Estes Date: 8/2/2022 (Valid 30 days from this date)	Date: 8-8-22 Apple for tel 01

This instrument and the accompanying inspection report contain the entire agreement between parties and no statement, inducement, or promise made by either of the parties, or any agent or employee, which is not contained herein, shall be valid or binding. CLIENT acknowledges that prior to signing, he/she has read and understands the Agreement, that it does not contain any uncompleted blank spaces, and he/she has received a copy of this Agreement. <u>Sentricon is a trademark of Corteva AgroSciences</u> (Revised February) (Revised February 2021)