



SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which

exceed the minimum dis	clos	ures	requ	ired	by	the C	Code.							_
CONCERNING THE PR	ROPE	ERT	Y A	Г				P			R 178 X 76566			
DATE SIGNED BY SEL	LEF	R AN	ID I	SN	OT.	A SI	JBSTITUTE FOR A	NY I	NSF	ECT	TION OF THE PROPERTY AS IONS OR WARRANTIES THE SELLER'S AGENTS, OR ANY	BL	JYEI	R
Seller is is not on	ccup	ying	the	Pro	pert	y. If	unoccupied (by Selle	er), l	ow	long :	since Seller has occupied the P he Property	rop	erty	?
Section 1. The Proper	ty h	as t	he it	tems	s ma	arke	d below: (Mark Yes	(Y),	No	(N), c				
Item	Υ	N	U	1	Ite	m		Y	N	U	Item	Y	N	U
Cable TV Wiring	X				Lic	uid	Propane Gas:	X			Pump: sump grinder		X	
Carbon Monoxide Det.			V				mmunity (Captive)		X		Rain Gutters	X		\vdash
Ceiling Fans	X			i	_		Property	~			Range/Stove	$\langle \rangle$		\vdash
Cooktop	6		X			t Tu			\vee		Roof/Attic Vents			\times
Dishwasher	X			1		STATE FOR STATE	m System		\Diamond		Sauna		V	
Disposal		X		1			vave		\sim		Smoke Detector	X	\sim	
Emergency Escape			_		_		or Grill			-	Smoke Detector - Hearing		1	-
Ladder(s)		X			"	ituot	or Offin	X			Impaired		X	
Exhaust Fans	X	•			Pa	tio/F	Decking	$\langle \rangle$			Spa		$\langle \rangle$	
Fences							ing System	\Rightarrow			Trash Compactor	X		
Fire Detection Equip.		X			Po		ing Cyclem		\sim		TV Antenna		V	
French Drain							quipment		\Rightarrow	-	Washer/Dryer Hookup	X	/	
Gas Fixtures	X						laint, Accessories		\Diamond		Window Screens		$\overline{}$	
Natural Gas Lines							eater		$\langle \rangle$		Public Sewer System		\triangleleft	
Tractar ar Gas Emiss				ı		0111			.~		r abile content cyclem			
Item				Υ	N	U			Α	dditi	onal Information			
Central A/C				X			★ electric gas	nur			nits: THREE ONE NEW 1	N.	202	1
Evaporative Coolers					X		number of units:				THE ONE NEW !	/ \	400	
Wall/Window AC Units					$\langle \rangle$		number of units:							
Attic Fan(s)					$\langle \times \rangle$		if yes, describe:							
Central Heat				<u></u>				nur	nber	of ur	nits: THREE			
Other Heat				$\stackrel{\frown}{\sim}$			if yes, describe: F							
Oven				X		_	number of ovens:		lan-i		ctric gas other:			
Fireplace & Chimney				X			wood × gas log	ıs	mo	400	other:			
Carport					V		- Control - Cont	_	chec		A CONTRACTOR OF THE CONTRACTOR		-	
Garage				V			attached X not							
Garage Door Openers						\vdash	number of units:				number of remotes: UNKNOW	1)		_
Satellite Dish & Controls				$\stackrel{\bigcirc}{\checkmark}$			owned lease		1000		Hamber of Terriotee. DA KNOW	įv	_	
Security System			-	\Diamond			owned lease		-	iN	OPERATIVE			_
Solar Panels				A	×	_	owned lease		_	FIV	WI LAND LIVE		-	_
Water Heater			,	Y			✓ electric ✓ gas		her:		number of units: 1	10	GAC	,
Water Softener				\wedge	X		owned lease	ALC: U					ILE (_
Other Leased Items(s)					(if yes, describe:	J 110			NEW			
(TXR-1406) 07-08-22 Texas Ranch Brokers LLC, P.O. Box 1339	8 Burne			led b	by: B	uyer		nd S	eller:	JRA one: 5127	Pa	ige 1	1 of 6	6

Concerning the Property at								ruilliela,	17	1000	JU			_
Underground Lawn Sprinkle	r		X		auto	matic		manual	are	as cov	ered: INDPERATIVE			
Septic / On-Site Sewer Facil	ity		X	if	yes, a	ttach	Inf	ormation /	Abo	ut On-	Site Sewer Facility (TXR-140	7)		
Water supply provided by: _	cit	v v	Mell .	V MIID		-on	- 11	nknown	_	ther:				
Was the Property built befor (If yes, complete, sign, a Roof Type: METH Is there an overlay roof c	e 19 and a L over	78? _attach	ye	s <u>X</u> no R-1906 c	un concer	knowr	n ea	d-based p	ain	t haza		oxim	ate	e) of
covering)?yes no X														
Are you (Seller) aware of an are need of repair? X yes GARAGE DOOR NE	no	o If ye	s, de	escribe (a	attach	additi	ion	al sheets	if n	ecess	vorking condition, that have d ary): ガル G	efec	ts,	or —
Section 2. Are you (Seller aware and No (N) if you ar					ts or	malfu	ınc	tions in a	any	of the	e following? (Mark Yes (Y) i	you	u a	re
Item	Y	N	-	Item					Υ	N	Item	,	1	N
Basement		X	-	Floors						X	Sidewalks	\perp		X
Ceilings	_	X	_	Foundat		Slab(s))			\times	Walls / Fences	4	- 0	\times
Doors		X	_	Interior V						X,	Windows	_		\leq
Driveways		\times	_	Lighting						X	Other Structural Components	4	2	\times
Electrical Systems		X	_	Plumbin	g Sys	tems				X		\bot	4	
Exterior Walls		X		Roof						\times				
Section 3. Are you (Seller you are not aware.)) aw	vare o	of ar	y of the	follo	wing	СО	nditions'	? (1\	/lark Y	es (Y) if you are aware and	No	(N)	if
Condition					V	N	Г	Conditio	n			1	1	N
Aluminum Wiring					+-		_	Radon Ga				+		Ż
Asbestos Components							-	Settling	40			+		Z
Diseased Trees: oak wilt					_	\sim	_	Soil Move	me	nt		+	-	×
Endangered Species/Habita	-	Prop	ertv		+	\Diamond	_			V-0-	ire or Pits	+	-	\geq
Fault Lines	. 011	1 100	Orty		+		_				ige Tanks	十	5	2
Hazardous or Toxic Waste						X	_	Unplatted				\top	1	Ż
Improper Drainage						X	_	Unrecord				\top	5	Z
Intermittent or Weather Spri	nas					\propto	_	A STATE OF THE STA			Insulation	\top		X
Landfill						X	_				t Due to a Flood Event	\top)	Z
Lead-Based Paint or Lead-E	Base	d Pt.	Haza	ards		\times	-	Wetlands				\top	-	×
Encroachments onto the Pro	per	ty				X	-	Wood Ro		•		\top	1	X
Improvements encroaching	_		' pro	perty			Γ	Active infe	esta	ation o	f termites or other wood	\top		
						X		destroying	g in	sects	(WDI)			X
Located in Historic District						X		Previous	trea	atment	for termites or WDI	\rightarrow		
Historic Property Designatio	n					\propto		Previous	terr	nite or	WDI damage repaired	7	X	
Previous Foundation Repair						\times		Previous	Fire	es			10	X
Previous Roof Repairs						\times	_				mage needing repair		1	×
Previous Other Structural Re	epai	rs				\bigvee	- 1	•		able M	lain Drain in Pool/Hot			X
							L	Tub/Spa*					1	1
Previous Use of Premises for	or Ma	anufa	cture	9										

(TXR-1406) 07-08-22

of Methamphetamine

Initialed by: Buyer: __

Page 2 of 6

and Seller:

Texas Ranch Brokers LLC, P.O. Box 1338 Burnet TX 78611

(TXR-1406) 07-08-22

Mike Bacon Drew Colvin

Phone: 5127567718 Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Initialed by: Buyer: _

and Seller:

John Hopkins

Page 3 of 6

Fax:

(TXR-1406) 07-08-22

Initialed by: Buyer: ____,

Concerning the Prop	perty at		2055 CR 178 Purmela, TX 76566	
		0	<u> </u>	
persons who reg	ularly provide in	spections and w	eller) received any writ ho are either licensed If yes, attach copies and co	ten inspection reports from as inspectors or otherwise omplete the following:
Inspection Date	Туре	Name of Inspec	tor	No. of Pages
4/22/2020	Unknown	Wes Rethe	rford	48
-γ				
Note: A buyer			ts as a reflection of the curre from inspectors chosen by th	
Homestead Wildlife Mana	any tax exemption(X Senior Citizen Agricultural	Disa	Property: abled abled Veteran nown
Section 11. Have y insurance provider	ou (Seller) ever file ? yes ∜no	ed a claim for dan	nage, other than flood da	nage, to the Property with any
insurance claim or	a settlement or awa	ard in a legal proce	for a claim for damage to eeding) and not used the p	the Property (for example, an roceeds to make the repairs for
requirements of Cl	he Property have what hapter 766 of the Honests if necessary):	ealth and Safety C	ode?* 💢 unknown no _	dance with the smoke detector yes. If no or unknown, explain.
installed in acc	cordance with the requirmance, location, and	irements of the building power source require	amily or two-family dwellings to ng code in effect in the area in ments. If you do not know the ct your local building official for n	which the dwelling is located, building code requirements in
family who will impairment fro the seller to in	reside in the dwelling m a licensed physician; stall smoke detectors fo	is hearing-impaired; and (3) within 10 day or the hearing-impaire	ne hearing impaired if: (1) the bu (2) the buyer gives the seller was after the effective date, the bu and and specifies the locations for a and which brand of smoke dete	rritten evidence of the hearing yer makes a written request for or installation. The parties may
Seller acknowledge the broker(s), has in	s that the statements structed or influence	s in this notice are to d Seller to provide i	true to the best of Seller's be naccurate information or to c	elief and that no person, including omit any material information.
Signature of Seller		Date	Signature of Seller	ns O//O/ZUZZ Date
Printed Name:		Bato	Printed Name: JOHN	R. HOPKINS
(TXR-1406) 07-08-22	Initialed	by: Buyer:,	and Seller:	Page 5 of 6

Texas Ranch Brokers LLC, P.O. Box 1338 Burnet TX 78611

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201

www.lwolf.com

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review Information Regarding Windstorm and Hail Insurance for Certain Properties (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

Electric: HAMILTON COUNTY ELECTRIC COOP	phone #: 254-386-3123
	phone #:
Water: MULTI COUNTY WATER SUPPLY	phone #: 354 - 865-2269
Water: TIDET COUNTY WATER SUPPLY	The state of the s
Cable:	phone #:
Trash:	phone #:
Natural Gas:	phone #:
Phone Company:	phone #:
Propane: BERT SCHRANK LP GAS CO	phone #: 254 - 386 - 8144
Internet:	phone #:


(7) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

(6) The following providers currently provide service to the Property:

The undersigned Buyer a	cknowledges receipt of the foregoi	ng notice.	
Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	
(TXR-1406) 07-08-22	Initialed by: Buyer:,	and Seller: ,	Page 6 of 6
Texas Ranch Brokers LLC, P.O. Box 1338 B	surnet TX 78611 Produced with Lone Wolf Transactions (zipForm Editio	Phone: 5127567718 Fax: n) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com	John Hopkins



"When knowing is more important than wondering"



2055 County Road 178 West Purmela, TX 76566

TREC Inspector #7436
TCEQ Septic Systems 32203
TDA Termite Inspector #644166
TDSHS Mold Consultant MAC1274
HAAG Certified Residential Roof Inspector
ITC Certified Thermographer - Level II
NSPF Swimming Pool Inspector
NESHAP Asbestos Inspector
EPA Lead Paint Testing
FHA Inspector C948
TDI Inspector

INVOICE

InspecTexas

PO Box 26 Purmela, TX 76566

Phone 254-721-7522

TREC 7436

SOLD TO:		
John Hopkins		
TX		

INVOICE NUMBER 20200422-01 INVOICE DATE 04/22/2020

LOCATION 2055 County Road 178 West

REALTOR Mike Bacon

DESCRIPTION	PRICE	AMOUNT
Passive Septic Inspection	\$25.00	\$25.00
Home Inspection	\$700.00	\$700.00
Termite Inspection	\$125.00	\$125.00
Water Well Pump Inspection	\$50.00	\$50.00
4/22/2020	(\$900.00)	(\$900.00)
	0515 - totalogou 1071111	
	To FQ Septice Systems 12000 TOA Construction 90440 c	
	SUBTOTAL	\$900.00
	TAX	\$0.00
	TOTAL	\$900.00
	not separate by the BALANCE DUE	\$0.00

THANK YOU FOR YOUR BUSINESS!

Please refer InspecTexas to your family and friends

"When knowing is more important than wondering"

InspecTexas PO Box 26 Purmela, TX 76566

Phone: 254-721-7522

Fax:

Email: Wes@InspecTexas.com

PROPERTY INSPECTION REPORT

Prepared For:	John Hopkins		
	(Name of Client)		
Concerning:	2055 County Road 178 West, Purmela, TX 76566		
	(Address or Other Identification of Inspected Property)		
By:	Wesley Retherford, Lic #7436	04/22/2020	
e page	(Name and License Number of Inspector)	(Date)	
	(Name, License Number of Sponsoring Inspector)	10 ×6 300 1 × 110	

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (http://www.trec.texas.gov).

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX

obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- · improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

General Information About The Report

The Texas Real Estate Commission requires some new building-code related issues to be marked as "deficient" in the home inspection report, regardless of the year the home was built. You are not required to upgrade any of these "deficiencies" in order to meet the new building code except under certain circumstances involving extensive remodeling, usually requiring a building permit. Check with your local building official for the exemptions.

Deficiency comments with the initials "BC" (for 'Building Code') means the state of Texas requires us to report the item as a deficiency, however, you are not required to upgrade the item to meet the code.

Some building code issues are directly related to the safety and well being of persons in or around the home. For example, smoke detectors should always be installed regardless of the age of the home. Safety related building code issues *should* be upgraded to meet newer building codes, but it is not required.

This report does not use directional terms like north, south, east or west when pinpointing areas or issues. This report uses directional terms such as front, back, left or right with reference to a person standing and facing the front of the home or the entry door to a specific room.

Energy savings tips are not a required component of the home inspection report, however, if they are included they will be in green font.

Safety hazards will be described using red font.

Issues immediately dangerous to life or health will be indicated with bold underlined red italicized font.

If any item is deemed to be "deficient" according to the Texas Standards of Practice, it will be listed under the "*Deficiency Notes*" heading. Other issues which are not deficiencies may be included for your information under the "*Other Notes*" heading.

Temperature: 74 Degrees

Humidity: 90% Weather: Misting

Present at inspection: Buyer; buyer and seller's agents

The available inspection services requested for this inspection by the client are as follows:

Yes	No	
\checkmark		Home Inspection
\checkmark		Wood Destroying Insect Inspection
\checkmark		Septic Tank Inspection
\checkmark		Water Well Inspection
	\checkmark	Sprinkler System Inspection
	\checkmark	Swimming Pool Inspection
	V	Spa/Hot Tub Inspection
	\checkmark	Foundation Level Analysis
	V	Thermal Imaging Inspection
	V	Mold Assessment
	\checkmark	Air Quality Testing
	V	Water Quality Testing
	\checkmark	Lead Paint Testing
	\checkmark	Asbestos Testing
	$\overline{\mathbf{V}}$	Sewer Line Video Inspection

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D I. STRUCTURAL SYSTEMS A. Foundations Type of Foundation(s): Slab Comments: Deficiency Notes: None. Other Notes: The concrete foundation was inspected and no structural problems were noted. B. Grading and Drainage Comments: Deficiency Notes: *Note:* Comments followed by the initials "BC" indicate an item that is not in compliance with the 2018 International Residential Code. Municipalities typically use older editions of the building code and therefore items reported as "Deficient" in this report may actually be in compliance with the existing code being enforced locally. As a general rule you are not required to upgrade any items noted as Deficient in this report to meet the building code. The returns do not discharge at least five feet from the foundation. "BC"

R801.3 Roof drainage. In areas where expansive or collapsible soils are known to exist, all dwellings shall have a controlled method of water disposal from roofs that will collect and discharge roof drainage to the ground surface not less than 5 feet from

foundation walls.

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Other Notes:

The grading was inspected and appears to allow sufficient drainage of typical water runoff.

1 c.	Roof Covering Materials Types of Roof Covering: Galvanized Steel Viewed From: Ground level Comments:
	Deficiency Notes:
	None.
	Other Notes:
	The roof covering system was inspected with no problems noted.
l D.	Roof Structures and Attics Viewed From: Entered attic Approximate Average Depth of Insulation: N/A Spray Foam Comments:
	Deficiency Notes:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

None.

Other Notes:

The attic and roof structures were inspected with no problems noted.

☑ □ □ ☑ E. Walls (Interior and Exterior) Comments:


Deficiency Notes:

There is moisture damage on the wall between the garage and screened porch. The source of the moisture was not determined.



There is minor moisture damage under a receptacle in the garage beneath the fishing pole rack. The source of the moisture was not determined.





NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

There is an active infestation of termites in the corner at the end of the hall by the entry door to the master bedroom.




Other Notes:


None.

F. Ceilings and Floors Comments:

Deficiency Notes:

There is some cracking and drywall tape separation on the upper deck walkway ceiling. These pictures are typical.





Other Notes:

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D


None.

G. Doors (Interior and Exterior)

Comments:


Deficiency Notes:

The attic door should be locked to prevent unauthorized access which could lead to property damage and/or personal injury.



When an automatic garage door opener is present, the mechanical lock should be disabled to prevent potential motor damage and/or an electrical fire hazard. An example of a disabled lock is shown in the picture on the left.





There is moisture damage on both of the doors to the screened porch. The arrow indicates the general location and the the circle shows a close up of the damage.

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D









Other Notes:

None.

H. Windows
Comments:

Deficiency Notes:

The blind between the panes of glass is not working properly in the dining room area window (next to the back exterior door).

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



One of the screens next to the exterior kitchen/dining room right side door is slightly damaged.



Other Notes:

The south window on the east wall in the upstairs pool table room was unlocked when I arrived onsite. I locked it prior to leaving.

☑ □ □ ☑ I. Stairways (Interior and Exterior)

Comments:

Deficiency Notes:

Note: Comments followed by the initials "BC" indicate an item that is not in compliance with the 2018 International Residential Code. Municipalities typically use

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

older editions of the building code and therefore items reported as "Deficient" in this report may actually be in compliance with the existing code being enforced locally. As a general rule you are not required to upgrade any items noted as Deficient in this report to meet the building code.

R311.7.6 Landings for stairways. There shall be a floor or landing at the top and bottom of each stairway. There is no landing at the top of the stairway going into the attic.



Other Notes:

None.

\checkmark		J.	Fireplaces and Chimneys
			Comments:

Deficiency Notes:

None.

Other Notes:

The chimney was inspected with no problems noted.

NI=Not Inspected

NP=Not Present


D=Deficient


I NI NP D

K. Porches, Balconies, Decks, and Carports Comments:


Deficiency Notes:

Most of the cement soffit board which has been cut into small sections for cosmetic use at the upper deck area has come loose and fallen off. These pictures are typical.





A section of metal rails and balusters have been replaced with wood on the back left corner of the upper deck.



The third section of rail from the back right corner heading towards the front of the home is loose.

Other Notes:

None.

I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D					U 12.10
	L.	Other Comments:			
		Deficiency Notes:			



Other Notes:

None.

II. ELECTRICAL SYSTEMS

✓ ☐ ☐ ✓ A. Service Entrance and Panels Comments:

Deficiency Notes:

Note: Comments followed by the initials "BC" indicate an item that is not in compliance with the 2018 International Residential Code. Municipalities typically use older editions of the building code and therefore items reported as "Deficient" in this report may actually be in compliance with the existing code being enforced locally. As a general rule you are not required to upgrade any items noted as Deficient in this report to meet the building code.

Knock outs (also known as "twist outs") are missing in the electrical panel box in the house. Plastic inserts can be purchased to block these openings. "BC" The picture on the left shows what one type of knockout insert looks like.

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

E3404.6 Unused openings shall be closed to afford protection substantially equivalent to the wall of the equipment.





The panel box in the house is no longer allowed in a clothes closet. "BC".

E3705.7 Overcurrent devices shall be readily accessible and shall not be located where they will be exposed to physical damage, where they will be in the vicinity of easily ignitible material such as in clothes closets and shall not be located in bathrooms or over steps of a stairway.



This type of circuit breaker in the panel in the home is not designed to have two wires connected to it. "BC" The picture on the left shows a type of circuit breaker which can have two installed wires.

E3706.4 Grounded conductor terminations. Each grounded conductor shall terminate within the panelboard on an individual terminal that is not also used for another conductor, except that grounded conductors of circuits with parallel conductors shall be

NI=Not Inspected


NP=Not Present

D=Deficient

I NI NP D


permitted to terminate on a single terminal where the terminal is identified for connection of more than one conductor.






The new code only allows one wire to be in each bus bar hole (house panel). "BC"

E3706.4 Grounded conductor terminations. Each grounded conductor shall terminate within the panelboard on an individual terminal that is not also used for another conductor, except that grounded conductors of circuits with parallel conductors shall be permitted to terminate on a single terminal where the terminal is identified for connection of more than one conductor.





E3601.7 The service disconnecting means shall consist of not more than six switches or six circuit breakers mounted in a single enclosure or in a group of separate enclosures.

The bottom two screws holding the panel on the wall in the home are missing.

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

Other Notes:

B. Branch Circuits, Connected Devices, and Fixtures Type of Wiring: Copper Comments:

Deficiency Notes:

None.

Note: Comments followed by the initials "BC" indicate an item that is not in compliance with the 2018 International Residential Code. Municipalities typically use older editions of the building code and therefore items reported as "Deficient" in this report may actually be in compliance with the existing code being enforced locally. Also, as a general rule you are not required to upgrade any items noted as Deficient in this report to meet the newer building codes.

There is no carbon monoxide alarm in the home. "BC"

R315.2.1 Carbon monoxide alarms shall be provided in dwelling units where either or both of the following conditions exist.

- 1. The dwelling unit contains a fuel-fired appliance.
- 2. The dwelling unit has an attached garage with an opening that communicates with the dwelling unit.

The ground fault circuit interrupter receptacle in the bathroom in the detached garage did not work.

The outlets are connected to a ground fault circuit interrupter, however, they are not labeled to show that fact in the kitchen, bathrooms and exterior. "BC" The left picture shows a typical label.


NI=Not Inspected

NP=Not Present

D=Deficient


NI NP D





A receptacle cover plate is missing in the attic. This may be low voltage wiring. "BC" *This is a potential shock hazard.*

E4002.13 Exposed terminals. Receptacles shall be enclosed so that live wiring terminals are not exposed to contact.



There is no protective globe on the light fixture in the attic. "BC"


E4003.2 Luminaires shall be installed or equipped with shades or guards so that combustible material will not be subjected to temperatures in excess of 194°F.

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



There was a switch taped over in the kitchen. I did not test it.




There are fan blades missing on the fixtures in the screened porch and outdoor BBQ area.

NI=Not Inspected


NP=Not Present

D=Deficient

I NI NP D



One fan in the screened porch has the pull chain for the light missing.




The light bulbs on the fan in the screened porch flicked on and off like a car blinker when I turned the switch on.

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Two of the receptacle covers on the counters in the outdoor BBQ area broke when trying to test the receptacles. Most of the ground holes are full of mud from some type of insect (circled).





The fan in the downstairs front office wobbles and needs to be balanced.

Most of the lights on the outdoor BBQ and gazebo area did not work. They may need new bulbs.

Other Notes:

The receptacles in the detached garage did not work until I reset the ground fault circuit interrupter on the exterior by the main overhead garage door.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

A. Heating Equipment

Type of Systems: Central Energy Sources: Electric Comments:


Deficiency Notes:

None.

Other Notes:

The heaters were inspected and the temperature difference between the return and supply air was at least 15 degrees which is good.

Upstairs





Downstairs





Detached Garage

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D





B. Cooling Equipment

Type of Systems: Central Comments:

Deficiency Notes:

None.

Other Notes:

The air conditioner was inspected and tested and the temperature difference between the return and supply air was at least 15 degrees which is good.

Upstairs





Downstairs

NI=Not Inspected

NP=Not Present

D=Deficient


NI NP D





Detached Garage





\checkmark		C.	Duct Systems, Chases, and Vent
			Comments:

Deficiency Notes:

None.

Other Notes:

The visible portion of the duct system was inspected with no problems noted.

IV. PLUMBING SYSTEMS

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter. Side yard

Location of main water supply valve: Side vard

Static water pressure reading: 41 psi at 7.8 gallons per minute


Comments:

Deficiency Notes:

None.

Other Notes:

The static water pressure is 80 psi, or less, which is good. The normal range is between 40 psi and 80 psi.



The water flow rate was checked at three fixtures simultaneously for at least five minutes and appeared to be sufficient for normal home use.

The building code requires all homes to have a sprinkler protection system installed for safety purposes. However, the State of Texas has amended that provision making it optional, but not required.

Section 1301.551, Occupations Code, is amended as follows:

(e) Notwithstanding any other provision of state law, after January 1, 2009, a municipality may not enact an ordinance, bylaw, order, building code, or rule requiring the installation of a multipurpose residential fire protection sprinkler system or any other fire sprinkler protection system in a new or existing one- or two-family dwelling. A municipality may adopt an ordinance, bylaw, order, or rule allowing a multipurpose residential fire protection sprinkler specialist or other contractor to offer, for a fee, the installation of a fire sprinkler protection system in a new one- or two-family dwelling.

I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient				
I NI NP	D				4 17 17			
		Drains, Wastes, and Vents Comments: Deficiency Notes: None. Other Notes: The drains, wastes and vents were inspected and tested with no problems noted. The sewer drain system is tested by running water in at least three of the fixtures simultaneously for at least five minutes, and flushing the toilets at least three times each while watching for potential blockages or slow draining. This is not a conclusive test an only a video scan of the sewer drain could confirm its actual condition. It could not be determined if the washing machine drain operates properly because the washing machine drain was not tested for the following reasons: 1. If a washing machine was connected, we do not operate it to see if the drain works. 2. If a washing machine is not connected, we do not check the drain because we have no way to reproduce the high pressures that are produced by a washing machine during the						
		Water Heating Equipm Energy Sources: Pro Capacity: On Demail Comments: Deficiency Notes: None. Other Notes:	ent opane Gas nd (two units)					

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



☑ □ □ ☑ D. Hydro-Massage Therapy Equipment Comments:

Deficiency Notes:

Note: Comments followed by the initials "BC" indicate an item that is not in compliance with the 2018 International Residential Code. Municipalities typically use older editions of the building code and therefore items reported as "Deficient" in this report may actually be in compliance with the existing code being enforced locally. As a general rule you are not required to upgrade any items noted as Deficient in this report to meet the building code.

The whirlpool tub in the master bathroom does not have a ground fault circuit interrupter outlet receptacle. "BC"

E4209.1 Hydromassage bathtubs and their associated electrical components shall be supplied by an individual branch circuit and protected by a readily accessible ground-fault circuit-interrupter.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Other Notes:

There is debris in the master bathroom jacuzzi tub from testing the system. This is usually due to lack of use and not indicative of a problem..



$ \sqrt{} $		E.	Other Comments:	
			Deficiency Notes:	
			None.	

Other Notes:

None.

I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D V. **APPLIANCES** A. Dishwashers Comments: **Deficiency Notes:** None. Other Notes: The dishwasher was inspected and run through one full cycle and no problems were noted. B. Food Waste Disposers Comments: Deficiency Notes: None. Other Notes: None. C. Range Hood and Exhaust Systems Comments: **Deficiency Notes:** None. Other Notes:

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX

I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D				
		The range hood was	inspected and operated v	vith no problems noted.
	D.	Ranges, Cooktops, and Comments:	Ovens	
		Deficiency Notes:		
		None.		
		Other Notes:		
		The oven was tested degrees which is con		red a temperature within plus or minus 25
			in the outdoor BBQ area. The igniters did work.	a did not work. I assume that the propane to
	E.	Microwave Ovens Comments:		
		Deficiency Notes:		
		None.		
		Other Notes:		

Rep	ort I	dentif	icatio	n: <u>202</u>	00422-01, 2055 County	Road 178 West, Purmela,	TX	
I=	Insp	ected			NI=Not Inspected	NP=Not Present	D=Deficient	
I	NI	NP	D					1
					The microwave was i		y warming a cup of water.	No problems
V				F.	Mechanical Exhaust Ve Comments:	nts and Bathroom Heaters		
					Deficiency Notes			
					Deficiency Notes:			
					None.			
					Other Notes:			
					The mechanical exha	ust fans were inspected a	and operated with no proble	ms noted.
\checkmark				G.	Garage Door Operators Comments:	e de la		
					Deficiency Notes:			
					None.			
					Other Notes:			
					The automatic garage	e door operator was inspe	ected and tested with no pro	blems noted.
V				Н.	Dryer Exhaust Systems Comments:			
					Deficiency Notes:			
					None.			
					1,0110.			
					Other Notes:			

I=Inspected	ì	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP	D				0. 92
		The dryer exhaust system	n was inspected with		
		Deficiency Notes:			
		None.			
		Other Notes:			
		None.			
		VI.	OPTIONAL SY	YSTEMS	
		A. Landscape Irrigation (Sprin Comments:	kler) Systems		
		Deficiency Notes:			
		None.			
		Other Notes:			
		None.			
		B. Swimming Pools, Spas, Hot Type of Construction: Po		es Partition	
		Deficiency Notes:			
		None.			

Report Identification: 20200422-01, 2055 County Road 178 West, Purmela, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D Other Notes: None. C. Outbuildings Comments: **Deficiency Notes:** None. Other Notes: None. D. Private Water Wells (A coliform analysis is recommended) Type of Pump: Submersible Deep Well Type of Storage Equipment: Bladder tank located in an outbuilding Comments: **Deficiency Notes:** The water well on the right side of the home by the utility pole did not work. The panel box indicated "Error" on it.

The valve handle and iron fittings are quite rusted.

I=Inspected


NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D





Other Notes:

None.

E. Private Sewage Disposal (Septic) Systems

Type of System: Septic Tank

Location of Drain Field: Back yard

Comments:

The septic system was flood tested for four hours with no problems noted.

☐ ☐ ☐ F. Other Comments:

Deficiency Notes:

None.

Other Notes:

None.

Mold Inspection Report

A visual inspection for mold growth and conditions conducive to mold growth was performed during this inspection. Mold is ubiquitous which means its is every where, in the air we breath, both indoors and outdoors. Mold is like people - it needs food and water to survive. Most homes are a food source for mold, so the only thing that's needed for mold to start forming is a moisture source. Without a moisture source there is usually no mold. A moisture source in a home is typically a moisture *problem* which needs to be repaired. This home was inspected for moisture problems and visible mold with the following conclusions:

✓ No moisture problems were noticed.		
☑ No visible mold was noticed.		
☐ There is a moisture problem which could lead to mold growth as fol	llows: Not applicable	
☐ Visible mold was found as follows: Not applicable	20 K 14 F	
Recommendation: None.		
70.1		

If there are concerns about mold which may not be visible, we can take air samples and obtain laboratory results for you by request.



InspecTexas PO Box 26

Purmela, TX 7656 254-721-7522 TCEQ #OS0032202

On-Site Sewage Facility Inspection Report

Inspection Overview:

Preliminary System Information

Inspection Of Treatment Tanks

Inspection Of Absorption Systems

Disposal/Conveyance System Assessment

Does all sewer enter the septic system? Yes Is there any type of sewage bypass? No

Client:

Same as owner: No

Address:

Preliminary System Information

Weather:	Is there a site plan available? No				
Last precipitation:					
Age of system:	Is there a septic map available? No				
Number of systems inspected: 1					
High impact hobbies onsite: No	Is the dwelling currently occupied: Yes				
Prior problems/repair history: N/A	If so, how many occupants:				
	If not, last date occupied: N/A				
Is a washing machine connected to a gray water disposal system? No					
Is the dwelling free of additional gray water systems? Yes					
Is the dwelling free of sump pump discharges to the system? Yes					
Is there any historical sewage backups into the structure? No					

Notes:



Inspection Of Treatment Tanks: N/A

Type of system: Passive

Tank material: N/A Approximate tank volume: N/A

Main tank lid opened for inspection? Yes No N/A

Are all portions of the tank(s) clear of structures, i.e., deck, driveway? Yes

Treatment tank pumped for this inspection? No

Is an affluent filter a part of the system? No

Are there any other types of accessory units present? No

Positive sewage flow from structure? Yes

Depth to top of tank access: N/A

Absorption System Inspection

Type: N/A

Was the absorption system located? N/A

Are the inspection ports present? N/A

Were the inspection ports inspected? N/A

Is the area of the absorption area free of odors? Yes

Does sewage flow from treatment tank to absorption system without flowing back? Yes

Is the area above or near any of the system components free from visible signs of effluent or sewage? Yes

Are areas above or near system components free of lush vegetation? Yes

Is the area directly over any part of the absorption system free of any evidence of large objects, i.e., cars, swimming pools, etc? Yes

Are the areas at or near the inlet invert of absorption area components free of visible signs of effluent or sewage? Yes



Disposal/Conveyance System Assessment
Does the system contain a pump tank? N/A
Is the pump operating? N/A
Do the alarms on the pump work? N/A
Is the pump elevated above the tank floor? N/A
Is the lid in satisfactory condition? N/A
Is the tank in satisfactory condition? N/A
Is the tank free from accumulated solids? N/A
- Ligo flow from structure? Yes
Items Reportable To The Health Department
☐ Ponding or breakout of sewage or effluent onto the surface of the ground.
☐ Seepage of sewage or effluent into portions of buildings below ground.
☐ Backup of sewage into the building served which is not caused by a physical blockage of the plumbing.
☐ Any manner of leakage observed from or into septic tanks, connecting pipes, distribution boxes and
other components that are not designed to emit sewage or effluent.
observation that is consistent with a condition noted above should be reported to the local administrative authority within twenty-four hours of the observation.
Disclaimer: Based on visual observations, InspecTexas submits this On-Site Sewage Facility inspection report of the surface conditions noted during the inspection. The inspection is based on the current visible condition of the on-site sewage system without any excavation to determine subsurface issues. InspecTexas makes no representation that the system was designed, installed or meets applicable TCEQ regulations. InspecTexas has not been retained to warrant, guarantee, or certify the proper functioning of the system for any period of time nor does so. Because of numerous factors (usage, soil type, installation, maintenance, etc.) which affect the proper operation of the subsurface disposal systems, as well as the inability to monitor the use and maintenance of the system, this inspection form shall not be construed as a warranty or guarantee by InspecTexas that the system will function properly for any prospective buyer for any period of time. InspecTexas disclaims any warranty, either express or implied, arising from the inspection of the on-site sewage facility.
Customer signature: Date:
Inspector signature: Wes Retherford Date: "When Knowing Is More Important Than Wondering"

This report is received in agreement with the buyer's acceptance of the Real Estate Inspection Agreement attached to this home Inspection Report. The Client understands and agrees the Real Estate Inspection Agreement is a part of the Inspection Report and acceptance of, or payment for, the Inspection Report by the Client will confirm this Agreement, even if the Client was not present at the inspection and/or has not signed this Agreement prior to the inspection. Client has seven (7) days to submit written objection to the terms of the agreement, otherwise Client is bound by the Agreement and Terms and Conditions of the Inspection Report, if not previously signed/accepted.

Real Estate Inspection Agreement

Between InspecTexas and John Hopkins

Date: 04/22/2020

Fee: \$900.00

The above parties agree to the following in consideration for the fee above received:

InspecTexas shall provide a licensed real estate inspector to perform a "Real Estate Inspection".

This report is received in agreement with the buyer's acceptance of the Real Estate Inspection Agreement. The Client understands and agrees the Real Estate Inspection Agreement is a part of the Inspection Report and acceptance of and/or payment for, the Inspection Report by the Client will confirm this Agreement, even if the Client was not present at the inspection and/or has not signed this Real Estate Inspection Agreement.

Client has seven (7) days to submit written objection to the terms of this Agreement, otherwise Client is bound by this Agreement and Terms and Conditions of the Report, if not previously signed/accepted.

Client requests a primarily limited visual inspection of the subject property to be conducted by a licensed real estate inspector with InspecTexas. The real estate inspector and the company and their agents, employees, and owners are jointly referred to herein as the "inspector". The purpose of the inspection is to inform the Client of visually observable major deficiencies in the condition of the inspected systems and items at the time of the inspection. Client represents and warrants that Client has secured all approvals necessary for inspector's entrance onto the subject property for the purpose of conducting the inspection. Client warrants that Client will carefully read the entire inspection report (herein called "report") on receipt and will promptly call the inspector with any questions they may have. Client and inspector understand that they are bound by all terms of this agreement.

FEE: Client agrees to pay the fees stated above for the performance of the inspection. This amount shall be paid in full prior to the completion of the inspection or as otherwise agreed. Should Client fail to timely pay agreed upon fee, Client shall be responsible for paying any and all fees associated with collection, including but not limited to attorney's fees and costs. The parties agree that the fee agreed to herein is not contingent on the reporting of any specific, predetermined condition(s) of the subject property. The inspector has not and will not accept a fee or other valuable consideration in this transaction from any person other than the Client. The

inspector has not and will not pay any portion of the fee received herein to any participant in this real estate transaction, with the exception of any fees required for laboratory expenses.

SCOPE OF INSPECTION: The inspection to be performed for Client is a non-invasive, primarily visual, examination of the inspected systems and items of the subject property. Major visible defects as they exist on the date of the inspection will be noted on the report, which will be prepared by the inspector during and/or after the actual inspection. The report will be furnished to Client within forty-eight hours after completion of the inspection. The inspection will be performed in accordance with the Standards of Practice of the Texas Real Estate Commission (TREC) and the inspector will use the TREC Property Inspection Report to report the findings. The TREC Standards of Practice and the Property Inspection Report define the scope of the inspection to be performed. Copies of the TREC Standards of Practice and Property Inspection Report will be provided upon request or Client may view them at http://www.trec.state.tx.us. The inspection only includes those systems and items expressly and specifically identified in the report. The inspection and report thereon is not a warranty, guarantee, insurance policy, or substitute for real estate transfer disclosures, warranties or Seller's Disclosure Statement which may be required by law.

EXCLUSIONS: This inspection is limited to the real property and does not include personal property unless so indicated in the report. Inspector will not inspect, or report, on systems and items that are not included or that are specifically excluded in the TREC Standards of Practice or Property Inspection Report unless otherwise agreed to in writing signed by parties. Inspector is not required to inspect anything identified in the TREC Standards of Practice as limitations or exclusions specific to the systems and components inspected. No representation is made as to how long any equipment will continue to function. Maintenance conditions may be discussed, but they are not a part of this inspection. The inspection to be performed is primarily a visual inspection only. Latent and concealed defects and deficiencies are excluded from the inspection. Inspector shall have no liability for conditions that are concealed from view or inaccessible to the inspector. A system or component is not accessible if inspection requires moving personal property, dismantling, destructive measures, or any action that will, in the opinion of the inspector, likely involve risk to persons or property. Anything not readily observable because it is concealed or inaccessible due to obstructions including (but not limited to) floor coverings, suspended ceiling tiles, insulation, furniture or other personal property, soil, vegetation, water, ice or snow cannot be inspected. Inspector is not required to move or disturb such items in order to diminish or eliminate the obstruction.

LICENSED INSPECTOR: Inspectors are licensed by the Texas Real Estate Commission. Client understands that the inspector is a generalist, knowledgeable in a variety of areas, but does not hold himself as an expert in any field. A preliminary general inspection and report is an unbiased opinion, based upon the experience of the individual inspector. Inspector is not an insurer or guarantor against defects in the systems and items inspected. If the inspector recommends consulting specialized experts for further evaluation or repair, it is up to the Client, at the Client's expense, to proceed with further inspections or evaluations with experts as selected by Client. Client agrees to consult with an appropriate specialist on any item noted in need of repair, replacement or further evaluation prior to closing.

Inspector may not perform or agree to perform repairs or maintenance in connection with the inspection. The inspector is not a principal, broker or salesperson in this real estate transaction.

LIMITED WARRANTY: CLIENT ACKNOWLEDGES THAT THE INSPECTOR WARRANTS ONLY THAT ITS INSPECTION WILL BE PERFORMED IN ACCORDANCE WITH THE SCOPE HEREIN,

THE INSPECTION REPORT, AND THE STANDARDS OF PRACTICE OF THE TEXAS REAL ESTATE COMMISSION. THIS IS A LIMITED AND NON-TRANSFERABLE WARRANTY AND IS THE ONLY WARRANTY GIVEN BY INSPECTOR. INSPECTOR MAKES AND CLIENT RECEIVES NO OTHER WARRANTY, EXPRESS OR IMPLIED. ALL OTHER WARRANTIES, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR PARTICULAR PURPOSE, ARE EXPRESSLY EXCLUDED AND WAIVED BY CLIENT. THIS STATED EXPRESS LIMITED WARRANTY IS IN LIEU OF ALL LIABILITIES OR OBLIGATIONS OF INSPECTOR FOR DAMAGES ARISING OUT OF OR IN CONNECTION WITH THE PERFORMANCE OF THE INSPECTION AND ANY DELIVERY AND USE OF AND RELIANCE ON THE REPORT. CLIENT WAIVES ANY CLAIM FOR CONSEQUENTIAL, EXEMPLARY OR INCIDENTAL DAMAGES.

LIMITATION OF LIABILITY: In the event the Inspector fails to fulfill the obligations under this agreement, Client's exclusive remedy at law or in equity against Inspector is limited to a maximum recovery of damages equal to the inspection fee paid herein. This limitation of liability applies to anyone, including Client, who is damaged or has to pay expenses of any kind, including attorney fees and costs, because of mistakes or omissions by inspector in this inspection or report. Client assumes the risk of losses greater than the refund of the fee paid herein. Client acknowledges that this limitation of liability is reasonable in view of the relatively small fee that the inspector charges for making the inspection when compared with the potential of exposure that the inspector might otherwise incur in the absence of such limitation of liability.

CONFIDENTIALITY OF REPORT: The report is confidential and is for the sole and exclusive use of the Client. It is not to be copied or disseminated to any other party without the express written consent of the inspector. Use of all information contained in the report is specifically restricted to the transaction for which the inspection was performed. Use of or reliance upon the report by other parties, or for other transactions, is strictly prohibited. No third party shall have any right arising from this contract or the report and may not rely on this report. In consideration of the furnishing of the report, the Client agrees to indemnify, defend, and hold harmless Inspector for all costs, expenses, legal fees, awards, settlements, and judgments in any legal proceeding brought by any third party who claims that he/she relied on representation made in such report and was damaged thereby. Client's request that Inspector release copies of the report to any third party or Client's release of copies of the report to any third party shall be at Client's risk with respect to the contents of this paragraph.

DISCLOSURE: Client requests and authorizes Inspector to disclose information and provide a copy of the report to real estate agents, sellers, lenders, attorneys and other parties intimate to this transaction. Inspector authorizes Client to provide a copy of the report to the seller, the lender and the real estate agents in this transaction.

DISPUTE RESOLUTION: Notice: Client understands and agrees that any claim for failure to accurately report the major visible defects of the subject property, as limited herein, shall be made in writing and reported to the inspector within 10 business days of discovery. Inspector agrees to respond promptly to any legitimate complaint and to re-inspect the portion of the property relating to the claimed condition by requesting permission to do so within 5 days of Client's written notice of the claimed condition. Client further agrees that Client and its agents, employees or independent contractors will make no alterations, repairs or replacements to the claimed condition prior to a re-inspection by the inspector. Client understands and agrees that any failure to timely notify inspector and allow adequate time to investigate and re-inspect as stated above shall constitute a

complete bar and waiver of any and all claims Client may have against inspector related to the alleged act, omission, or claimed condition.

MEDIATION: Client agrees that if a dispute or claim arises from this agreement, the inspection, or the report, and the dispute cannot be settled through direct discussions, the parties agree to endeavor first to settle the dispute by mediation before resorting to arbitration. If the mediation does not result in a settlement of the dispute, then any unresolved controversy shall be submitted to arbitration, as set forth below. The parties shall share equally the costs of the mediator.

ARBITRATION: Any and all disputes, not resolved by direct discussions or mediation, concerning the interpretation of this Agreement or arising from the inspection and report shall be resolved by final, binding, non-appealable arbitration conducted in Coryell County, Texas in accordance with the rules of the American Arbitration Association, except that the parties shall mutually agree upon an Arbitrator who is familiar with the real estate industry and the TREC Standards of Practice. At the arbitration the parties may adjudicate all claims and issues, as provided for or limited herein, that could have been raised before a court of law, including but not limited to, lawful attorneys fees and costs, where provided by statute. The decision of the Arbitrator shall be final and binding. The parties shall share equally the cost of the arbitrator. Either party may demand arbitration by written notice to the other. Such demand for arbitration must be made less than one year after the date of the inspection.

STATUTE OF LIMITATIONS: The parties agree that no claim, demand, or action, whether sounding in contract or in tort, may be brought to recover damages against the Inspector, or its officers, agents, or employees MORE THAN ONE YEAR AFTER THE DATE OF THE INSPECTION. TIME IS EXPRESSLY OF THE ESSENCE. Client understands that this time period may be shorter than otherwise allowed by law.

ACCEPTANCE OF REPORT: If the Client has not signed this agreement then acceptance of the report shall constitute agreement with all of the terms of this agreement. The report to be prepared by Inspector shall be considered the final and exclusive findings of the Inspector regarding the inspection of the property. Client shall not rely on any oral statements made by the Inspector prior to the issuance of the printed report.

SEVERABILITY: If any portion of this agreement is found to be invalid or unenforceable by any court or arbitrator, the remaining terms shall remain in force and effect to the parties to the fullest extent possible.

CHOICE OF LAW AND VENUE: This agreement shall be construed and enforced in accordance with the laws of the state of Texas, and venues shall be in Coryell County, Texas.

ACCEPTANCE OF THIS AGREEMENT: This agreement shall be binding upon and inure to the benefit of the parties hereto, their heirs, successors, assigns, agents, and representatives of any kind whatsoever. If Client is married, Client represents that this obligation is a family obligation incurred in the interest of family. With regard to words used herein, the singular shall include the plural and the plural shall include the singular where appropriate. This agreement constitutes the entire integrated agreement between the parties pertaining to the subject matter hereof and may be modified only by a written agreement signed by all of the parties. This agreement supersedes any and all representations or discussions, whether oral or written, if any, among the parties relating to the subject matter of this agreement. No oral agreements, understandings, or representations shall change, modify, or amend any part of this agreement.

	AL WOOD DESTROY	ING INSECT REPOR		Page 1 of 4
Inspected Address	Purmera	City		Zip Code
A. This inspection covers only the multi-family structure, primary will not be included in this inspection report unless specificall B. This inspection is limited to those parts of the structure(s) that limited to (1) areas concealed by wall coverings, furniture, eq or defacing any part of the structure(s) (including the surface in or on the structure(s) at time of inspection but which in the contractive devices. Damage that has been concealed or repositive devices. It visible evidence of active or previous infestation of listed work pest(s) inactive. D. If visible evidence of active or previous infestation of listed work publication of listed work proposed for treatment, it does not imply that damage squalified to give an opinion regarding the degree of structural F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A Work of treatment, including pesticides, baits or other method proposed for treatment, including pesticides, baits or other method proposed for treatment, including pesticides to be used and concovered by warranty, renewal options and approval by a certification that the contracting party. H. There are a variety of termite control options offered by pest of renewal options. I. There are some specific guidelines as to when it is appropriativisible evidence of an active infestation in or on the structure, of treatment is recommended based solely on the presence of buyer and seller should be aware that there may be a variety and effectiveness and may or may not require the services of conducive conditions by either mechanical alteration or cultur conditions. If this inspection report recommends any type of the control operator for a second opinion, and/or the Structural P.	y noted in Section 5 of this retard visible and accessible a julipment and stored articles appearance of the structure may be revealed in the couroying insects, it may not always a peat control company, and destroying insects is repshould be repaired or replaced admage. Evaluation of dam VARRANTY AS TO THE AB and the structure of the property. The incontrol companies. These options of the for corrective treatment to the formation of the control companies. These options of the formation of the formation of the formation of the property. The incontrol companies. These options of the formation of	ss. Sheds, detached garage eport. at the time of the inspection and (2) any portion of the st. b. Inspection does not coverse of repair or replacements be possible to determine to., is frequently repaired priest by defacing the surface as indicated by visual evidence of the inspectors of a previous infestation with the inspector of a previous infestation with the inspector of the inspector of the inspectors of a previous infestation with the inspector of the inspector of the inspector of a previous infestation with the inspector of the inspector of the inspector of a previous infestation with the inspector of the inspector of a previous infestation with the inspector of the	es, lean-tos, fences, guest la Examples of inaccessible ructure in which inspection ver any condition or dament work. The the presence of infestation to the inspection with purpoperance. The WDI inspection company usually are not should be performed by ROYING INSECTS. The provide a diagram of the earranty must specify which ding treatment and any ward duty to provide such informaticy, areas treated, warrantieve treatment may only be reatment and only be returned to conducive conditions (s). These corrective meases where the inspector in incess the most economical ay contact the inspector in	areas include but are not would necessitate removing which was not visible on without defacing or utty, spackling, tape or other specting company cannot tent, has rendered the age is present. The structure (s) inspected and areas of the structure (s) arranties should be provided in the spection on the second of the structure areas to any person other test, treatment techniques a second of the seatment.
1A. InspecTexas Name of Inspection Company	1B.	7426 SPCS Business Lic		
1c. PO Box 26	Purmela	TX 76	566 254-	721-7522
Address of Inspection Company	City	State Zip	Telepho	
1D. Wesley Retherford		1E. Certified Applicator		(check one)
Name of Inspector (Please Print)		Technician		(5.105.115.7)
2Case Number (VA/FHA/Other)	3. <u>Wedne</u> I	esday, April 2 nspection Date	22, 2020	
4A. <u>John Hopkins</u> Name of Person Purchasing Inspection 4B. N/A	Seller Agent	Buyer 🗹 Managemen	t Co. Other	
Owner/Seller				
4C. REPORT FORWARDED TO: Title Company or Mortgagee (Under the Structural Pest Control regulations only the pur			□ Buyer □	=
The structure(s) listed below were inspected in accordance with the of to the conditions listed under the Scope of Inspection. A diagram must 5. Residence	fficial inspection procedures t be attached including all str	adopted by the Texas Struc ructures inspected.	ctural Pest Control Service.	This report is made subject
List structure(s) inspected that may include residence, detached garage	ges and other structures on t	he property. (Refer to Part A	A, Scope of Inspection)	
				-


TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

6A. Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B.	Yes 🗹	No 🗆			
6B. The obstructed or inaccessible areas include but are not limited to the following Attic Insulated area of attic Insulated	ng: Plumbing Area Slab Joints Eaves	s 🗆	Planter box abut Crawl Space Weepholes	ting structure	
7A. Conditions conducive to wood destroying insect infestation? (Refer to Part J, Scope of Inspection) If "Yes" specify in 7B.	Yes 🗆	No 🗹	s Betsell industration in size main 4,895 at the property of the street 94,900 markets and a	SEAR A SEARCH SE	1 , 2
7B. Conducive Conditions include but are not limited to: Wood to Ground Contact (G) Debris under or around structure (K)		Wood Rot (I	s left in place (I) M) nce in Contact with the	Excessive Moisture (Heavy Foliage (N) e Structure (R)	J)
8. Inspection Reveals Visible Evidence in or on the structure: 8A. Subterranean Termites 8B. Drywood Termites 8C. Formosan Termites 8D. Carpenter Ants 8E. Other Wood Destroying Insects Specify: 8F. Explanation of signs of previous treatment (including pesticides, baits, existing as been observed in there is visible evidence of active or previous infestation, it must be noted. The inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspected must be noted in the second blank.)	the following area type of insect(s) m	Ye Ye Ye Ye Ye Ye Ye Ye Ye A ye A hall by	master bedroo	om entry door	ne property
The conditions conducive to insect infestation reported in 7A & 7B: 9. Will be or has been mechanically corrected by inspecting company: If "Yes", specify corrections: 9A. Corrective treatment recommended for active infestation or evidence of previous as identified in Section 8. (Refer to Part G, H and I, Scope of Inspection) 9B. A preventive treatment and/or correction of conducive conditions as identified Specify reason: Refer to Scope of Inspection Part J			Yes 🗹	No 🗆	
	Spot Limite	ed 🗆 —	Bait Name of Pestici	Other Other de, Bait or Other Method	
This company has a contract or warranty in effect for control of the following wood Yes No List Insects: If "Yes", copy(ies) of warranty and treatment diagram must be at		s:	ESE TO STATE OF THE STATE OF TH	con to nation and man in the	

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Diagram of Structure(s) Inspected

The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: EEvidence of infestation; A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H-Carpenter Ants; Other(s) - Specify



Additional Comments	

Page 4 of 4

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company which I am acting is associated in any way with any party to the transaction.

Signatures:	Notice	of Inspection Was Posted At or N	ear
11A. Wes Retherford	12A.	Electric Breaker Box	
Inspector		Water Heater Closet	
Approved:		Bath Trap Access Beneath the Kitchen Sink	□
11B. Wes Retherford 644166	12B.	Date Posted April 22,	
Certified Applicator and Certified Applicator License Number			Date
			A STATE OF THE STA
Stat	tement of Pu	ırchaser	
I have received the original or a legible copy of this form. I have read and unders understand that my inspector may provide additional information as an addendur If additional information is attached, list number of pages:	stand any reco m to this report	mmendations made. I have also r	ead and understand the "Scope of Inspection."
Signature of Purchaser of Property or their Designee	Date		
	_		