

TEXAS ASSOCIATION OF REALTORS®

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2016

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which

		ex	cee	d the	minimum disclosures	required	by t	he C	ode.			
CONCERNING THE PROPERTY AT				1273 G Miller Rd Columbus, TX 78934								
THIS NOTICE IS A DISC DATE SIGNED BY SELI MAY WISH TO OBTAIN. AGENT.	CLOSUI LER AN IT IS I	RE C ND I NOT	OF S S N A \	OT / WAR	A SUBSTITUTE FOR RANTY OF ANY KIN	OF THE ANY IN D BY SI	CON ISPE ELLE w lor	IDIT CTI R, S	TION OF THE PROPERTY AS ONS OR WARRANTIES THE SELLER'S AGENTS, OR ANY ince Seller has occupied the I	E BI	UYE	ER ER
Section 1. The Property	y has t	he it	tem	s ma	rked below: (Mark Y	es (Y), I	No (N		r Unknown (U).) which items will & will not conve	у.		
Item		NI	J	Ite	m	Y	N	Ū	Item	Y	N	U
Cable TV Wiring	~			Liq	uid Propane Gas:	V	1	1.	Pump: sump grinder	1 52	<	
Carbon Monoxide Det.	1]	-LF	Community (Captive)			Rain Gutters		V	
Ceiling Fans	1	(i) (i)		-LF	on Property	V			Range/Stove	V		
Cooktop	1			Но	t Tub		1		Roof/Attic Vents	V		1.
Dishwasher	1			Intercom System		V			Sauna		<	À.
Disposal	V		/	Microwave		V		1.4	Smoke Detector	V		. 1:
Emergency Escape Ladder(s)unknown		~	7	Outdoor Grill Ves		١			Smoke Detector - Hearing Impaired unknown			L
Exhaust Fans	1			Pal	lio/Decking	J	1		Spa		1	
Fences	1			Plu	mbing System	1			Trash Compactor	1 11	1	3.4
Fire Detection Equip.	V			Po			1		TV Antenna		1	12.
French Drain	15 (5)	J	7	Por	ol Equipment	1	V		Washer/Dryer Hookup	V		
Gas Fixtures	1			Pool Maint. Accessories		- 10	1		Window Screens	V		
Natural Gas Lines	1	1 1 1 2	1	Po	ol Heater	, 11% (S	1		Public Sewer System	Г	1	
	131										111	4.14
Item			Y	N	U	A	ddit	iona	al Information	1	1	
Central A/C		\$46.T	V	31	electric gas							
Evaporative Coolers				7	number of units:							
Wall/Window AC Units				1	number of units:			100	A CALL TO A CALL			
Attic Fan(s)			V		if yes, describe:							
Central Heat			V	111	electric gas	number	of u	nits:	not sure			
Other Heat		0/20000	10		if yes, describe:							
Oven			1		number of ovens:1			ectri	c gas other:			
Fireplace & Chimney		Ž		wood gas log	js mo	ock_	_ ot	her:				
Carport				>		attache	d	te. "				ACCESS OF
			1			attache				energy 1 do		manual (
Garage Door Openers			/		number of units: 1	4		าเ	umber of remotes:2			
Satellite Dish & Controls			1			from:ur				0.00		
Security System			7		owned lease from:							
Water Heater			1		electric gas other: number of units:2							
Water Softener			V		owned lease	from:						

Underground Lawn Sprinkler

Septic / On-Site Sewer Facility

Fax: 979.733.9009

manual areas covered:

if yes, attach Information About On-Site Sewer Facility (TAR-1407)

Page 1 of 5 1273 G. Miller

(TAR-1406) 01-01-16 Initialed by: Buyer:
Coldwell Banker - The Ron Brown Company, 930 Walnut Street Columbus, TX 78934 Phone 9
Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48028 Nicola Hammett

automatic

1273 G Miller Rd

Concerning the Property		·		Columbu	the same of the sa		
Water supply provided b	y: cityw	ellMUD	co-op_	_ unknown .	other: _		
(If yes, complete, sig	on, and attach	TAR-1906 con	cernina	lead-based	paint haza	ards).	
Roof Type: metal	, , , , , , , , , , , , , , , , , , ,		Age:	5 years		(app	roximate)
Is there an overlay roccovering)?yes _/ no		the Property	(shingl	les or roof	covering	placed over existing shingle	es or roof
- 1.1.10	MALE SALE	ana liatad in A	hia Caal	ion d that a		unding condition that have	dafaata au
are need of repair?y	es <u>rany</u> of the it	, describe (atta	ich addi	tional sheets	s if necess	working condition, that have cary):	derects, or
				14.7.1		V 1.1.1	
Section 2. Are you (Se aware and No (N) if you			or malfu	ınctions in	any of the	e following?: (Mark Yes (Y)	if you are
Item	YN	Item			YN	Item	YN
Basement		Floors	117,144,17			Sidewalks	V
Ceilings		Foundation	/ Slab(s	3)	7	Walls / Fences	
Doors		Interior Wal		:	1	Windows	V
Driveways		Lighting Fix			J	Other Structural Component	
Electrical Systems		Plumbing S		111,-111	J		
Exterior Walls		Roof			J		
			<u> </u>			ts if necessary):	
							l No (N) if
you are not aware.)		any of the fo			: (Mark Y		IVIN
you are not aware.) Condition		any of the fo	llowing	conditions	: (Mark Y		IVIN
you are not aware.) Condition Aluminum Wiring	eller) aware of	any of the fo	llowing	Conditions Conditions Previous	: (Mark Y	es (Y) if you are aware and	IVIN
you are not aware.)	eller) aware of	any of the fo	llowing	Conditions Condition Previous Previous	: (Mark Y n Foundatio	res (Y) if you are aware and on Repairs	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components	eller) aware of	any of the fo	llowing	Conditions Condition Previous Previous	: (Mark Y n Foundatio Roof Rep uctural Re	res (Y) if you are aware and on Repairs	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak	eller) aware of	any of the fo	llowing	Conditions Condition Previous Previous Other Str	: (Mark Y n Foundatio Roof Rep uctural Re	res (Y) if you are aware and on Repairs	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha	eller) aware of wilt bitat on Prope	any of the fo	ollowing	Conditions Previous Previous Other Str Radon G Settling Soil Move	n Foundatio Roof Rep uctural Re as	es (Y) if you are aware and on Repairs pairs	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines	eller) aware of wilt bitat on Prope	any of the fo	Illowing Y N	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa	n Foundation Roof Reproductural Reas ement ce Structurat	res (Y) if you are aware and on Repairs	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage	wilt bitat on Proper	any of the fo	Illowing Y N Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro	n Foundation Roof Reproductural Reas ement ce Structurund Store	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill	wilt bitat on Proper	rany of the fo	Illowing Y N Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro	n Foundation Roof Reproductural Reas ement ce Structural Stora	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks ints	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea	wilt bitat on Proper ste Springs	rany of the fo	Illowing Y N Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord	n Foundation Roof Reproductural Reas ement ce Structurund Stora I Easemei ed Easemei	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks nents	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea	wilt bitat on Proper	rty	ollowing Y N Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form	n Foundation Roof Repructural Reas ement ce Structurul Stora I Easement ed Easement	re or Pits age Tanks nents inents inents	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroach	wilt bitat on Proper ste Springs ad-Based Pt. H Property ing on others' p	rty	ollowing Y N Y Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form Water Pe	n Foundation Roof Repructural Reas ement ce Structurund Stora I Easement led Easement led Easement	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks nents panses	Y N
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floc	wilt bitat on Proper ste Springs ad-Based Pt. H Property ing on others' p	rty	Illowing Y N Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form Water Pe	n Foundation Roof Reproductural Reas ement ce Structural Stora I Easement led Easem	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks nents panses	Y N
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floo Located in Floodway	wilt bitat on Proper ad-Based Pt. H Property ing on others' p	rty	ollowing Y N Y Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forr Water Per Wetlands Wood Ro	m Foundation Roof Reproductural Reas Ement Sement S	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks nets pents pents pents pents pents	YN
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover	wilt bitat on Proper ad-Based Pt. H Property ing on others' podplain	rty	Illowing Y N Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forn Water Pe Wetlands Wood Ro Active inf destroyin	r (Mark Y n Foundation Roof Republication Re	re (Y) if you are aware and on Repairs pairs pairs pairs re or Pits age Tanks nents plants included in the control of termities or other wood (WDI) no	Y N Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floo Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414	wilt bitat on Proper ste Springs ad-Based Pt. H Property ing on others' podplain	rty	Illowing Y N Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forr Water Pe Wetlands Wood Ro Active inf destroyin Previous	r (Mark Y n Foundation Roof Repuctural Reas ement ce Structural Stora I Easement ded Easement ed Easement ed Easement and Easement on Propert testation of	res (Y) if you are aware and on Repairs pairs pairs pairs pairs re or Pits age Tanks nents pents inents ine	Y N Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floo Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414) Previous Flooding into the	wilt bitat on Proper ste Springs ad-Based Pt. H Property ing on others' podplain rage)	rty	Illowing Y N Y Y Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form Water Pe Wetlands Wood Ro Active inf destroyin Previous Previous	rement ce Structural Reasement ce Structural Reasement de Easement de Easement de Easement de Easement de Concretation on Propest de Easement de Easem	re (Y) if you are aware and on Repairs pairs pairs pairs re or Pits age Tanks nents plants included in the control of termities or other wood (WDI) no	Y N Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414 Previous Flooding into the Previous Flooding onto the	wilt bitat on Proper ste Springs ad-Based Pt. H Property ing on others' podplain rage) ne Structures he Property	rty	Illowing Y N Y Y Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forr Water Per Wetlands Wood Ro Active inf destroyin Previous Previous Previous	reatment termite or Fires	res (Y) if you are aware and on Repairs pairs pairs pairs pre or Pits age Tanks nents e Insulation prty f termites or other wood (WDI)no for termites or WDI WDI damage repaired	Y N Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y
you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was	wilt bitat on Proper ste Springs ad-Based Pt. H Property ing on others' p odplain rage) ne Structures he Property ct	rty	Illowing Y N Y Y Y Y Y Y Y Y Y Y Y Y Y	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form Water Per Wetlands Wood Ro Active inf destroyin Previous Previous Previous Termite of	restation of ginsects treatment termite or Fires or WDI dar	res (Y) if you are aware and on Repairs pairs pairs pairs pairs re or Pits age Tanks nents pents inents ine	Y N Y Y Y Y Y Y Y

(TAR-1406) 01-01-16

Page 2 of 5

1273 G. Miller

1273 G Miller Rd Columbus, TX 78934

Concerning	the Property	y at		Co	lumbus, TX 78	934		
If the answe	er to any of t f repair afte	he items in Se er storms in 1	ection 3 is yes, ex 2016	plain (attacl	additional shee	ts if necess	ary):	
	777.7							
	1.5			7. 7.	A 112 1 4 1 4 1 1			
	*A sing	le blockable r	nain drain may ca	use a sucti	on entrapment h	azard for an	individual.	
which has	not been p	reviously di	of any Item, equip sclosed in this r	notice?	yes no If y	the Proper es, explain	ty that is i	n need of repair, ditional sheets if
	· .			1,5.		1		
		1						
not aware.		eller) aware	of any of the fo	llowing (M	ark Yes (Y) if y	ou are awa	re. Mark N	lo (N) if you are
Y N	Room addit	ions, structur ce with buildi	al modifications, ong codes in effect	or other alte	ations or repairs	made with	out necess	ary permits or not
	Manage	f accordation	ns or maintenance	State of the state		4.5	10	
	Manag	er's name:				Phone	:	
	Fees of Any un If the P	r assessment naid fees or a	s are: \$ ssessment for the nore than one ass	Property?	ves (\$	and are	: manda) no other asso	atory voluntary
_ <u>~</u>	with others.	If yes, compl	ties such as pools ete the following: es for common fac	- 14		o If yes, de	scribe:	
	Any notices Property.	of violations	of deed restriction	ns or gover	nmental ordinan	ces affectin	g the cond	tion or use of the
	Any lawsuit to: divorce,	s or other leg foreclosure, l	al proceedings din neirship, bankrupt	rectly or ind	irectly affecting tes.)	he Property	. (Includes	but is not limited
		on the Propei ition of the Pr	ty except for thos operty.	se deaths ca	aused by: natura	l causes, s	uicide, or a	ccident unrelated
	Any condition	on on the Pro	perty which mater	rially affects	the health or sa	fety of an in	dividual.	
	hazards su	ch as asbesto attach any cei	s, other than routi s, radon, lead-bas tificates or other o mediation or other	sed paint, u documentati	rea-formaldehyd on identifying the	e, or mold.		
	Any rainwa water supp	ter harvesting ly as an auxili	system located o ary water source.	on the Prope	erty that is larger	than 500 g	allons and	that uses a public
	alteriated Printer Attaches	10.70	a propane gas sy					
_ 🗹	Any portion	of the Prope	rty that is located	in a ground	water conservati	on district o	r a subside	nce district.
(TAR-1406)		Initia	led by: Buyer:		and Seller:	m. Kil	<u> </u>	Page 3 of 5

Concerning the Pro	operty at	1273 G Miller Rd Columbus, TX 78934					
If the answer to an	y of the items in S to all in this secti	ection 5 is yes, o	explain (attach additional sheets	if necessary):			
				,			
		1.1.	*	***************************************			
Section 7. Within regularly provide	the last 4 years Inspections and	s, have you (Se who are either	eller) received any written ins licensed as inspectors or oth complete the following:	pection reports from persons wh erwise permitted by law to perform			
Inspection Date	Туре	I Name o	f Inspector	No. of Pages			
inspection Date	Туре	Name	/ mapeciol	No. or rages			
**************************************	127, 14						
1 1, 1 11 11	1 11 11 11 11 11	5. 5. 1 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.					
provider?yes _ Section 10. Have	vno you (Seller) ever or a settlement or	r received proc award in a lega	eeds for a claim for damage al proceeding) and not used the	e Property with any insurance to the Property (for example, and proceeds to make the repairs for			
	1						
*Chapter 76 smoke detect which the du local building A buyer may of the buyer evidence of	Chapter 766 of the sheets if necessary and the Health actors installed in a welling is located, aliding code require g official for more it is family who will it the hearing impair	e Health and Sa y): and Safety Code accordance with including performements in effect information. o install smoke of reside in the dwo	requires one-family or two-far the requirements of the building mance, location, and power sour in your area, you may check undetectors for the hearing impaire celling is hearing-impaired; (2) the mosed physician; and (3) within the second of the second	mily dwellings to have working ag code in effect in the area in the requirements. If you do not inknown above or contact your d if: (1) the buyer or a member e buyer gives the seller written to days after the effective date,			
the buyer m	nakes a written re	equest for the stallation. The part	eller to install smoke detectors rties may agree who will bear t	for the hearing-impaired and			

(TAR-1406) 01-01-16

initialed by: Buyer: ____, ___ and Seller ____, ____ Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 France | Seller | Se

Page 4 of 5

1273 G. Miller

1273 G Miller Rd Columbus, TX 78934 Concerning the Property at Seller acknowledges that the statements in this notice are true to the best of Seller's belief and that no person, including the broker(s), has instructed or influenced Seller to provide inaccurate information or to omit any material information. Signature of Selle 7. Printed Name: ADDITIONAL NOTICES TO BUYER: (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department. (2) If the property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information. (3) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information. (4) The following providers currently provide service to the property: phone #: Electric: phone #: Sewer: phone #: Water: phone #: Cable: _ phone #: Trash: phone #: Natural Gas: phone #: Phone Company: phone #: Propane: (5) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	

(TAR-1406) 01-01-16

Page 5 of 5



TEXAS ASSOCIATION OF REALTORS®

INFORMATION ABOUT ON-SITE SEWER FACILITY

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS® IS NOT AUTHORIZED. ©Texas Association of REALTORS®, Inc., 2004

CONCERNING THE PROPERTY AT Columbus	iller Rd TX 78934
A. DESCRIPTION OF ON-SITE SEWER FACILITY ON PROPERTY:	
(1) Type of Treatment System: Septic Tank Aerobic Treatme	Unknown
(2) Type of Distribution System:	Unknown
(3) Approximate Location of Drain Field or Distribution System:	OF HOUSE Unknown
(4) Installer:	
(5) Approximate Age: 59PS	Unknown
B. MAINTENANCE INFORMATION:	
(1) Is Seller aware of any maintenance contract in effect for the on-site If yes, name of maintenance contractor:	ewer facility? Yes No
Phone: contract expiration date: Maintenance contracts must be in effect to operate aerobic treatment sewer facilities.)	and certain non-standard" on-site
(2) Approximate date any tanks were last pumped?	
(3) Is Seller aware of any defect or malfunction in the on-site sewer facilityes, explain:	
(4) Does Seller have manufacturer or warranty information available for	p
C. PLANNING MATERIALS, PERMITS, AND CONTRACTS:	
(1) The following items concerning the on-site sewer facility are attache planning materials permit for original installation final installation maintenance contract manufacturer information warranty in	ection when OSSF was installed
(2) "Planning materials" are the supporting materials that describe submitted to the permitting authority in order to obtain a permit to in	ne on-site sewer facility that are all the on-site sewer facility.
(3) It may be necessary for a buyer to have the permit to of transferred to the buyer.	erate an on-site sewer facility
(TAR-1407) 1-7-04 Initialed for Identification by Buyer, and Sel	Byn, TIM Page 1 of 2
Coldwell Banker - The Ron Brown Company, 938 Walnut Street Columbus, TX 78934 Phone: 979. Nicola Hammett Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 Yes The Ron Brown Company, 938 Walnut Street Columbus, TX 78934 Phone: 979.	.4594 Fax: 979.733.9009 1273 G. Miller

Nicola Hammett

D. INFORMATION FROM GOVERNMENTAL AGENCIES: Pamphlets describing on-site sewer facilities are available from the Texas Agricultural Extension Service. Information in the following table was obtained from Texas Commission on Environmental Quality (TCEQ) on 10/24/2002. The table estimates daily wastewater usage rates. Actual water usage data or other methods for calculating may be used if accurate and acceptable to TCEQ.

<u>Facility</u>	Usage (gal/day) without water- saving devices	Usage (gal/day) with water- saving devices
Single family dwelling (1-2 bedrooms; less than 1,500 sf)	225	180
Single family dwelling (3 bedrooms; less than 2,500 sf)	300	240
Single family dwelling (4 bedrooms; less than 3,500 sf)	375	300
Single family dwelling (5 bedrooms; less than 4,500 sf)	450	360
Single family dwelling (6 bedrooms; less than 5,500 sf)	525	420
Mobile home, condo, or townhouse (1-2 bedroom)	225	180
Mobile home, condo, or townhouse (each add'l bedroom)	75	60

This document is not a substitute for any inspections or warranties. This document was completed to the best of Seller's knowledge and belief on the date signed. Seller and real estate agents are not experts about on-site sewer facilities. Buyer is encouraged to have the on-site sewer facility inspected by an inspector of Buyer's choice.

Richard H. Martin	
Descript males and admed	h

Date

Signature of Seller Ronalee P. Martin

Date

Receipt acknowledged by:

Signature of Buyer

Date

Signature of Buyer

Date