

LINE	BEARING	DISTANCE
L1	S69°01'50"W	114.78'
L2	S57°33'09"W	39.10'
L3	S29°17'51"W	26.33'
L4	S02°13'38"W	34.17'
L5	S23°09'45"E	49.54'
L6	S04°04'38"E	59.64'
L7	S16°05'19"E	39.53'
L8	S37°44'08"E	57.05'
L9	N78°58'48"W	113.12'
L10	N75°35'21"W	120.69'
L11	N72°12'21"W	162.32'

TM113-A-57
Hershel J. Childress, Sr.
D.B.788 p.856
P.B.E p.96

TM99-1-14
S. Vance Wilkins, Jr.
D.B.799 p.818
P.B.I p.20

TM99-1-13
S. Vance Wilkins, Jr.
D.B.799 p.818
P.B.I p.20

TM99-1-6
S. Vance Wilkins, Jr.
D.B.768 p.509
P.B.I p.20

TM99-1-4
Formerly
Katherine J. Perry
D.B.480 p.208
Contract Purchaser
Otis J. Weaver, III

Notes:

1. Tax Map Parcel No.99-1-5.
2. This plat agrees with found plats, deed descriptions, ground evidence and local witnesses as near as possible.
3. This plat is based on a current field survey.
4. Drainfield site located as staked by Robert Johansen, Onsite Soil Evaluator, DPOR No. 1940001333.




14S0175
FB1173-50

Boundary Survey of Tax Map Parcel No.99-1-5 for Howard C. Anby Cheryl Carnevale Anby

Current Owner: Ruthia M. Ingram Estate D.B.965 p.704
Courthouse District, Amherst County, Virginia

December 16, 2014

Scale: 1in.=100ft.



Maxey & Associates, P.C.

Land Surveyors • Engineers • Planners • Consultants
P.O. Box 90 • Farmville Virginia 23901 • Tel:434-392-8827