




- Notes:
1. Owner: KL Components
 2. Zoning: RP
 3. This survey performed without benefit of a title report.
 4. Property shown hereon is in Flood Zone "X", a non hazard Flood Zone, from FEMA community panel 51033C0350C, dated 03/02/2009.

I hereby certify that this Boundary Survey, to the best of my knowledge and belief, is correct and complies with the minimum procedures and standards established by the Virginia State Board of Architects, Professional Engineers, Land Surveyors and Certified Landscape Architects.

**Plat Showing a Boundary Survey of
9.66± Acres of Land Lying on the South Line of
State Route #656, Dry Bridge Road
Reedy Church District, Caroline County, Virginia**



Date: March 7, 2019 Scale: 1" = 100' JN: 55130169

Goodfellow, Talbert, Beard, and Associates Inc.
 7104 Mechanicsville Turnpike / P.O. Box 539
 Mechanicsville, Virginia 23111
 (804) 746-7097 Fax (804) 730-7275
ENGINEERING - SURVEYING - PLANNING