



MICHAEL TURNER LAND SURVEYING, INC.

109 HENDERSON STREET GILMER, TEXAS 75644 903-843-2965

DESCRIPTION - 2.717 ACRES ESTEVAN MORO SURVEY, A - 4 UPSHUR COUNTY, TEXAS

BEING a 2.717 acre tract of land situated in the Estevan Moro Survey, Abstract No. 4, Upshur County, Texas and said tract being that called 2.72 acre tract of land described in a deed to R. B. Denton and Joan Denton filed October 4, 2007 and recorded in Volume 764, Page 23, Official Records of said county, said 2.717 acre tract being more particularly described as follows;

BEGINNING at a 5/8 inch iron rod found at the Northwest corner of said 2.72 acre tract, same being the Southwest corner of the residue of a called 149.92 acre tract described in Volume 115, Page 425, Deed of Trust Records and said corner being in the East line of the residue of a called 27.7 acre tract of land described in Volume 368, Page 655, Deed Records;

THENCE N 89deg 34min 02sec E (deed N89deg34min02secE 300.04 feet) along the North line of said 2.72 acre tract (Bearing Base) and along a South line of said residue tract described in Volume 115, Page 425 a distance of 299.79 feet to a 1/2 inch iron rod found at the Northeast corner of said 2.72 acre tract, same being an ell corner of said residue tract, a 5/8 inch iron rod found bears S00deg00min19secW a distance of 3.2 feet;

THENCE S 00deg 00min 19sec W (deed S00deg00min12secW 396.58 feet) along the East line of said 2.72 acre tract and at 182.14 feet passing 0.23 feet West of a 5/8 inch iron rod found at the Northwest corner of a called 0.70 acre tract of land described in Volume 110, Page 11, Official Records and continuing along said East line and along the West line of said 0.70 acre tract and along same bearing in all a total distance of 396.70 feet to a 5/8 inch iron rod found at the Southeast corner of said 2.72 acre tract, same being the Southwest corner of said 0.70 acre tract and said corner being in the North right of way line of State Highway No. 154 and said corner being 0.4 feet West of a 3/8 inch iron rod found and a concrete right of way marker found bears S86deg53min47secE a distance of 108.07 feet;

THENCE in a Westerly direction along said right of way line as follows;

N 86deg 53min 47sec W a distance of 89.43 feet to a concrete right of way marker;

S 87deg 12min 37sec W a distance of 200.48 feet to a concrete right of way marker;

S 88deg 54min 13sec W a distance of 9.82 feet to a 5/8 inch iron rod found at the Southwest corner of said 2.72 acre tract, same being the Southeast corner of a called 1.06 acre tract of land described in Volume 488, Page 655, Deed Records;

THENCE N 00deg 03min 23sec W (deed N00deg00min58secW 399.57 feet) along the West line of said 2.72 acre tract and along the East line of said 1.06 acre tract and along the East line of the residue of previously mentioned 27.7 acre tract a distance of 399.54 feet to the Point of Beginning and containing 2.717 acres of land.

This description is to be used in conjunction with the plat of this survey for a more complete report.

I, MICHAEL L. TURNER DO HEREBY STATE THAT THIS DESCRIPTION WAS PREPARED FROM AN ACTUAL BOUNDARY SURVEY MADE ON THE GROUND BY ME IN MARCH, 2010.

esten

MICHAEL L. TURNER

R.P.L.S. NO. 4606



UP3110