

SAN ANTONIO BOARD OF REALTORS, INC.

RESIDENTIAL LOT SELLERS DISCLOSURE NOTICE



To Be Completed By The Seller For Residential Lots

THIS FORM IS FURNISHED BY THE SAN ANTONIO BOARD OF REALTORS® FOR USE BY ITS MEMBERS. USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF A BOARD/ASSOCIATION OF REALTORS® IS NOT AUTHORIZED.

Concerning the Property at:

131 THRILL HILL,	MOUNTAIN HOME, TX 78056
	perty Address)
This notice is a Disclosure of Seller's knowledge of the condition any inspections or warranties the purchaser may wish to obtain.	n of the Property as of the date signed by seller and is not a substitute for It is not a warranty of any kind by seller, seller's agents, or any other agent.
A. Mark below: (Y) for Yes (N) for No (U) for Unknown.	
Y N U Discorded in 100-Year Flood plain Present Flood Insurance Previous Flooding onto the Property Soil Movement Surface Structures or Pits Underground Storage Tanks Wetlands on Property Discorded in 100-Year Flood plain	Y N U Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Intermittent or Weather Springs Landfill Lead-Based Paint Hazards Radon Gas
If you answered yes to any of the above, please explain:	
B. General Information: Is the Seller aware of any of the following:	•
or responsibility for maintenance may have an effect of the control of the contro	at may affect the Property. on of "setback" requirement. ting the Property. operty ents pursuant to a claim made for damage to the Property and not used
yesno; If yes, explain: 8. Any tax exemption(s) which you (Seller) currently claim	im for the Property. If yes, list:
9. Any violent crime or death on the Property except for unrelated to the Property. Concerning the Property at	
SABOR Form 550 08-03-98 Residential Lots Sellers Disclosure Notice	Initialed for Identification by:BuyerSeller

Mark below	(Y) for Yes (N) for	No (U) for Unknown			
Y N U D X D 10	. Any Homeowner's	Association or mainte	nance fees or asses	sments. If yes, complete:	
	Amount of fee or as	sessment: \$			
	■ Mandatory	□ Voluntary	Name of Associat	ion:	
	Manager's Name:				
	Due:	_Monthly	Quarterly	Annually	
	Any unpaid fees or	assessments for the F	Property:Ye	sNo	
□ ≱ (□ 11	If yes, amount \$. Municipal Utility Dis	trict which has any au	ithority over the Pro	perty; If yes, Name of District:	
If you answ	ered yes to any of the	above, please expla	in:	190 maring provided A 4 Annie Carlon (190 maring 190 ma	
					·
	ES AVAILABLE : r Available (O) on sit	e (U) Unknown			
	atural Gas ectric	City X Well D M	•	ARDS (SUPPOSED) AQUITER (name of water source).	
IF WELL O	N PROPERTY: appr	oximate depth 190	well extends into $\underline{\mathscr{E}}$	(name of water source).	The well does to does not
need repai	r, if so, explain:				
IF SEPTIC	SYSTEM: In Place	Required	·	_ Not Allowed Raukaul E E green of Seller	Fgert 3/2/22
advise you relied on th	is notice as true and	closure Notice was co	ompleted by Seller, eason to believe it	and Other Broker, as of the date signed. The Listin to be false or inaccurate. YOU AF O CLOSING.	ng Broker and Other Broker have RE ENCOURAGEDTO HAVE AI
The unders	signed purchaser here	eby acknowledges rec	ceipt of the foregoing	notice.	
Signature o	of Buyer		Date	Signature of Buyer	Date

TEXAS REALTORS

UPDATE TO SELLER'S DISCLOSURE NOTICE

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS®, INC. IS NOT AUTHORIZED.

©Texas Association of REALTORS®, Inc. 2018

UPDATE TO THE SELLER'S DISCLOSURE NOTICE CO Mountain Home, TX 78058-5030	ONCERNING THE PROPERTY AT 131 Thrill Hill Dr.
Seller is aware of the following new information regarding are changed to read (cite specific sections and copy the any necessary changes):	applicable language in the sections verbatim, making
See attached well and septic inspections con	mpleted 3/23/22, 3 pages to follow
This Update to the Seller's Disclosure Notice was comincluding the broker(s), has instructed or influenced Sematerial information. The brokers have relied on this intellieve it to be false or inaccurate.	eller to provide inaccurate information or to omit any
Seller acknowledges that the statements in this form are true to the best of Seller's belief.	Buyer acknowledges receipt of this form.
Steven Edward Eggert 03/26/2022	
Signature of Seller Date	Signature of Buyer Date
	•
Printed Name: Steven Edward Eggert	Printed Name:
Pocusigned by: Rachael Elizabeth Egypt DEERFORZY92499	
Signature of Seller Date	Signature of Buyer Date
Printed Name: Rachael Elizabeth Eggert	Printed Name:
Fillited Natile.	i ilitted Ivallie.
/TVD 1/19\ 02.01.19	Page 1 of 1

(TXR 1418) 02-01-18

Steve & Rachael

Phone: (512) 575-3644 Fax: 830-634-2010

HILL COUNTRY SEPTIC SERVICE

1-800-728-2025

P.O. Box 291186

Kerrville, Texas 78029-1186

5495 Hwy. 27 East

CALISTICA

03-23-2022

Visual Inspection Report

Seller:

Steven Eggert

Buyer:

Property Location:

131 Thrill Hill, Mt. Home, TX 78058

To whom it may concern:

Hill Country Septic Service performed a visual inspection of the unlicensed, Conventional, septic system at the above referenced property. At the time of the inspection the fluid level in the septic tank was correct. The septic tank does not leak. The septic tank does not need to be pumped out at this time. There are some minor feeder roots getting in the tank at the inlet and outlet ports. We ran water through the system for approximately 45 minutes and the leach field seems to be taking the water properly at this time. The leach field shows no signs of failure on the surface.

At the time of this inspection, there was no evidence that the facility was causing or threatening to cause injury to the public health or nuisance conditions and was generally functioning in a satisfactory manner.

This report is based upon a limited inspection and is not a guarantee or warranty that the facility will, in fact, operate or function properly for any particular length of time. Latent defects may exist which would render the system in violation of the rules and/or standards.

Sincerely,

Jose T. Barrientos, Vice-President

Hill Country Septic Service

Installer II #27860 & Site Evaluator #24414

page 1 of 3

Docusigned by:

Steven Edward Egychadhaul Elizabeth Egych

DEELF990A7792499...

Conventional Septic System Inspection

Date: 3-23-202-2
Aminus Times Class
Arrival Time: 9:26 Departure Time: 1/20 Seller: Buyer:
Seller: Buyer: Address: 131 Mvill Hill, Maintain Ham, D
Address: 131 Mvill Hill, Maintain Ham, To
Phone Number:
Inspection Ordered by:
System Licensed: Yes (No.
As-built Provided: Yes (No)
System Type: Commercial Residential
Conventional with: Pipe & Gravel Pumped Conventional
How many Tanks:
Are there any Pumps: Yes No
Is Alarm Installed: Yes No
Is Alarm Working Properly: Yes No
Clean-out by house: (Yes No
Water Standing in Clean-Out: Yes
Is water getting from house to tank: So No
Size of Pipe from House to Tank(s): 3'
Riser Lids Secure on Arrival: Yes No
Riser Lids Secure on Departure: Yes No
Risers within 12" of Natural Ground: Yes No
Solids in Primary Tank: 6 "inches
Water Level in Primary Tank: 7.5 inches from bottom of tank lid to water level, before adding water
Water Level in Primary Tank after running water: 7 inches
Any Roots in Primary Tank: To No Feeder Routs
Sanitary T installed in Primary Tank: Ves No
Down Spout Extension in Primary Tank: Ver No
Solids in Secondary Tank: (9" inches
Water Level in Secondary Tank: 7.5 inches from bottom of tank lid to water level, before adding water
Water Level in Secondary Tank after running water: 7 inches
Any Roots in the Secondary Tank: (Yes) No Roeder RODT
Down Spout Extension in Secondary Tank: No
Does Septic System Need Pumping: Yes
Ran water for 45 minutes to 1 hour: Yes No
Are there one or two drainfield beds: One Two
Is there a bull-run valve installed: Yes No
Is Bull-run valve working properly: Yes No
Is Drainfield taking water OK: Yes No
Did we walk the drainfield area: Yes No
Is water surfacing at the drainfield area: Yes
Inspection port at drainfield: Yes No
Water level at Inspection Port if holding water: inches Comments/Repairs Needed: Tocameral Hawy tank Sallal
Comments/Repairs Needed: Wecumend Many Tank Saller
Inspection Performed by:
DocuSigned by: DocuSigned by:
page 2 of 3 Steven Edward Eggert Ralial Elizabeth Egypt



Kerr Country Pump Company LP

1150 Sidney Baker South Kerrville, TX 78028

Office #830-257-4107

	Date	Invoice #	
-	3/25/2022	24898	

Bill To	
Steve Eggert	
131 Thrill Hill	
Mt. Home, TX 78058	

P.O. No.	Terms	Project	

Qty	Description	Rate	Amount
1	Water Samples	20.00	20.00
1	Fuel Surcharge	18.00	18.00
1.5	Service Time Hours	130.00	195.00
	Well Inspection 131 Thrill Hill Rd.		
	1 HP Submersible pump (no date code) pulling 9.8 Amps (good) Well making good flow - 8 to 10gpm 1" pipe at well head Pressure tank was low on air - added 30psi - 35/55 system - date code on		
	tank 4/21/2000 No storage tank		
	All equipment working at time of inspection		

If credit card is used please add 2% fee

Balance due in full upon receipt- A Finance Charge of 1.5% Per Month (18% per Annum) will be charged on all accounts unpaid after 30 days-A 2% service charge will be added for paying with a credit card. Regulated by the Tx. Dept. of Licensing & Reg. P. O. Box 1215 Austin, TX 78711-800-803-9202 512-463-7880

kerreountrypump.net	Kerrpump@hetc.net

 Subtotal
 \$233.00

 Sales Tax (8.25%)
 \$16.09

 \$249.09

Docusigned by:
Steven Edward Eggert

DEE4F96A2792499...

