LEVEL 1 INSPECTION

CHIMNEY INSPECTION REPORT

SERVICE PROVIDER:	CUSTOMER	CUSTOMER:							
🛫 wite 🥔				Name GINGER ALLEN					
				Address 426 Ranch Rd E 962					
Bringing Comfort Home P.O. Box 278 * Cypress, TX 77410 Austin 512-000-8703 * San Antonio 210-685-225 * Dallas 214-224-0826 Houston 281-4519-2713 www.naturesownchimerg/deaning.com				City Round Mountain State TX Zip 78663 Phone (571) 276-7946					
									Source
				Technician james	natio comminino pocaning com		Map Code		
Service Date 5/26/21	Time-In		Time-Out					·	
			nine-Out						
SOURCE									
Fireplaces, Number of:	3	_							
Construction	[]Factory-built	[]Factory-built []Modular		[X]Masonry					
Fireplace opening sizes	1" x	2	*X*	3	"x	-			
Heating Appliances, Number of:		_							
Туре	[]Insert	[X]Freestanding	[]Furnace	[l				
Fuel	[X]Wood	[]Coal	[]Gas	[]Oil	[]				
Chimney									
Construction	[]Factory-built	[X]Masonry	[]Other						
Chimney height		feet							
Liner	[X]Flue tile	[]Stainless	[]Cast	[X]Unlined					
Flue sizes	[]8"x8" []8" Round	[]8"×13" [X] flat top	[X] 13"x13"	[]8"x17"	[].	3"x17"	[]6" Round		
Last cleaned	year(s)		er []	Jnknown					
COMMENTS									
CHIMNEY CLEAN AND	OR INSPECTION							QUOTE AMOUNT	
			INVOICE / REC						
ANNUAL INSPECTION It is recommended by the National Fire Protection Association (NFPA) that an annual inspection of all fireplaces, chimneys,				EIPT					
and vents be conducted. Your annual inspection is scheduled for:				SERVICE PERFORMED					
				Front room needs a cap 1313ss 1313ss Back two need a custom flat top cap Custom cap All three need interior tuckpoints 3x in					
CUSTOMER VERIFICATION This Chimney Inspection Report is based on the fin	dings of a visual inspection perform	ed at the time of cleaning. It is r	not to						
be considered a certification of the safety or merit of the chimney, but is merely a courtesy to our customer. It should be noted that conditions of use and hidden construction are beyond our control; therefore, no guarantee is being made for the safety or function of any appliance and none is to be implied. Having read this report. I fully understood the condition of my fireplace, appliance, and/or vent system, and the limitation									
				\$1000 deposit was paid					
of this report as specified in the paragraph above. BY SIGNING THIS YOU ACKNOWLEDGE YOU READ THE BACK OF THE INVOICE									
b. 1.11									
Customer MMM			METHOD OF P						
Signature	Date	0/26/21	[X]CREDIT CA	RD	[]VOUCHER	[]CASH	[]CHECK		
							AMOUNT PAID	2116 52	
							ANUOUNT FAID	2.10.02	

BALANCE

NO WARRANTY UNLESS SPECIFIED

ALL DEPOSITS ARE NON REFUNDABLE

This is a limited inspection only. The Company shall only inspect and report on those systems and components that are readily accessible at time of chimney inspection.

This report supersedes all previous communications and represents a visual evaluation of those "systems" outlined in the invoice that were readily accessible on this day only. The Report does not represent an endorsement for or against the purchase of real estate. This Report is intended to provide an overview of the existing conditions at time of inspection only and should not be used as an indicator of future performance; no expressed or implied warranties or guarantees of any kind are given in conjunction with the inspection of the premises. A building and its components are subjected to constantly changing conditions and environment and problems can develop immediately upon completion of the inspection. Therefore, we do not issue a guarantee or warranty on our inspection.

The contents of this *Report* are CONFIDENTIAL, for the exclusive use of the Client named in the Inspection Agreement. The *Report* is not assignable to third parties or transferable to others. Should this *Report* be sold or transferred to another party, all opinions are null and void and the *Company* disclaims any and all liability which may result from this *Report* and the opinions contained therein. The *Company* reserves the right to institute legal litigation against any party who distributes or shares information Contained within this inspection *Report* with other parties not involved in the sales transaction without our written and/or oral approval.

Make sure that it accurately documents the visual problems that were disclosed to you during the hours of the home inspection. If you have any questions or require any further clarification, please call my office for free assistance. If you should desire a "return visit inspection, please contact my office for a quotation based on minimum trip charge and hourly rate. If you were absent during this chimney inspection or you do not understand the *Final Report*, you must **call the office immediately** to speak with the inspector who performed the inspection. At that time, the inspector will give you a verbal consultation of the property. The *Company* cannot be held liable for your understanding or misunderstanding of this *report* contents if you choose not to consult with the inspector.

To prevent "false expectations," please understand that the task of a home inspector is to function as a "general practitioner" who is trained to be a professional in the identification of typical home deficiencies. He or she performs a visual examination to identify certain components, states their general condition, locates telltale problems and then recommends that you consult with appropriate tradesmen or other expects for further evaluation and repair estimates. <u>Be advised that a chimney inspector will not find every little problem during the inspection and that</u> <u>undisclosed problems are often revealed during repairs or after further evaluation by tradesmen</u>. A home inspector and that <u>undisclosed problems are often revealed during repairs or after further evaluation by tradesmen</u>. A home inspector does NOT perform destructive testing, can NOT see through walls, and does NOT move furniture or stored goods or predict the future. **Only problems that are** *readily accessible* at time of inspection will be included in the invoice. If the inspector recommends consulting other specialized experts, any such consultation shall be at the *Client's* sole discretion and expense. Any comments regarding correction or repair are based on typical practices used by contractors in the field and are not made as specific recommendations for the noted problems. In all cases, specialists, in appropriate fields, should be consulted before any work is undertaken. Correction or repair of problems or outfitions noted in this *Report* should be done by qualified professionals in accordance with the requirements of the building code. Any work done by the homeowner is strictly at the *Client's* risk.

DISCLAIMER: Those defects hidden or concealed at time of inspection are EXCLUDED from this report. The *Client* understands that only deficiencies which are exposed and *readily accessible* at the time of inspection will be included in the *chimney Report* and that all opinions expressed concerning the adequacy of the structure or systems are based on visual examination only and do not involve engineering calculations or testing of any nature.

If the **INSPECTION AGREEMENT** is unsigned, delivery and payment for the inspection *Final chimney Report* shall constitute acceptance of all terms on the **CHIMNEY INSPECTION**.

Signed on: Thursday, 05/27/2021