

INVOICE



INVOICE#14516
DATE:12/27/21

P.O. Box 2221
Canyon Lake, TX 78133-0009
Phone 830-899-2971
Bakersepticsservice@yahoo.com

Inspection Performed by:
Colin Baker
License # MT0001295
Maintenance Technician

TO Scheschuk, Mike
1259 Forrest View Dr.
Blanco TX, 78606
512-293-8988

INSPECTOR		JOB	PAYMENT TERMS	DUE DATE	
Colin Baker		Inspection	PAID		
QTY	DESCRIPTION			UNIT PRICE	LINE TOTAL
1	Visual Inspection of septic system located at 1259 Forest View, Blanco, TX 78606.			250.00	250.00
1	Septic pump up to 1000 Gallons			440.00	440.00
Inspection date: 12/27/21					
A. Septic Tank appeared to be a 1000-gallon single compartment concrete tank as per Septic Tank pumping.					
B. The pretest level in the tank appeared to be at the normal operating range as per 285.32 Criteria for Sewage Treatment System (TCEQ).					
C. Water field test done to determine if the lateral lines were taking water at time of inspection. At 10:10 am started to add water to septic tank. At 10:55 am, 300 gallons of water had been added as per hose meter and the water level had not risen in the tank from the pretest level. The test appeared to show that the lateral lines had taken 300 gallons of water without any back up.					
D. Concrete lid appeared to be intact.					
E. Inlet and outlet tee in both septic tanks were present. Inspector was able to locate a two-way cleanout between the house and the tank as per 285.32 (TCEQ).					
Please refer to Texas Commission on Environmental Quality or local regulator for any and all regulations regarding your septic system.					
Paid by: Check# Cash Visa MasterCard				SUBTOTAL	690.00
Date: Approval #				TAX 8.25%	
Signature:				TOTAL	690.00