



Mold Inspection & Testing | MI&T  
Nationwide Unbiased Mold Testing  
Website: <http://mitmold.com>  
[855-600-6653](tel:855-600-6653) | [Office@mitmold.com](mailto:Office@mitmold.com)

Client Name: Joe Quinonez Clearance 2  
Inspector: Austin, TX - Dale White  
Location Address: 3625 Ranch Rd 3347, Round Mountain, TX, 78633  
Inspection Date: 08/03/2023  
Time of Inspection: 3:00 PM



Outside Temperature: 96  
Outside Humidity: 38  
Outside Conditions: clear

Indoor Temperature: 95  
Indoor Humidity: 39

***Basic Mold Inspection Details:***

A basic mold inspection by an MI&T inspector includes a full visual assessment of a property's readily accessible areas with use of specific tools of our trade in order to identify any possible "red flags" that could be causing a mold growth problem. It also includes the collection of 2 air samples. The first must be taken from outside and serves as a "control," every home or business has "normal" levels of mold and this will determine what is acceptable for a property in your area. It also shows that all the equipment/supplies used were working properly and makes our results legally binding. The other air sample is taken from the area inside the home or business that the inspector and client agree is the area of greatest concern. These 2 air samples will determine whether or not elevated conditions exist at the property in question.

***Advanced Mold Testing:***

For those that wish to confirm the source of a mold problem and receive specific instructions for remediation, additional mold testing is necessary. We offer surface samples via tape lift/swabs and in-wall cavity air samples to accomplish this task. When an inspector finds something specific that they believe is compromising the indoor air quality of a property, he will suggest one of the above samples mentioned. If the problem shown by the general air sample is the same seen at the localized testing location, we can not only confirm that is the source of a problem, but also offer exactly what you need to do in order to fix it. If the problem area is large enough, multiple samples may be suggested to establish precisely what has been contaminated. Additional general air samples are also beneficial to determine how far an air quality problem has spread.



*Clearance Letter*



Mold Inspection & Testing | MI&T  
Nationwide Unbiased Mold Testing  
Website: <http://mitmold.com>  
[855-600-6653](tel:855-600-6653) | [Office@mitmold.com](mailto:Office@mitmold.com)

---

08/06/2023

3625 Ranch Rd 3347, Round Mountain, TX, 78633

To whom it may concern,

On 08/03/2023, a mold inspection was conducted at 3625 Ranch Rd 3347, Round Mountain, TX, 78633 to determine if elevated mold conditions exist within the property listed. A full visual inspection was performed, and samples were collected from the following areas:

- 286-0110 - Kitchen.
- 286-0121 - Southwest room.
- 286-0130 - Great room.
- 286-0119 - Outside

Laboratory analysis of the samples taken show that elevated mold conditions do not exist at the property in question. The collected Indoor air quality sample(s), when compared to the control, are within normal range. Based on the visual inspection and laboratory results, our professional opinion is that Professional Mold Remediation is NOT required.

If you have any questions or concerns, please contact us.

Sincerely,

Austin, TX - Dale White  
MI&T-Mold Inspection & Testing  
<http://mitmold.com>  
[Office@mitmold.com](mailto:Office@mitmold.com)



## Basic Mold Inspection Report



Mold Inspection & Testing | MI&T  
Nationwide Unbiased Mold Testing  
Website: <http://mitmold.com>  
[855-600-6653](tel:855-600-6653) | [Office@mitmold.com](mailto:Office@mitmold.com)

# of air samples taken: 4

# of surface samples taken: 0

Recommended Samples NOT Submitted: 0

Areas of Concern:

### General Observations

Observation	Yes	No
Musty Smell or Odor		✓
Water Damage		✓
Excess Humidity		✓
Excess Moisture		✓
Visual Growth		✓
Roof Leak		✓
HVAC Problem		✓
Plumbing Issue		✓
Health Complications		✓
Localized Problem		✓
Widespread Problem		✓
Control Sample Taken	✓	

Additional Notes: Clearance testing only

## Mold Sample Details



Mold Inspection & Testing | MI&T

Nationwide Unbiased Mold Testing

Website: <http://mitmold.com>

855-600-6653 | [Office@mitmold.com](mailto:Office@mitmold.com)

**Sample ID:** 286-0110

**Type of Sample:** Air Sample

**Area Tested:** Kitchen.

**Picture of Sample Medium:**



**Picture of Sample Collection:**



<i>Sample Details</i>	<i>YES</i>	<i>NO</i>
Air Sample	✓	
Surface Sample		✓
Control Sample		✓
General Air Sample		✓
In-Wall Cavity Sample		✓
Swab		✓
Tape Lift		✓

## Mold Sample Details



Mold Inspection & Testing | MI&T

Nationwide Unbiased Mold Testing

Website: <http://mitmold.com>

855-600-6653 | [Office@mitmold.com](mailto:Office@mitmold.com)

**Sample ID:** 286-0121

**Type of Sample:** Air Sample

**Area Tested:** Southwest room.

**Picture of Sample Medium:**



**Picture of Sample Collection:**



<i>Sample Details</i>	<i>YES</i>	<i>NO</i>
Air Sample	✓	
Surface Sample		✓
Control Sample		✓
General Air Sample		✓
In-Wall Cavity Sample		✓
Swab		✓
Tape Lift		✓



## Mold Sample Details



Mold Inspection & Testing | MI&T

Nationwide Unbiased Mold Testing

Website: <http://mitmold.com>


855-600-6653 | [Office@mitmold.com](mailto:Office@mitmold.com)

**Sample ID:** 286-0130

**Type of Sample:** Air Sample

**Area Tested:** Great room.

**Picture of Sample Medium:**



**Picture of Sample Collection:**



<i>Sample Details</i>	<i>YES</i>	<i>NO</i>
Air Sample	✓	
Surface Sample		✓
Control Sample		✓
General Air Sample		✓
In-Wall Cavity Sample		✓
Swab		✓
Tape Lift		✓

## Mold Sample Details



Mold Inspection & Testing | MI&T

Nationwide Unbiased Mold Testing

Website: <http://mitmold.com>

855-600-6653 | [Office@mitmold.com](mailto:Office@mitmold.com)

**Sample ID:** 286-0119

**Type of Sample:** Air Sample

**Area Tested:** Outside

**Picture of Sample Medium:**



**Picture of Sample Collection:**



<i>Sample Details</i>	<i>YES</i>	<i>NO</i>
Air Sample	✓	
Surface Sample		✓
Control Sample		✓
General Air Sample		✓
In-Wall Cavity Sample		✓
Swab		✓
Tape Lift		✓



Mold Inspection & Testing | MI&T  
Nationwide Unbiased Mold Testing  
Website: <http://mitmold.com>  
[855-600-6653](tel:855-600-6653) | [Office@mitmold.com](mailto:Office@mitmold.com)

---

No elevated mold conditions detected after remediation. Remediation was successful. Mold lab results are attached in the email with this report.

Attached are the lab results from independent AIHA accredited microbiology laboratory. If you have any questions about this report, the lab results, or anything else, please feel free to give us a call at the number listed below.

Austin, TX - Dale White  
MI&T-Mold Inspection & Testing  
[www.MitMold.com](http://www.MitMold.com)  
855-600-6653





## *Additional Mold Inspection Pictures*



Mold Inspection & Testing | MI&T

Nationwide Unbiased Mold Testing

Website: <http://mitmold.com>

855-600-6653 | [Office@mitmold.com](mailto:Office@mitmold.com)

---





Matthew Dale White Texas MAC #1528 Expiration - 4/26/2024