	STATE OF TEXAS WELL REPORT for Tracking #48188				
Owner:	Joe Herron	Owner Well #:	No Data		
Address:	3010 W. RR 1431 Kingsland, TX 78639	Grid #:	57-38-2		
Well Location:	13744 Hwy 281 N. Round Mountain, TX 78663	Latitude:	30° 28' 01" N		
		Longitude:	098° 19' 27" W		
Well County:	Blanco	Elevation:	No Data		
Type of Work:	New Well	Proposed Use:	Domestic		

Drilling Start Date: 8/20/2003 Drilling End Date: 8/20/2003

	Diameter (in.) Top Dep	oth (ft.)	Bottom Depth (ft.)
Borehole:	8	0		60
Drilling Method:	Air Hammer			
Borehole Completion:	mpletion: Straight Wall			
	Top Depth (ft.)	Bottom Depth (ft.)	Des	scription (number of sacks & material)
Annular Seal Data:	0	20		4 1/2
Seal Method: Po	oured Slurry	Dis	tance to Pr	operty Line (ft.): No Data
Sealed By: B.			c Field or other ntamination (ft.): No Data	
	Distance to Septic Tank (ft.): No Data			Septic Tank (ft.): No Data
			Metho	d of Verification: No Septic
Surface Completion:	Surface Sleeve Ir	nstalled		
Water Level:	10 ft. below land surface on 2003-08-20 Measurement Method: Unkno		urement Method: Unknown	
Packers:	Plastic 20			
Type of Pump:	No Data			
Well Tests:	Estimated	Yield: 40 GPM		

	Strata Depth (ft.)	Water Type		
Water Quality:	No Data No Data			
	Chemical Analysis Made		: Unknown	
	Did the driller I	knowingly penetrate any strata which contained injurious constituents?		wn
Certification Data:	driller's direct supervi correct. The driller ur	at the driller drilled this well (or the we sion) and that each and all of the stat nderstood that failure to complete the turned for completion and resubmitta	tements he required it	rein are true and
Certification Data: Company Information	driller's direct supervi correct. The driller ur the report(s) being re	sion) and that each and all of the stat nderstood that failure to complete the turned for completion and resubmitta	tements he required it	rein are true and
	driller's direct supervi correct. The driller ur the report(s) being re	sion) and that each and all of the stat nderstood that failure to complete the turned for completion and resubmitta	tements he required it	rein are true and
	driller's direct supervi correct. The driller ur the report(s) being re : Highland Drilling I 309 Fraizer St.	sion) and that each and all of the stat nderstood that failure to complete the turned for completion and resubmitta nc.	tements he required it	rein are true and

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	1	Top Soil
1	2	Clay
2	30	Sugar Sand
30	60	Lime Stone

Casing: BLANK PIPE & WELL SCREEN DATA

 Dia. (in.)
 New/Used
 Type
 Setting From/To (ft.)

 4 1/2 New PVC 0 30 SCH #40

4 1/2 New Perf 30 50 SCH #40

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540