

# OFFICIAL GEORGIA WOOD INFESTATION INSPECTION REPORT

Company Name Arrow Exterminators, Inc. License No. 100456  
Address 368 Craig St, Suite 102, East Ellijay, GA 30540  
Telephone No. 706-503-7034 Date of Issuance 01/21/2025  
Seller Marilynn Trotter Inspector Devin Thomas SP14487  
File No. \_\_\_\_\_ Purchaser(s) \_\_\_\_\_

## SCOPE OF INSPECTION

An inspection of the below listed structure(s) was performed by a qualified inspector employed by this firm to determine the presence or previous presence of an infestation of the listed organisms and is not intended to be a structural report. Neither is this a warranty as to absence of wood destroying organisms. **This report is subject to all conditions enumerated on the reverse side and is issued without warranty or guarantee except as provided in Rule 620-6-.03 of the Rules of the Georgia Structural Pest Control Act or subject to any treatment guarantee specified below.**

Main Structure House on a Slab  
Other Structure(s) NA  
Address of Structure(s) 110 Sunset Cove, Ellijay, GA 30540-6710

## FINDINGS

Inspection Reveals Visible Evidence of:

Subterranean Termites  
Powder Post Beetles  
Wood Boring Beetles  
Dry Wood Termites  
Wood Decaying Fungus (Not Molds and Mildews)

### Active Infestation

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>

### Previous Infestation

YES	NO
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>

Were any areas of the structure obstructed or inaccessible?

☒ YES ☐ NO

If yes, list these areas (see Item 3 on reverse side of form)

### Wall and Floor Coverings, Fixtures, Appliances, Stored Items, Exterior Cladding

The following conditions conducive to infestation for wood destroying organisms were found at the time of inspection. The location of these conditions conducive to infestation are indicated on the attached diagram:

No conducive conditions found at this time.

Remarks/Additional Findings:

See attached graph/Mold addendum

**NOTE:** If visible evidence of active or previous infestation is reported it should be assumed that some degree of damage is present and a diagram identifying the structure(s) inspected and showing the location of such evidence must be attached to this form. Evaluation of damage and any corrective action should be performed by a qualified inspector in the building trade approved by the purchaser and lending agency.

## TREATMENT

The above described structure(s) was treated by this company as follows:

Organism	Treatment Date	Contract Expiration	Type Treatment (Chemical Barrier, Bait, Wood Treatment)
Subterranean Termites	_____	_____	NA
Powder Post Beetles	_____	_____	
Wood Boring Beetles	_____	_____	
Dry Wood Termites	_____	_____	
Wood Decaying Fungus	_____	_____	

The present treatment warranty(ies) is:

- ☐ Transferable to any subsequent owner of the property upon payment of a fee on or before the expiration date.  
☐ Not transferable to any subsequent owner of the property.  
☒ The above structure(s) are not covered by a treatment contract with this company.

This structure has a current Official Waiver Form issued by this Company

☐ YES ☒ NO

If Yes, a copy must be attached as part of this report.

## CERTIFICATION

This is to certify that neither I, nor the company has had or contemplates having any interest in the property involved, nor is acting in any association with any party to the transaction.

*Chris Elliott SP13898*

Signature of Designated Certified Operator

Signature of Purchaser or Legal Representative Acknowledging Receipt of Report

Copies to: ☐ Purchaser ☐ Mortgagee ☐ Realtor ☐ Seller

## CONDITIONS GOVERNING THIS REPORT

1. This report is limited to the five organisms listed.
2. This report covers only those structures listed on the front.
3. Inspection, including sounding and/or probing, was performed in only those areas which were readily accessible. Inaccessible areas not inspected include, but are not limited to areas obstructed by, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances or other personal items. The inspection also included a check of company records to determine if the structure has been treated and/or under renewal contract with the company within the past two years for any of the covered organisms. A copy of any current Official Waiver or Exception Form II form for this structure must be included as part of this report.
4. Reporting of Wood Destroying Fungi on this report is intended to cover only white rot, brown rot or water conducting fungi infestations which occur below the first floor level. This report does not cover the reporting of molds and mildews. Structural Pest Control companies are not responsible for inspecting for molds.
5. The term Wood Boring Beetles as used on the reverse side means only those beetles which are known to establish and maintain a continuing infestation in structures, such as, but not limited to the Old House Borer.
6. Regardless of whether any visible evidence of infestation by any of the listed Wood Destroying Organisms is found during inspection, if an infestation of one or more of these organisms from which apparent freedom was certified is found within 90 days of issuance of this report the property shall receive, free of charge, a minimum adequate treatment for control of the infestation consistent with Rules 620-6-.03 (1) (a), (b), (c) and (d), of the Georgia Structural Pest Control Act.
7. This is not a structural report. A wood destroying organism inspector is not ordinarily a construction or building trade expert and is therefore not expected to assess structural soundness. Evaluation and correction of damage which may have resulted from an active or previous infestation should be performed by a qualified inspector in the building trade, who is approved by the purchaser and the lending agency.
8. This report implies no responsibility on the part of the Georgia Department of Agriculture or the Georgia Structural Pest Control Commission to enforce or require anything other than treatment or retreatment to the minimum adequate treatment requirements specified in Rule 620-6-.04.
9. Conditions conducive to Infestation means conditions that exist in a structure that favor the development of wood destroying organisms. These are limited to: cellulosic material underneath a building and wood in contact with the soil which has not been treated with preservatives to a minimum preservative retention designed for ground contact and ventilation of the under-floor space between the bottom of the floor joist and the earth that does not meet the requirements of the International Residential Building Code for one and two family dwellings, the latest edition as adopted and amended by the Georgia Department of Community Affairs. Any condition conducive to infestation as defined above, that is known to have existed at the time of inspection and was not reported and is found within 90 days of the issuance date of this report shall be corrected free of charge by the licensee.

The format of this report conforms to the Rules of the GEORGIA STRUCTURAL PEST CONTROL COMMISSION. Chapter 620-6-.03, as amended. Printed and distributed, to provide a central source of supply, as a service to the industry by GEORGIA PEST CONTROL ASSOCIATION.  
2034 Beaver Ruin Road  
Norcross, Georgia 30071, 770/417-1881





## ADDENDUM FOR DISCLAIMER OF MOLD

110 Sunset Cove

Street

Ellijay

City

GA

State

30540-6710

Zip

Arrow has not inspected and is not qualified to inspect the air, structure, and surfaces of the indicated structure or dwelling for the presence of any molds, mold-like conditions, or other non-wood destroying fungi (including but not limited to *Stachybotrys atra*) that could affect the health of any occupant. Arrow's liability for inspection or reporting of the presence of such molds, mold-like conditions, or non-wood destroying fungi is specifically disclaimed. Mold, mold-like conditions, and fungi not affecting wood are not wood destroying organisms covered by this report or this inspection and are therefore outside the scope of this report.

Questions regarding the presence of mold, mold-like conditions, or non-wood destroying fungi in this structure should be referred to the appropriate mold professional or certified industrial hygienist chosen by the seller, lender, or purchaser, as appropriate.

ARROW EXTERMINATORS

[www.arrowexterminators.com](http://www.arrowexterminators.com)

2:43 PM Tue Jan 21

...

LTE 68%



qpublic.schneidercorp.com



Gilmer County, GA - Report: 3055H 004

PestPac - Location 2504621

Dawson County, GA - Report: 016A 071

