

The revision dates below represent the file save dates for the posting of the listed revisions. The archive dates for these revisions are posted within the ARCHIVE REVISIONS box in the drawing title block.

08/11/95 - SLW
P-3805-32-025-44 out of 025-44 (24)

04/24/00 - SLW
Pin of P-3505-32-029-46 out to P/W on Sat 19 (25)

03/11/02 - SLW
P-3577-023-001-00 thru 105-0 pointed into
NUNDEENEN PLATE (03)

06/17/02 - bc
Pin of P-3505-32-025-44 out to P/W (03)

07/08/02 - bc
Pin of P-3505-32-025-44 out to P/W on Sat 19 (02)

10/30/03 - JCI
Pin of S10059-32-5620 out to P/W (03)

04/14/04 - TH
P-3805-32-021-34 pointed into BULLER PARK (24)

06/21/04 - VMC
Pin of S10059-32-5620 out to P/W Eastern (05)

04/27/05 - SLW
P-4540-012-018-0 out of 017-4 (now -0) (08)
P-5485-012-002-0 out of 001-4 (now -0) (06)

09/26/05 - TH
Pin of P-3805-32-025-44 out to P/W Eastern (05)

01/08/05 - SLW
Pin of 0505 P/W combined w/ P-10580-001-005-0 (now -4) (06)

08/17/06 - SLW
P-5485-007-105-0 out of 005-4 (now -0) (07)

01/17/08 - ET
Pin of P-3505-32-025-46 out to 25050 P/W (38)

03/05/08 - VMW
44044 Pin located 44044s Part 10, Trays 5 - 10,
P-3505-32-004-44 resubmitted as 004-44 (21)



