

HARRISON COUNTY, TEXAS

MOUND POND

MOSSEY ACRES SUBDIVISION

Found 3/4" Iron Pipe

S 50°44'46"E 50.02'

Found 3/4" Iron Pipe

S 69°24'55"E 99.78'

Found 3/4" Iron Pipe

Water's Edge

FLOOD AREA ZONE "A"

LOT 5

LOT 4

LOT 6

N 20°12'59"E 218.54'

N 07°41'43"E 187.83'

Wood Deck

FRAME DWELLING

Carport

LOT 3

S 06°46'52"W 159.52'

N 81°53'00"W 90.00'

N 85°47'00"W 100.00'

Set 1/2" Iron Rod
From which a Fence
Corner post bears
N 59°02'05"E - 1.85'

Set 1/2" Iron Rod

Found 3/4" Iron Pipe
from which a Fence
Corner post bears
N 46°57'42" W - 3.81'

KINGS ROAD

PLAT SHOWING

RT. 2, BOX 85AA, KARNACK TEXAS

LOT 4 & 5

MOSSY ACRES SUBDIVISION
JAMES ADAMS SURVEY, A-33
HARRISON COUNTY, TEXAS

Cabinet A, Slide 98

To CHIP JOHNSON, MOSELEY ABSTRACT, exclusively
I, Mark H. Patheal, hereby certify that this survey was made on the
ground, under my supervision, and that this plat correctly represents
the facts found at the time of survey. I further state that there
are no visible easements or right of ways except as shown hereon,
other than those serving same. There are no buildings or other improvements
or encroachments except as shown. Parts of this lot do fall within the
100 Year Flood Plane per HUD Community Panel # 480319 0004B
11/01/89

Bearing Basis: Bearings are oriented to record
bearing of North line of Lot 3.

Mark H. Patheal, R.P.L.S. # 4528



LEGEND

Dashed Wire Fence	---
Chain Link Fence	—X—
Wood Fence	—□—
Tree, Cedar	—T—
Pavement	—E—
Concrete	—C—
Pyramid	—P—

Surveying & Mapping By

Surveyed for