

CERTIFICATE OF SURVEY

IN THE NORTH HALF OF SECTION 13,
T.20N., R.27W., AND SECTIONS 7, 8 AND 18 OF
T.20N., R.26W., M.P.M., SANDERS COUNTY, MONTANA.

THIS SURVEY WAS PERFORMED AT THE REQUEST
OF WILLIAM HAGEDORN IN FEBRUARY, 2006.

LINE	BEARING	DISTANCE	L34	S89°11'18"E	40.09'
L1	S87°16'10"E	85.91'	L35	S88°10'12"E	65.76'
L2	N81°59'21"E	299.50'	L36	N89°45'57"E	262.07'
L3	S81°08'43"E	138.48'	L37	S88°05'27"E	92.28'
L4	S75°19'34"E	257.67'	L38	N89°20'42"E	211.33'
L5	N87°48'16"E	94.19'	L39	S86°22'30"E	153.85'
L6	S76°46'44"E	234.83'	L40	N83°55'25"E	44.40'
L7	S68°49'08"E	199.94'	L41	N87°37'34"E	122.78'
L8	S68°11'57"E	677.02'	L42	N76°19'28"E	235.64'
L9	S87°37'31"E	92.60'	L43	N77°51'23"E	78.66'
L10	S67°01'53"E	139.89'	L44	N75°11'53"E	166.22'
L11	S70°03'36"E	676.95'	L45	N71°58'06"E	185.35'
L12	S63°58'59"E	342.20'	L46	N80°54'45"E	80.64'
L13	S77°22'24"E	73.12'	L47	N75°08'31"E	149.31'
L14	S69°35'00"E	82.83'	L48	N74°06'05"E	315.94'
L15	S59°51'43"E	125.77'	L49	N80°21'03"E	204.74'
L16	S63°57'58"E	84.11'	L50	N84°26'42"E	237.34'
L17	N79°35'13"E	29.08'	L51	N84°56'43"E	253.99'
L18	S56°31'58"E	206.90'	L52	S83°23'59"E	39.22'
L19	S64°53'45"E	389.30'	L53	S68°50'31"E	162.00'
L20	S24°41'42"E	25.82'	L54	N79°38'17"E	34.53'
L21	S59°07'25"E	232.98'	L55	S40°42'15"E	188.37'
L22	S87°49'28"E	44.45'	L56	S38°47'22"E	113.64'
L23	S55°31'53"E	33.46'	L57	S35°14'06"E	155.70'
L24	S86°17'12"E	27.48'	L58	S29°16'22"E	103.31'
L25	N68°28'50"E	40.42'	L59	S30°19'02"E	355.96'
L26	S67°05'51"E	40.13'	L60	S35°57'08"E	129.66'
L27	N35°38'06"E	28.30'	L61	S45°30'41"E	209.39'
L28	S45°45'39"E	46.84'	L62	S40°54'40"E	201.90'
L29	S64°02'26"E	91.95'	L63	S38°46'31"E	301.29'
L30	S82°54'17"E	180.81'	L64	S32°49'05"E	298.82'
L31	S73°11'28"E	52.63'	L65	S30°30'36"E	375.21'
L32	S89°35'01"E	143.12'	L66	S30°14'10"E	389.05'
L33	N88°43'48"E	133.87'	L67	S88°30'16"E	120.96'
			L68	S89°35'01"E	59.82'

