



Jirasek Realty P: (254)770-0996



The information contained herein was obtained from sources deemed to be reliable. MapRight Services makes no warranties or guarantees as to the completeness or accuracy thereof. 844.932.6277 - mapright.com

|D Gunter 86 85.9 ac

SOIL CODE	SOIL DESCRIPTION	ACRES	%	CAP
HeB	Heiden clay, 1 to 3 percent slopes	53.9	62.72	2e
HgD2	Heiden-Ferris complex, 3 to 8 percent slopes, moderately eroded	20.6	23.98	4e
WcB	Wilson clay loam, 1 to 3 percent slopes	1.8	2.07	3e
Ту	Tinn clay, 0 to 1 percent slopes, frequently flooded	9.6	11.23	5w
TOTALS		85.9	100%	2.84

Capability Legend

Increased Limitations and Hazards

Decreased Adaptability and Freedom of Choice Users

1	2	3	4	5	6	7	8	
•	٠	٠	•	٠	٠	٠	٠	
٠	٠	٠	•	٠	٠	٠		
•	٠	٠	•	٠	٠	٠		
•	٠	٠	•	٠	٠			
•	٠	٠	•	٠				
٠	٠	٠	•					
٠	٠	٠						
٠	٠							
٠								
	• • • • • • • • • • • • • • • • • • • •	 . .<		 • •<		$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		$\begin{array}{c ccccccccccccccccccccccccccccccccccc$

Grazing Cultivation

- (c) climatic limitations (e) susceptibility to erosion
- (s) soil limitations within the rooting zone (w) excess of water