Nixon Lake Rd - 5 ac Tracts

Texas, AC +/-





Boundary

Nixon Lake Rd - 5 ac Tracts

Texas, AC +/-





Boundary



ID Boundary 10.0 ac


SOIL CODE	SOIL DESCRIPTION	ACRES	%	CAP	
32	Frelsburg clay, 3 to 5 percent slopes	0.1	0.83	Зе	
56	Renish clay loam, 1 to 5 percent slopes	5.1	50.9	4s	
27	Cuero sandy clay loam, 1 to 3 percent slopes	4.8	48.1	2e	
6 Bleiblerville clay, 1 to 3 percent slopes		0.0	0.17	Зе	
TOTALS		10.0	100%	3.03	

Capability Legend								
Increased Limitations	and Haz	ards						
Decreased Adaptabili	ty and Fr	eedon	of Cl	noice I	Jsers			
Land, Capability								
	1	2	3	4	5	6	7	8
'Wild Life'	•	•	•	•	•	•	•	•
Forestry	•	•	•	•	•	•	•	
Limited	0	•	0	0	•	•	0	
Moderate	0	0	0	0		•		
Intense	0	0	0	0				
Limited	•	•	•	•				
Moderate	•	•	•					
Intense	•	•						
Very Intense								

Grazing Cultivation

- (c) climatic limitations (e) susceptibility to erosion
- (s) soil limitations within the rooting zone (w) excess of water

5 Acres / Nixon Lake Road, Burton, Tx 77835





Blakey Land Surveying

Burton, Texas 77835-5794

Telephone/Fax 979-289-3900

EARL HENRY HAIGHT TRUST TRACT B - 5.00 ACRE TRACT

ALL THAT TRACT OR PARCEL OF LAND containing 5.00 acres, situated in Washington County, Texas, being out of the Samuel Hinch Survey, Abstract No. 60, and being a portion of a called 27.619 acre tract described in that deed dated December 21, 2015, from Early Henry Haight, et al, Successor Co-Trustees of the Evelyn Haight Family Trust, U/A May 1, 1995 to Earl Henry Haight, Trustee for the Earl Henry Haight Trust, recorded in Volume 1530, Page 0495, Official Records of Washington County, Texas, said 5.00 acre tract being more particularly described as follows:

BEGINNING at found ½ inch iron rod, lying in the Northeast margin of Nixon Lake Road (public right-of-way), marking the West corner of the Dean Roy Haight and Dave Ray Haight Trust called 43.381 acre tract (Volume 1530, Page 0492, Official Records of Washington County, Texas), marking the South corner of the original called 27.619 acre tract (hereafter referred to as "original tract"), and marking the South corner of the herein described tract;

THENCE along the Northwest margin of said road, with a portion of the Southwest line of the original tract, N 44deg 52min 19sec W, 269.41 ft., to a ½ inch iron rod, set for comer, marking the South comer of a 5.00 acre tract (surveyed this date, designated Tract A), and marking the West comer of the herein described tract;

THENCE departing said road margin, with the Southeast line of Tract A, with the Northwest line of the herein described tract, severing the original tract, N 45deg 38min 58sec E, 808.30 ft., to a ½ inch iron rod, set for corner, marking the East corner of said Tract A, and marking the North corner of the herein described tract;

THENCE with the Northeast line of the herein described tract, S 45deg 00min 00sec E, 269.42 ft., to a ½ inch iron rod, set for comer, lying in the Southeast line of the original tract, also lying in the Northwest line of the aforementioned Dean Roy Haight and Dave Ray Haight Trust called 43.381 acre tract, and marking the East corner of the herein described tract;

THENCE with a portion of the Southeast line of the original tract, S 45deg 38min 58sec W, 808.90 ft., to the PLACE OF BEGINNING and containing 5.00 acres of land.

September 25, 2020

W.O.#2020-3054

Michael J. Blakey Registered Professional Land Surveyor No. 5935

lait brepared and made a part of this description.

