



- | | | | |
|----|---------------|----|---------------|
| 1 | N 43° 12.123 | 11 | N 43° 12.035 |
| | W 093° 51.463 | | W 093° 51.460 |
| 2 | N 43° 12.087 | 12 | N 43° 12.035 |
| | W 093° 51.455 | | W 093° 51.455 |
| 3 | N 43° 12.039 | | |
| | W 093° 51.452 | | |
| 4 | N 43° 11.991 | 4 | |
| | W 093° 51.492 | | |
| 5 | N 43° 12.017 | | |
| | W 093° 51.436 | | |
| 6 | N 43° 12.036 | | |
| | W 093° 51.468 | | |
| 7 | N 43° 11.938 | | |
| | W 093° 51.467 | | |
| 8 | N 43° 12.058 | | |
| | W 093° 51.469 | | |
| 9 | N 43° 11.987 | | |
| | W 093° 51.482 | | |
| 10 | N 43° 12.086 | | |
| | W 093° 51.481 | | |

4" plastic


8" diam



John Quinn
Tiling Done 11-26-03
Bingham Twp. Hancock Co.
S.E. 1/4 Sec. 24



North



Quinn Farm
Bingham Twp.
S.E. 1/4 Sec 24
Tiling Done Fall
2001

installed 11/10
6" plastic main, 4" laterals
N43 12.131'
W093 51.532'

N43 12.112'
W093 51.625' 4" 425'

N43 12.099'
W093 51.640' 4" 500'

N43 12.121'
W093 51.534'

N43 12.075'
W093 51.648' 4" 240' 6" 210'

N43 12.108'
W093 51.538'

N43 12.075'
W093 51.682' 6" 1060'

N43 12.057'
W093 51.638' 4" 305' clay

N43 12.047
W093 51.705

