

STATE OF TEXAS

COUNTY OF MORRIS

Denney Land Surveying, ULC does hereby certify that the following plat and description were perpeted from an actual survey made on the ground during the month of September, A.D. 2017.

DESCRIPTION OF PROPERTY

Being a treat of Land located in the George M. Junes Survey, Abstract No. 157. Morris County, Texas, and being all of the cantainder of a called 13,699 acre tuned conveyed to Olive Farms, Inc. in a Deed found in Volume 329, Page 201 of the Official Public Records of Morris County, Texas, and being more particularly described as follows:

Beginning in 1/2" fron red with a cap mirked "Himpton" found at the southeast corner of said 17,699 acre tred and a northeast corner of a called 167.265 agree tred (Treat I) conveyed to Byon Wood and with. Ji Wood in a Deed Joundi N Volame 328, Page 291 of the Olficial Public Records of Morris County. Texas, the same lying in the western teglated way like of U.S. Highway, No. 259, and/in the west line 65 called 1,599 acre for (Pared 4) conveyed to the State of Jewns in a Judyment Joundin Volume 108, Page 278 of the Owel Records of Morris County, Texas, from which a 12" tree for fonce corner bems North 36" East of Jewns in a Judyment Joundin Volume 108, Page 278 of the Owel Records of Morris County, Texas, from which a 12" tree for fonce corner bems North 36" East of

Thence South 87°21'20" West, generally along a fence, along the south line of said 13.699 acre tract and a north line of said 167.265 acre tract, passing the end of said fence, then continuing on for a total distance of 880.68 feet to a 1/2" iron ford with a cap marked "Denney" set at the southwest corner of said 13.699 are tract and din ell vertice of said 167.265 are truet.

Thence North One'S 172" West, along the west line of said 13.699 are tract and an east line of said 167.285 are truet and the southwest corner of a called iron rod thurst on the east side of a 6" wooden fence corner, at the northwest corner of the remainder of said 13.699 are truet and the southwest corner of a called iron rod thurst on the east side of a 6" wooden fence corner, at the northwest corner of the remainder of said 13.699 are truet and the southwest corner of a called

ion rod fund) on the east side of a 6" wooden fence corner, at the northwest corner of the remainder of said 13.699 ages treet and the southwest corner of a called 3.311 ages (1904) Trust #1) conveyed to Danny M. Lilley and wife, Laura J. Lilley in a Deed found in Volume 408, Page 282 of the Official Pairlie Records of Morris County, Texas:

Ť

There South 18*1314* East, generally along a fence, along the north line of the remainder of said 13.689 are that and the south line of said 3.311 are trust for a distance of 16.576 feet to a 12% ton rod with a cap marked "Donney" as it at the northest sorner of the remainder of said 13.699 are trust and the southeast sorner of the remainder of said 13.690 are trust and the southeast sorner of the remainder of said 13.690 are trust and the southeast sorner of the southeast sorner of a called 84.733 are trust ontwo years of the 19.4 feet, and a concrete monament found at the northeast corner of said 3.311 are trust and the southeast corner of a called 84.733 are trust conveyed to Dump M. Lilley and with, Lauta J. Lilley in a Doed found in Valume 405, Page 573 of the Official Public Records of Morris County, Texas bears North 15*2750°W Sext a distance of 322.50 feet.

Thence South 15*2720°W jetst altering of 322.50 feet.

530.95 feet to the place of beginning, and containing 11.316 acres offland

Mount Pensant, TX 75456 Office: 903-577-0424 Fax: 903-577-0425 Licensed State Land Surveyor Denney Land Surveying, LLC Firm Registration No. 10194010 John W. Denney Registered Professional Land Surveyor, No. 6516



ismail: john@derneylandsurveying.com Job No. 2017-D201b

| 1.3 | 1.2 | ľ | Course |
|---------------|---------------|---------------|----------|
| S 89°45'29" W | N 12°45'50" W | S 89°16'50" W | Bearing |
| 79.80 | 139.38' | 205.62 | Distance |

Volues: Work indicational utilities shown. No cascanent revents performed and no cascanents shown. No flood information revented.

(2) Bearings are based on grid north in NADS(2011). Twas Coordinate System, Nursh Cordinate One Oto 42027, as observed by GNSS.

(3) The property shown was serveyed based on a provided deed and/or legal description. It is possible one or more thanks have been severed from the subject, and this survey does, not includ to describe power-day of all or any part of the subject.

(4) Controlling monuments are (4) all iron rods shown as found, (b) the paved tenterline of HW 259.