



## LEGEND

— × —	FENCE (AT CENTER OF (FENCE POST)	D WM	WATER METER
— эне —	- OVERHEAD POWER	⊳u WV	MATER VALVE
PP g	POWER POLE	p⊲ ICV	IRRIGATION CONTROL VALVE
LP-\$	LIGHT POLE		
	GUY WIRE(S)	<i>s</i>	TRAFFIC/PARKING SIGN
LR.F.	IRON ROD FOUND		
LR.S.	IRON ROD SET	0	TELEPHONE
TXDOT MON.	TEXAS DEPARTMENT OF TRANSPORTATION MONUMENT	73.09	MANHOLE CABLE TELEVISION
F.C.P.	FENCE CORNER POST	GA. T. K	SUB-SURFACE BOX
LP.F.	IRON PIPE FOUND	4.4	CONCRETE
PH-¢	FIRE HYDRANT	//_	EDGE OF ASPHALT
ss/co •	SANITARY SEMER CLEAN-OUT	DHS.	COVERED AREA
		NOTE: ALL IRON RODS FOUND ARE 1/2" UNLESS OTHERWISE NOTE. ALL IRON RODS SET ARE 1/2" WITH YELLOW CAP STAMPED "ARTHUR SURVEYING COMPANY"	
O SSW4	SANITARY SEWER MANHOLE		

## **BOUNDARY SURVEY**

Lot 16R-1, Block B of The Orchards Tarrant County, Texas

PC/TECH: FC/SWIM DATE: 06-27-17 SCALE: 1"= 30' ASC NO.: 1706502





mailing address 11848 Native Drive Republic Title of Texas, Inc. 620 N. Carroll Ave., Suite 100 Southlake, Texas 76092 Ph.: 817.424.3373 Fax: 817.424.3376

SURVEYOR'S CERTIFICATION: The undersigned does hereby certify to Republic Title of Texas, Inc. (G.F.# 1010-22305-84T), that this survey was this day made on the ground of the property legally described heroron and correct and to the best of my knowledge, there are no issible discrepancies, conflicts, shortages in rare, boundary line conflicts, encreachments, overlapping of improvements, ensements or rights of way that I have been advised of except as shown heroron. The bearings shown hereon are based on the above referenced recorded may or pit unless otherwise

FLOOD NOTE: It is my opinion that the property described hereon is not within the 100-year floed zone area according to the Federal Emergency Management Agency Flood Insurance Rate Map Community-Panel No. 480582 0010 K, presset reflective date of map, September 25, 2009, herein properly situated within 200- X\* (Shaded).



220 Elm St., # 200 - Lewisville, TX 75057 Ph. 972.221.9439 - TFRN# 10063800

