





LINE	BEARING	DISTANCE
L1	S15°08'02"W	50.81'
L2	S05°39'34"E	41.98'
L3	S14°49'40"E	81.07'
L4	S26°33'51"W	135.67'
L5	S05°51'45"W	70.04'
L6	S14°20'06"E	98.88'
L7	S32°31'35"E	99.92'
L8	S08°40'55"W	125.26'
L9	S07°12'58"E	29.36'
L10	S47°27'04"E	139.08'
L11	S43°39'48"E	168.24'
L12	S70°39'50"W	39.03'
L13	S26°59'46"W	57.67'
L14	S44°48'36"W	146.60'
L15	S03°14'44"W	141.12'



Boundary Survey
for
Marshall A. Thackston
Gary L. Atkins

Current Owners by D.B.246 p.879 and Inst.No.200502438
Prospect District, Prince Edward County, Virginia

June 21, 2010
Scale: 1in.=200ft.

0' 200' 400' 600'

Maxey-Hines & Associates, P.C.
Land Surveyors • Engineers • Planners • Consultants
P.O. Box 90 • Farmville • Virginia • 23901 • Tel:434-392-8827

- Notes:
1. Tax Map Parcel No.33-A-115.
 2. This plat has been prepared without the benefit of a title examination and therefore does not necessarily indicate all encumbrances on the property.
 3. This plat agrees with found plats, deed descriptions, ground evidence and local witnesses as near as possible.
 4. This plat is based on a current field survey.

10s0067
FB1160-44