

TRACK D

STATE OF TEXAS WELL REPORT for Tracking #91870

Owner:	Peter Malin/Six Peaks LLC	Owner Well #:	No Data
Address:	5925 Forest Lane, Ste. 505 Dallas, TX 75230	Grid #:	57-27-1
Well Location:	Vista Encantada, #4 TX	Latitude:	30° 35' 01" N
Well County:	Llano	Longitude:	098° 43' 38" W
Elevation:	No Data	GPS Brand Used:	Garmin III+
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Date: Started: 8/31/2006
Completed: 8/31/2006

Diameter of Hole: Diameter: 9 in From Surface To 25 ft
Diameter: 6.75 in From 25 ft To 26 ft
Diameter: 6 in From 26 ft To 120 ft

Drilling Method: Air Hammer

Borehole Completion: Open Hole

Annular Seal Data: 1st Interval: From 0 ft to 5 ft with 1 - cement (#sacks and material)
2nd Interval: From 5 ft to 25 ft with 3 - bentonite (#sacks and material)
3rd Interval: No Data
Method Used: grout
Cemented By: Taylor Virdell Jr.
Distance to Septic Field or other Concentrated Contamination: n/a ft
Distance to Property Line: n/a ft
Method of Verification: No Data
Approved by Variance: No Data

Surface Completion: Surface Sleeve Installed

Water Level: Static level: 26 ft. below land surface on 8/31/2006
Artesian flow: No Data

Packers: No Data

Plugging Info: Casing or Cement/Bentonite left in well: No Data

Type Of Pump: Submersible
Depth to pump bowl: 100 ft

Well Tests: Jetted
Yield: 17 GPM with (No Data) ft drawdown after (No Data) hours

Water Quality: Type of Water: good (310 ppm TDS)
Depth of Strata: 30 & 40 ft.
Chemical Analysis Made: No
Did the driller knowingly penetrate any strata which contained undesirable constituents: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for