)wner:	Bill Dalton	Owner Well #:	No Data
Address:	268 CR 116 Llano, TX 78643	Grid #:	57-19-1
Well Location:	268 CR 116	Latitude:	30° 43' 46" N
Llano, TX 78643		Longitude:	098° 42' 43" W
Well County:	Llano	Elevation:	No Data
Type of Work:	New Well	Proposed Use:	Stock

	Diameter (in.) Top Dep	th (ft.)	Bottom Depth (ft.)	
Borehole:	9	0		18	
	6.375	18		200	
Drilling Method:	Air Hammer				
Borehole Completion:	n: Straight Wall				
	Top Depth (ft.)	Bottom Depth (ft.)	Des	cription (number of sacks & material)	
Annular Seal Data:	-2	18		8	
Seal Method: Ha	and	Dist	ance to Pro	operty Line (ft.): 60	
Sealed By: Dr	riller			c Field or other tamination (ft.): No Data	
		Di	stance to S	eptic Tank (ft.): No Data	
			Method	of Verification: Owner	
Surface Completion:	Surface Sleeve Ir	nstalled			
Water Level:	125 ft. below lan	d surface on 2011-06- 1	5 Meas	urement Method: Unknown	
Packers:	Rubber 18 Ft				
Type of Pump:	No Data				
Well Tests:	Jetted	Yield: 1.6 GPM w	ith 0 ft. dra	awdown after .5 hours	

_

	Strata Depth (ft.)	Water Type		
Water Quality:	180	Good		
		Chemical Analysis Made	e: No	
	Did the driller I	knowingly penetrate any strata which contained injurious constituents?		
Certification Data:	driller's direct supervision correct. The driller ur	at the driller drilled this well (or the w ision) and that each and all of the sta nderstood that failure to complete the turned for completion and resubmitta	tements he required i	erein are true and
Certification Data: Company Information:	driller's direct supervision correct. The driller ur the report(s) being ref	ision) and that each and all of the stand nderstood that failure to complete the turned for completion and resubmitta	tements he required i	erein are true and
	driller's direct supervision correct. The driller ur the report(s) being ret	ision) and that each and all of the stand nderstood that failure to complete the turned for completion and resubmitta	tements he required i	erein are true and
	driller's direct supervision correct. The driller un the report(s) being ref Walden Drilling, In 1690 CR 102	ision) and that each and all of the sta nderstood that failure to complete the turned for completion and resubmitta nc	tements he required i	erein are true and

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description	Dia. (in.) New/Used Type Setting From/To (ft.)
0	2	Topsoil	6 New PVC #40 +2-18
2	17	Red Granite Gravel	
17	200	Gray Granite	

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880