

Revised 1-71

WEST VIRGINIA
SEPTIC TANK INSPECTION FORM

Morgan Health Department Installation Permit No. 09 27-117
 Name of Owner Robert L. T. Morgan
 Address 1507 Marshall St, Baltimore Md 21230
 Property Address Left side of house Rob

DESCRIPTION & NUMBER OF UNITS SERVED

Type Facility Served Dwelling No. Water Closets 1
 Lot Size 10.3 sq. ft. Area suitable for sewage disposal installation — sq. ft.
 Source of Water Supply X No. Lavatories —
 No. Bedrooms 2 No. Showers or Tubs — No. Baths —
 No. Garbage Grinders — No. Automatic Washers —

SEPTIC TANK

Material Concrete Length — x Width — x Depth — = 1000 ^{gal.} cubic feet
 Liquid Depth — ft. Liquid Capacity 1000 gal.
 Distance to: Dwelling X Water Supply X Nearest Property Line 30'

SOIL ABSORPTION SYSTEM

Type Drain Line Material Plastic Trench Width 36 Inches
 Trench Depth 20 Inches Total Absorption area in Trench Bottom 600 sq. ft.
 Diameter of Drain Line 4 Inches Type Filter Media Gravel
 No. of Drain Lines 2 Depth Filter Media Under Drain Line 6 Inches
 Length of Each Line 100 ft. Depth Filter Media Over Drain Line 2 in.
 Distance of Disposal Field to: (a) Dwelling X
 (b) Water Supply X (c) Nearest Property Line 50'

An inspection of the septic tank system described herein disclosed that said system (MEETS, ~~DOES NOT MEET~~) the minimum standards established by the West Virginia State Department of Health.

Date 1/15/88J. Robertson
Sanitarian

SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.

111KE - BEAUMONT ^{res}
Septic
System

* Have not present at time of inspection
11/15/85

[Handwritten signature]

