Subject: Fwd: Emailing: Well Report Tracking #172086.htm

From: Kathy Beckham (kbeckham@remax-llano-tx.com)

To: glaird71@yahoo.com;

Date: Friday, August 9, 2013 4:51 PM

Sent from my iPhone

Begin forwarded message:

County:

From: "Virdell Drilling" <virdelldrilling@verizon.net>

Date: August 9, 2013, 4:18:20 PM CDT

To: "Kathy Beckham" <kbeckham@remax-llano-tx.com> Subject: Emailing: Well Report Tracking #172086.htm

5	STATE	OF	TEXAS	WELL	REPORT	for	Tracking #172086	
								-

Rev. Rick Cundieff Owner Well #: Owner: No Data

106 E. Granite Grid #: Address: 57-11-7

Llano, TX 78643

Rio Llano, Lot #237 Latitude: 30° 45′ 10″ N

Well Location: TX

Well Llano Longitude: 098° 44' 36" W

Elevation: No Data GPS Brand Used: Garmin III

Type of **New Well** Proposed Use: **Domestic** Work:

Drilling Date: Started: 3/23/2009 Completed: 3/23/2009

Diameter of Hole: Diameter: 9 in From Surface To 53 ft

Diameter: 6.75 in From 53 ft To 54 ft Diameter: 6 in From 54 ft To 160 ft

Drilling Method: Air Hammer

Borehole Gravel Packed From: 30 ft to 63 ft

Completion: Gravel Pack Size: 3/8

Annular Seal 1st Interval: From 0 ft to 5 ft with 1 Cement (#sacks and material) 2nd Interval: From 5 ft to 30 ft with 5 Bentonite (#sacks and material) Data:

3rd Interval: No Data

Method Used: Grout Cemented By: Lvnn Hov

Distance to Septic Field or other Concentrated Contamination: No Data

Distance to Property Line: No Data Method of Verification: No Data Approved by Variance: No Data

Surface

Pitless Adapter Used

Completion:

Water Level:

Static level: 40 ft. below land surface on 3/23/2009

Artesian flow: No Data

Packers:

No Data

Plugging Info:

Casing or Cement/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 150 ft

Well Tests:

Yield: 10 GPM with (No Data) ft drawdown after (No Data) hours

Water Quality:

Type of Water: good (450 ppmTDS)

Depth of Strata: 57-63, 75 ft. Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained undesirable

constituents: No

Certification

Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for completion and

resubmittal.

Company

Information:

Virdell Drilling Inc. 111 E. Grayson St.

Llano, TX 78643

Driller License

Number:

1900

Licensed Well

James Taylor Virdell

Driller Signature:

Registered Driller James Caleb Virdell

Apprentice

Signature:

57668

Apprentice Registration

Number:

Comments:

No Data

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #172086) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157 Austin, TX 78711 (512) 463-7880

DESC. & COLOR OF FORMATION MATERIAL	CASING, BLANK PIPE & WELL SCREEN DATA			
From (ft) To (ft) Description 0 - 2 Topsoil 2 - 34 Metamorphic Gravel & Clay	Dia. New/Used Type Setting From/To 6'' N PVC +2 - 54 sch 40			
34 - 57 Gray & Black Metamorphic 57 - 63 Gravel Sill 63 - 160 Gray Granite	6" N PVC, Custom Slott 54 - 64 sch 40			