

WEST VIRGINIA
SEPTIC TANK INSPECTION FORM

Hampshire County Health Department Installation Permit No. 57-14-80-4

Name of Owner EVANS, W. D.
Address Box 159C - SPRING GAP Rd., SLANESVILLE, W. VA
Property Address 7 MILES NORTH ON SPRING GAP MT. Rd., DANLEY

DESCRIPTION & NUMBER OF UNITS SERVED

Type Facility Served NEW HOUSE No. Water Closets 1
Lot Size 32-ACRES sq. ft. Area suitable for sewage disposal installation 20,000 sq. ft.
Source of Water Supply TO BE DRILLED WELL No. Lavatories 1
No. Bedrooms 3 No. Showers or Tubs 1 No. Baths 1
No. Garbage Grinders 0 No. Automatic Washers 1

SEPTIC TANK

Material CONCRETE Length x Width x Depth = cubic feet.
Liquid Depth ft. Liquid Capacity 1,000 gal.
Distance to: Dwelling 26' TO BE Water Supply 100' Nearest Property Line 150'

SOIL ABSORPTION SYSTEM

Type Drain Line Material PLASTIC Trench Width 36" 24 Inches
Trench Depth 30 Inches Total Absorption area in Trench Bottom 630 sq. ft.
Diameter of Drain Line 4 Inches Type Filter Media GRAVEL
No. of Drain Lines 3 Depth Filter Media Under Drain Line 6 Inches
Length of Each Line 70', 70', 70' ft. Depth Filter Media Over Drain Line 2 in
Distance of Disposal Field to: (a) Dwelling 45'
(b) Water Supply TO BE 120' (c) Nearest Property Line 30'

An inspection of the septic tank system described herein disclosed that said system (MEETS,) the minimum standards established by the West Virginia State Department of Health.

Date AUG. 18, 1980

Sanitarian

SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.

