



CERTIFICATE OF SURVEY
I, THE UNDERSIGNED HEREBY CERTIFY THAT THIS SURVEY WAS PERFORMED WHOLLY UNDER MY DIRECTION AND TO THE BEST OF MY KNOWLEDGE AND BELIEF WAS EXECUTED ACCORDING TO THE REQUIREMENTS OF #864 IAC 11-12



*Property in the name of Chester B. Stem Tract #2.
Property in the name of Charlie Smith Tract #1.*

PAUL PRIMAVERA & ASSOCIATES, INC.
REGISTERED ENGINEERS & LAND SURVEYORS
301 EAST CHESTNUT ST., CORYDON
P.O. BOX 188
CORYDON, INDIANA 47112
PHONE 728-1124

SURVEYOR'S REPORT
(THIS REPORT IS MADE IN COMPLIANCE WITH TITLE 864 ADOPTED BY INDIANA GENERAL ASSEMBLY OF 1986)
REFERENCED PROJECT #92-4666 CHARLIE SMITH & CHESTER B. STEM
A. AVAILABILITY & CONDITION OF MONUMENTS
A pin found marking the section corner between Sections 3 and 4 was found in good condition. A stone was found on the East line of the West half of the Southwest quarter of Section 4. Fence posts and remnants of a fence were also found at the Southwest corner of the Southwest quarter of the Southwest quarter of Section 4. These points were used as a basis for this survey.
B. LINES OF POSSESSION
A fence line along the Eastern side of the West half of the Northwest quarter of Section 4 did not coincide with the property line, however the property owners informed me that the fence had been built West of the old fence in order to eliminate the cost of clearing the fence line.
C. CLARITY OR AMBIGUITY OF DEEDS
The deeds were clear in their intent.
D. THEORETICAL UNCERTAINTY
The theoretical uncertainty of this survey was 0.48 feet.

FIELD WORK COMPLETED 4-24-92			
PLAT OF SURVEY FOR CHESTER B. STEM & CHARLIE SMITH			
PT. OF E1/2 SEC 4 & W1/2 SEC 3 BOTH IN T4S R5E			
PRIMAVERA & ASSOC. INC.			
Date: 4-30-92	Engineers &	NO. 92-4666	
Drawn By: PFP	Land Surveyors	Dwg. No.	A
Checked: [Signature]	Corydon, Indiana	1	OF 1