

TEXAS ASSOCIATION OF REALTORS®

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2011

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

	-	-	300				minum discission i	2012							
CONCERNING THE PRO	200	·D.T.	/ AT								R 17				
CONCERNING THE PRO												75497			
DATE SIGNED BY SELI	LEF	AN S	I DI	SNO	T A	A S	UBSTITUTE FOR A	NY	IN	SPE	CTIO	ON OF THE PROPERTY A INS OR WARRANTIES TH ELLER'S AGENTS, OR AN	IE E	BUY	ER
Seller is is not or	ccu	pyin	g the	e Pro	per	y. I	f unoccupied (by Sel	ller)	, ho	w lo	ng sir	nce Seller has occupied the	Pro	oper	rty?
							ver occupied the Pro							. Min. John	
Section 1. The Propert	tv h	as f	he i	tems	ma	rke	d helow: (Mark Yes	: /Y	1 1	o (N	or	Inknown (II))			
												which items will & will not conv	ey.		
Item	YNU			П	Item			Υ	N	U	П	tem	Y	N	U
Cable TV Wiring		X		1	Liquid Propane Gas:			X		I	oump: ☐ sump ☐ grinder		X		
Carbon Monoxide Det.		X		1	-LP Community (Captive)				X		I	Rain Gutters	X		
Ceiling Fans	X		\neg		-LP on Property				X		I	Range/Stove	X	Г	
Cooktop		K		T	Hot Tub			X		_	Roof/Attic Vents	V			
Dishwasher	X	1			Intercom System			X		5	Sauna	1	X		
Disposal		X		1	viic	owa	ave		X	П	3	Smoke Detector		X	
Emergency Escape Ladder(s)		X			Dute	oot	r Grill		X		100	Smoke Detector – Hearing mpaired	3	X	
Exhaust Fans			F	Patio/Decking			X	ľ		1	Spa		1		
Fences	X	<i>(</i> `		Plumbing System		X		П	-	rash Compactor	13	X			
Fire Detection Equip.		X	П	F	000	6		-	X		-	TV Antenna		文	
French Drain				F	Pool Equipment				X		V	Washer/Dryer Hookup	X	*	
Gas Fixtures	X		F	Pool Maint. Accessories			K	П	-	Vindow Screens	X				
Natural Gas Lines		X		F	900	Не	ater		Z		F	Public Sewer System		K	
Item				Y	N	U			A	dditi	onal	Information			
Central A/C				X			☐ electric ☐ gas	n	um	ber o	f unit	S:			
Evaporative Coolers			-	X		number of units:									
Wall/Window AC Units				17		number of units:									
Attic Fan(s)				X		if yes, describe:									
Central Heat			X			★ electric gas number of units: /									
Other Heat				X		if yes, describe:					<u> </u>			=27	
Oven					X		number of ovens:		_	Пе	lectric	gas other:			
Fireplace & Chimney					X		☐ wood ☐ gas lo	gs		moc	< D	other:			-0.0
Carport			$-\mathbf{x}$	L		Sattached no	t at	tac	ned						
Garage					X		☐ attached ☐ no	t at	tac	ned					
Garage Door Openers				1	X		number of units:				_ nu	ımber of remotes:			
Satellite Dish & Controls				\times			owned Nease	ed fr	on						
Security System					X		owned lease		-		_				_
Water Heater			X			☑ electric ☐ gas	_==			1/1	umber of units:			_73	
Water Softener					X		owned leased from								
Underground Lawn Sprin					7		automatic m								-
Septic / On-Site Sewer F	acil	ity		X			if yes, attach Inforn	nati	on.	Abou	t On-	Site Sewer Facility (TAR-14	07)		

(TAR-1406) 9-01-11

Initialed by: Seller:

and Buyer:

	at				Yantis	g, Tx.	75497		37
Water supply provided by	r Deily D	well [] MIID	r	100-0	n Clunt	known 1	other Jake Fork Water	1	Su
Was the Property built be	ofore 19782 Y	Mar Divide	-	Junk Junk	p Dun	KIIOWII /	Pomer (Mars 10 cm occur)		
(If yes, complete, sig						ed paint	hazards)		
Roof Type:							(аррі	mixor	nate
Is there an overlay roof o	overing on th	e Property (sh	nina	les or	roof cove	erino pla	ced over existing shingles or roof co	overi	ina)
□yes □no ⊠unkno						Tima Fire			97
/ \	e an an		e e e e				Control of the Contro	2000000	
							working condition, that have defec	ts, o	r ar
need of repair? Uyes	no If yes	s, describe (att	ach	addit	ional she	ets if nec	essary):		1
			_						
	20 10			89	N 2550			35	
			s or	malf	unctions	in any	of the following?: (Mark Yes (Y) if	you	ıar
aware and No (N) if you	are not awar	re.)							
Item	YN	Item				YN	Item	Y	N
Basement	X	Floors				X	Sidewalks		1
Ceilings	X	Foundation	n / S	Slab(s)	X	Walls / Fences		1
Doors	\times	Interior Wa	alls			X	Windows		X
Driveways		Lighting Fi	xtur	es		X	Other Structural Components		X
Electrical Systems	X	Plumbing \$	Syst	tems		X			
Exterior Walls	X	Roof	-0			X			Т
If the answer to any of the	. 1.0.110 111 000		7.1				needs if freedestary).		
	ller) aware o	of any of the	follo	owing	j conditie	ons: (Ma	ark Yes (Y) if you are aware and N	1) oV	N) i
	ller) aware o	of any of the		owing	condition Condi		ark Yes (Y) if you are aware and I	- 33	
you are not aware.) Condition	iller) aware o	of any of the			Condi	ition		- 33	N
you are not aware.)	ller) aware o	of any of the			Condi	ition	dation Repairs	- 33	N
you are not aware.) Condition Aluminum Wiring	The second secon	of any of the			Condi Previo	ition ous Foun	dation Repairs Repairs	- 33	N
Condition Aluminum Wiring Asbestos Components Diseased Trees:	cwilt 🗆				Condi Previo	ition ous Foun ous Roof Structura	dation Repairs	- 33	N X X
Condition Aluminum Wiring Asbestos Components	cwilt 🗆				Condi Previo Previo Other	ition ous Foun ous Roof Structura o Gas	dation Repairs Repairs	- 33	N X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: act	k wilt bitat on Prope				Condi Previo Orner Radon Settlin	ition ous Foun ous Roof Structura o Gas	dation Repairs Repairs al Repairs	- 33	XXXXX
Condition Aluminum Wiring Asbestos Components Diseased Trees: all oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was	k wilt bitat on Prope				Condi Previo Other Radon Settlin Soil M	ition bus Foun bus Roof Structura i Gas g overnent	dation Repairs Repairs al Repairs	- 33	XXXXX
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was	k wilt bitat on Prope ste				Condi Previo Other Radon Settlin Soil M	ition ous Foun ous Roof Structura ous Gas g overnent	dation Repairs Repairs al Repairs ucture or Pits	- 33	XXXXXX
Condition Aluminum Wiring Asbestos Components Diseased Trees: all oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was	k wilt bitat on Prope ste				Condi Previo Other Radon Settlin Soil M Subsu Under	ition ous Foun ous Roof Structura ous Gas g overnent orface Str	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks	- 33	N X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S	k wilt bitat on Prope ste Springs	erty			Condi Previo Other Radon Settlin Soil M Subsu Under	ition ous Foun ous Roof Structura ous Gas g overnent orface Structura ground Structura	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks	- 33	NXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea	wilt bitat on Prope ste Springs	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat	ition ous Foun ous Roof Structura ous Gas g overnent orface Str ground S oted Ease orded Ease	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks ements sements	- 33	N X X X X X X X X X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea	k wilt bitat on Prope ste Springs ad-Based Pt. I Property	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco	ition ous Foun ous Roof Structura of Gas g ovement orface Str ground S orded Ease orded Ease	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks ements sements sements	- 33	NXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi	k wilt	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-fi Water	ition ous Foun ous Roof Structura of Gas g ovement orface Str ground S orded Ease orded Ease orded Ease ormaldel	dation Repairs Repairs al Repairs ucture or Pits storage Tanks ements essements syde Insulation	- 33	N X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floor	k wilt	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-fi Water	ition ous Foun ous Roof Structura of Gas g overnent orface Str ground S orded Ease orded Ease ormaldel Penetral	dation Repairs Repairs al Repairs ucture or Pits storage Tanks ements essements syde Insulation	- 33	N X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway	k wilt bitat on Prope ste Springs ad-Based Pt. I Property ing on others'	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-fi Water Wetlar	ition ous Foun ous Roof Structura of Gas g overnent orface Str ground Stated Ease orded Ease ormaldel Penetral onds on P Rot	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks ements sements sements nyde Insulation tion	- 33	N X X X X X X X X X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather S Landfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floor	ste Springs ad-Based Pt. It Property ing on others'	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-fi Water Wetlar Wood Active	ition ous Foun ous Roof Structura of Gas g ovement orface Structura ground Structura ground Structura orded Ease orded Ea	dation Repairs Repairs al Repairs ucture or Pits storage Tanks ements essements syde Insulation	- 33	N X X X X X X X X X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414)	k wilt	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-f Water Wetlar Wood Active destroy	ition ous Foun ous Roof Structura of Gas g overnent orface Str ground Stred Ease orded Ease orded Ease ormaldel Penetral ormalds on P Rot infestatio	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks ements ements esements nyde Insulation tion roperty on of termites or other wood	- 33	N X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover	c wilt	erty			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-fi Water Wetlar Wood Active destroy	ition ous Foun ous Roof Structura of Gas g ovement orface Str ground S orded Ease orded Ease orded Ease ormaldel Penetral ods on P Rot infestatio ying inse	dation Repairs Repairs al Repairs ucture or Pits storage Tanks ements ements hyde Insulation tion roperty on of termites or other wood cts (WDI)	- 33	N X X X X X X X X X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414) Previous Flooding into the	c wilt	erty			Condi Previo Other Radon Settlin Soil M Subsu Unders Unplat Unreco Urea-fi Water Wetlar Wood Active destroy Previor	ition ous Foun ous Roof Structura of Gas g ovement orface Str ground Stred Ease orded Ease orded Ease ormaldel Penetral ods on P Rot infestatio ying inse us treatn us termit	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks ements sements sements nyde Insulation tion roperty on of termites or other wood cts (WDI) ment for termites or WDI	- 33	N X X X X X X X X X X X
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414) Previous Flooding into the Previous Flooding onto the	k wilt	erty Hazards property			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-f Water Water Wood Active destroy Previor Termit	ition ous Foun ous Roof Structura of Gas g overnent orface Str ground Sted Ease orded Ease orded Ease ormaldel Penetral ormaldel Penetral ormaldel inds on P Rot infestatio ying inse ous treatn us termit e or WDi	dation Repairs Repairs al Repairs ucture or Pits Storage Tanks ements esements hyde Insulation tion roperty on of termites or other wood cts (WDI) hent for termites or WDI e or WDI damage repaired	- 33	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak Endangered Species/Ha Fault Lines Hazardous or Toxic Was Improper Drainage Intermittent or Weather Standfill Lead-Based Paint or Lea Encroachments onto the Improvements encroachi Located in 100-year Floot Located in Floodway Present Flood Ins. Cover (If yes, attach TAR-1414) Previous Flooding into the Previous Fires	k wilt	erty Hazards property			Condi Previo Other Radon Settlin Soil M Subsu Under Unplat Unreco Urea-f Water Water Wood Active destroy Previor Termit	ition ous Foun ous Roof Structura of Gas g overnent orface Str ground Sted Ease orded Ease orded Ease ormaldel Penetral ormaldel Penetral ormaldel inds on P Rot infestatio ying inse ous treatn us termit e or WDi	dation Repairs Repairs al Repairs ucture or Pits storage Tanks ements exements hyde Insulation tion roperty on of termites or other wood cts (WDI) hent for termites or WDI e or WDI damage repaired I damage needing repair	- 33	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

634 CR 1750

Con	cerning	tine Property at Tantis, Tx. 75497
If the	e answ	er to any of the items in Section 3 is yes, explain (attach additional sheets if necessary):
whic	h has	*A single blockable main drain may cause a suction entrapment hazard for an individual. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair not been previously disclosed in this notice? yes no If yes, explain (attach additional sheets in the property that is in need of repair not been previously disclosed in this notice?
	aware.	Are you (Seller) aware of any of the following (Mark Yes (Y) if you are aware. Mark No (N) if you are Room additions, structural modifications, or other alterations or repairs made without necessary permits or no
	1	In compliance with building codes in effect at the time. Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: Manager's name: Fees or assessments are: \$ per and are: mandatory voluntary Any unpaid fees or assessment for the Property? yes (\$) no
	í	Fees or assessments are: \$ per and are: \ mandatory \ voluntary Any unpaid fees or assessment for the Property? \ yes (\$) \ no If the Property is in more than one association, provide information about the other associations below or attach information to this notice.
		Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following: Any optional user fees for common facilities charged? yes Ino If yes, describe:
		Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
		Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited o: divorce, foreclosure, heirship, bankruptcy, and taxes.)
ו ם		Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to he condition of the Property.
	*	Any condition on the Property which materially affects the health or safety of an individual.
ק ם	_	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental nazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
		Any rainwater harvesting system connected to the property's public water supply that is able to be used for indoor potable purposes.
If the	answe	r to any of the items in Section 5 is yes, explain (attach additional sheets if necessary):
(TAR-	-1406)	9-01-11 Initialed by: Seller: and Buyer:, Page 3 of 5

Concerning the Pro	perty at		634 CR 1750 Yantis, Tx. 75497	
Section 7. Within regularly provide	n the last 4 year	s not attached a survey of ars, have you (Seller) red d who are either licensed yes, attach copies and comp	ceived any written inspection I as inspectors or otherwise	n reports from persons who permitted by law to perform
Inspection Date	Туре	Name of Inspector		No. of Pages
Pr Section 8. Check ☐ Homestead ☐ Wildlife Mana	operty. A buye any tax exemp agement	er should obtain inspection otion(s) which you (Seller) Senior Citizen	ports as a reflection of the constrom inspectors chosen be currently claim for the Prope Disabled Disabled Veteran	y the buyer. erty:
requirements of Cl	napter 766 of th	e Health and Safety Code	ectors installed in accordance?* unknown no ye	e with the smoke detector es. If no or unknown, explain.
(Attach additional sh	eets if necessa	ry):		
smoke detec which the dw know the bu	tors installed in relling is located	accordance with the requi l, including performance, lo irements in effect in your a	one-family or two-family dwell irements of the building code in cation, and power source requi- irea, you may check unknown a	n effect in the area in rements. If you do not
of the buyer's evidence of t the buyer m specifies the	s family who will he hearing impa akes a written locations for in:	I reside in the dwelling is he airment from a licensed phy request for the seller to in	for the hearing impaired if: (1) the earing-impaired; (2) the buyer g sician; and (3) within 10 days a estall smoke detectors for the agree who will bear the cost o	gives the seller written fter the effective date, hearing-impaired and
			to the best of Seller's belief and ate information or to omit any ma	
Manual Signature of Seller	Daine	3/16/2013	Simplure of Salles	Date:
orinted Name:		1 1000000 30	Signature of Seller Printed Name:	Date
TAR-1406) 9-01-11	Init	ialed by: Seller:,	and Buyer.	, Page 4 of 5

Initialed by: Seller: _____, and Buyer:

Page 4 of 5

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit <u>www.txdps.state.tx.us</u>. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.
- (4) The following providers currently provide service to the property:

Electric: WCEC	phone #:
Sewer:	
Water: &F	phone #:
Cable:	phone #:
Trash:	phone #:
Natural Gas:	phone #:
Phone Company:	
Propane:	phone #:

(5) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Cignoture of Duner	Data	Dispating of Dogge	5.1.
Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	

(TAR-1406) 9-01-11 Page 5 of 5