

# WELL INFORMATION LOG

**WELL OWNER:** William H. Gosdin III  
**ADDRESS:** 8620 N. New Braunfels, Suite 300  
San Antonio, Texas 78217  
**DATE:** April 10, 2007

**WELL LOCATION:**

**STATE TRACKING #:** n/a  
**COUNTY:** Llano  
**ADDRESS:** End of county road 201 - well in pasture  
**LATITUDE:** 30° 46' 08" N  
**LONGITUDE:** 98° 37' 36" W

**CURRENT WELL USE:** Domestic - Private

**WELL DETAILS:**

**CASING DIAMETER:** 5" schedule 40 PVC  
**CASING DEPTH:** +2' to -18' to solid formation using packer and bentonite  
**WELL DEPTH:** 167'  
**STATIC LEVEL:** 15' (4/8/07)  
**PUMP BOWL:** 140'  
**PRODUCTION (GPM):** 7.5 GPM  
**WATER QUALITY:** Good

**WORK PERFORMED:**

The well was cased down to solid rock formation with 5" schedule 40 PVC casing utilizing a packer and bentonite. A 5" PVC Well Cap was placed for future utilization of the well.

**WORKED PERFORMED BY:**

Ellis Water Well Service - Christopher D. Ellis Lic# 54599PK  
(325) 248-0588 Office - (512) 419-8418 Cell

**NOTE:**

This log is for informational use only. It is not a state-provided form. It is intended for record keeping and reference purposes only. Please place this form with all warranty and other paperwork provided by installer.