

STATE OF TEXAS WELL REPORT for Tracking #130375

Owner:	Farm and Ranch Construction	Owner Well #:	No Data
Address:	P.O. Box 112 Cranfill Gap , TX 76637	Grid #:	57-27-7
Well Location:	300' S of FM 965 on Hohmann Ranch Rd; 500' E on hill TX	Latitude:	30° 30' 29" N
Well County:	Llano	Longitude:	098° 44' 37" W
Elevation:	No Data	GPS Brand Used:	Garmin III
Type of Work:	Reconditioning	Proposed Use:	Domestic

Drilling Date: Started: **12/26/2007**
Completed: **12/26/2007**

Diameter of Hole: Diameter: **9 in From Surface To 120 ft**

Drilling Method: **Air Rotary**

Borehole Completion: **Open Hole**

Annular Seal Data: 1st Interval: **From 1 ft to 3 ft with 1 Cement (#sacks and material)**
2nd Interval: **From 3 ft to 25 ft with 5 Bentonite (#sacks and material)**
3rd Interval: **No Data**
Method Used: **Grout**
Cemented By: **Taylor Virdeil Jr.**
Distance to Septic Field or other Concentrated Contamination: **No Data**
Distance to Property Line: **No Data**
Method of Verification: **No Data**
Approved by Variance: **No Data**

Surface Completion: **Pitless Adapter Used**

Water Level: Static level: **42 ft. below land surface on (No Data)**
Artesian flow: **No Data**

Packers: **1 Rubber 25**

Plugging Info: Casing or Cement/Bentonite left in well: **No Data**

Type Of Pump: **Submersible**
Depth to pump bowl: **100 ft**

Well Tests: **Jetted**
Yield: **27 GPM with (No Data) ft drawdown after (No Data) hours**

Water Quality: Type of Water: **Good (650 ppmTDS)**
Depth of Strata: **unk ft.**
Chemical Analysis Made: **No**
Did the driller knowingly penetrate any strata which contained undesirable constituents: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the

required items will result in the log(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.
111 E. Grayson St.
Llano, TX 78643**

Driller License Number: **1900**

Licensed Well Driller Signature: **Taylor Virdell Jr.**

Registered Driller Apprentice Signature: **James Caleb Virdell**

Apprentice Registration Number: **57668**

Comments: **No Data**

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #130375) on your written request.

**Texas Department of Licensing & Regulation
P.O. Box 12157
Austin, TX 78711
(512) 463-7880**

DESC. & COLOR OF FORMATION MATERIAL

CASING, BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description
0 - 120 prev drilled

Dia.	New/Used	Type	Setting From/To
6 N	PVC	27 +2	- 25



VIRDELL DRILLING INC.

111 E. GRAYSON ST.
LLANO, TEXAS 78643
(325) 247-4249
www.virdelldrilling.com
vdi@tstar.net

SOLD TO:

FARM AND RANCH CONST.
P.O. BOX 112
CRANFILL GAP, TX 76637

DATE: 01/04/08
INVOICE NO: 000332800000
TERMS: NET 30

*pd. 1/10
ck# 16060*

CUSTOMER NO. 06647

INVOICE

QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
	LLANO CO; WELL ON HOHMANN RANCH AT OLD HUNTING CABIN (FIRST GATE FROM HWY) TRACKING #130375; N303029, W984437		
1	GOULDS PUMP, 1-1/2 HP, #13GS15412		
100	3-WIRE, 230 VOLT SUBMERSIBLE		
108	FT. PVC PIPE, 1-1/4", SCH 80, T&C		
1	FT. SUB CABLE W/GROUND, #10-3		
1	BARON PRESSURE TANK, #BN17002		
1	PITLESS ADAPTER COMPLETE, 5" & 6"		
1	REGULAR PRESSURE SWITCH		
1	WATT KNOT LIGHTNING ARRESTOR, 230V		
8	FT. PVC PIPE, 1-1/4", 200 PSI		
20	FT. PVC GRAY CONDUIT, 3/4", SCH 40		
24	FT. UF CABLE W/GROUND, #10-2		
23	FT. DITCH		
1	FITTINGS PACKAGE		
1	INSTALLATION		
	DATE INSTALLED: 01/03/08 PUMP #F0720145 MOTOR #A2607X231112 TANK #30113257		

ALL ACCOUNTS
30 DAYS OLD ARE
CONSIDERED
PAST DUE. A
FINANCE CHARGE
OF 1-1/2%
PER MONTH
(18% ANNUAL)
WILL BE ADDED
TO ALL PAST DUE
ACCOUNTS.

**** THANK YOU ****

WE NOW OFFER THE OPTION TO PAY WITH YOUR CREDIT CARD. PLEASE CALL 325/247-4249 OR 830/997-4966 TO PROCESS YOUR PAYMENT TODAY.



SUB-TOTAL
SALES TAX

TOTAL

Pd 12/31/07 check #10027



VIRDELL DRILLING INC.

111 E. GRAYSON ST.
LLANO, TEXAS 78643
(325) 247-4249

www.virdelldrilling.com
vdi@tstar.net

SOLD TO:

FARM AND RANCH CONST.
P.O. BOX 112
CRANFILL GAP, TX 76637

DATE: 12/26/07
INVOICE NO: 000332610000
TERMS: NET 30

INVOICE

CUSTOMER NO. 06647

QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
1	LLANO CO; WELL ON HOHMANN RANCH AT OLD HUNTING CABIN (FIRST GATE FROM HWY) N363026, W984437 ===== *****WELL TEST***** WELL DEPTH.....121' STATIC LEVEL.....33' CASING- 9" I.D. TIN 5" ABOVE GROUND WITH A CEMENT SLAB. THE CASING EXTENDS ABOUT 13" DOWN PUMP SETTING.....110' GPM.....27 LABOR CHARGE TO TEST WELL		