

AREA-GR W Hwy 67	EX. DATE- 09/12/12	I/DATE&TIME	S/I NO SH	Sept. Jan. May
---------------------	-----------------------	-------------	-----------	----------------



2030 Southwest Pkwy  
Granbury, Texas 76048  
Business: (817) 573-4296

## AEROBIC SEPTIC SERVICE REPORT

Peter Wyckoff  
1183 CR 2023  
Glen Rose, Texas 76043  
(254) 897-9776

A service technician has inspected your Aerobic System today in compliance with state law. A copy of this report will be forwarded to your local permitting agency as required.

PERMIT FROM : Somervell#2-220  
MFG / SERIAL # : Hoot  
ADD CHLORINE : Yes ☐ No ☒

### RESULTS

	OPERATIVE	INOPERATIVE
HIGH WATER AUDIBLE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
HIGH WATER VISUAL	<input checked="" type="checkbox"/>	<input type="checkbox"/>
AIR COMPRESSOR	<input checked="" type="checkbox"/> 3psi	<input type="checkbox"/>
ELECTRICAL	<input checked="" type="checkbox"/>	<input type="checkbox"/>
WATER PUMP	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SPRAY HEADS	<input checked="" type="checkbox"/>	<input type="checkbox"/>

ODOR, COLOR: NONE/CLEAR ☒ SLIGHT/SOAPY ☐ STRONG/GREY ☐  
 CHLORINE: 63 PPM CHLORINE ADDED ☐ NEEDS CHLORINE ☒  
 SLUDGE LEVEL: TRASH TANK ☐ AEROBIC TANK ☐ PUMP TANK ☒  
 LIDS SECURELY FASTENED? YES ☒ NO ☐  
 LIDS IN OPERABLE CONDITION? YES ☒ NO ☐

REPAIRS REQUIRED: \_\_\_\_\_

(IN AN EFFORT TO AVOID NEGATIVE ACTION FROM YOUR PERMITTING AUTHORITY, PLEASE RESPOND IMMEDIATELY)

SUGGESTED REPAIRS BUT NOT REQUIRED/COMMENTS: \_\_\_\_\_

This report indicates the condition of the above Onsite Wastewater Treatment System at the time of the operations and maintenance service visit. It does not guarantee that it will continue to function satisfactorily.

Inspected by: [Signature] License# WWD022829, OS0025135, MCOOOOO11  
 Date: 5-22-12



Invoice #	Total	Amount Owed	Days Past Due