




Hays County Environmental Health
1251 CIVIC CENTER LOOP
SAN MARCOS, TEXAS 78666
512/393-2150

SEPTIC TANK PUMPING REPORT

CLIENT NAME Billy Ray Hudson DATE 12/11/01

SITE ADDRESS 407 DAWN VIEW CR.

SUBDIVISION Dripping Springs, TX PHASE #

SECTION # LOT # BLOCK #

LEGAL DESCRIPTION (IF OTHER THAN SUBDIVISION)
(Acreage)

(Survey)

(Vol / Page / Date)

TANK VOLUME 1,000 gal

TANK SHAPE RECTANGLE

SLUDGE DEPTH 6"

METHOD USED TAPE

BOTTOM OF OUTLET TO TOP OF SLUDGE 31"

(Measured in inches)

CONDITION OF TANK EXCELLENT
(Cracks, Tees intact, Lid sealed, etc.)

MISCELLANEOUS COMMENTS TANK WAS MISSING THE

INLET "T" BUT TANK WAS IN GREAT
SHAPE

PUMPER COMPANY NAME B M Septic

SIGNATURE OF PUMPER John Kelly