


DRAINAGE TILE MAP – PARCEL 2



LOIS LEONER FARM

NAME October 1976 5940ft @ 68.8654/ft ⁸ 409059

Section..... Township..... County Franklin

Contractor D+D Drainage Date installed.....

Amount of tile installed 5" 5495' 6"..... 8" 225'.....

10"..... 12"..... Larger.....

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

THE SHEFFIELD BRICK AND TILE COMPANY, SHEFFIELD, IOW