

## STATE OF TEXAS WELL REPORT for Tracking #181874

Owner:	<b>Billy Bartlett</b>	Owner Well #:	<b>No Data</b>
Address:	<b>102 Tanglewood Gatesville, TX 76528</b>	Grid #:	<b>40-34-1</b>
Well Location:	<b>CR 176 Gatesville, TX 76528</b>	Latitude:	<b>31° 28' 29" N</b>
Well County:	<b>Coryell</b>	Longitude:	<b>097° 51' 20" W</b>
		Elevation:	<b>No Data</b>
Type of Work:	<b>New Well</b>	Proposed Use:	<b>Domestic</b>

Drilling Start Date: **6/30/2005**      Drilling End Date: **7/4/2005**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	<b>9</b>	<b>0</b>	<b>70</b>
	<b>6</b>	<b>70</b>	<b>632</b>

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks &amp; material)</i>
Annular Seal Data:	<b>0</b>	<b>15</b>	<b>3 Cement</b>
	<b>50</b>	<b>70</b>	<b>3 Cement</b>

Seal Method: **Gravity Feed**

Sealed By: **Unknown**

Distance to Property Line (ft.): **50+**

Distance to Septic Field or other  
concentrated contamination (ft.): **none on site**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **Visual**

Surface Completion: **Surface Sleeve Installed**

Water Level:	<b>373 ft. below land surface on 2005-07-07</b>	Measurement Method:	<b>Unknown</b>
Packers:	<b>Rubber 20' Rubber 400'</b>		
Type of Pump:	<b>No Data</b>		
Well Tests:	<b>Jetted</b>	<b>Yield: 20 GPM</b>	

Water Quality:

Strata Depth (ft.)	Water Type
No Data	Good

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which  
contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Harrison & Sons Well Service, Inc.**

**P.O. Box 986  
Lampasas, TX 76550**

Driller Name: **Juan Munoz**

License Number: **54176**

Comments: **\$mew**

Lithology:  
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:  
BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	14	Overburden
14	62	Fine Tan Sand
62	432	Gray Shale
432	452	Brown Sandstone (Water)
452	464	Red Sandstone
464	540	Red Clay
540	618	Sandstone / Clay
618	632	Hard Limestone

Dia. (in.)	New/Used	Type	Setting From/To (ft.)
6	New	SCH 40 PVC	0 - 70
4 1/2	New	SDR 17	0 - 632
		Perforated	420 - 632

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation  
P.O. Box 12157  
Austin, TX 78711  
(512) 334-5540**