

Angus Farm—Spring 2009 Aerial Photos Showing Drainage Tile



April, 2009 installed tile WSW of bin site in W portion of S1/2 SE1/4.

Lighter areas indicating tile.



Angus Farm—Spring 2009 Aerial Photos Showing Drainage Tile



Lighter areas indicating tile in N portion of the farm.




Lighter areas indicating tile installed prior to 2009.

Angus Farm—Spring 2009 Aerial Photos Showing Drainage Tile



Lighter areas indicating tile in S 40 acres of E1/2 NE1/4 & adjoining areas of the farm.



Lighter areas indicating tile in portions of the SW1/4NE1/4 & NW1/4SE1/4.

Angus Farm—Spring 2009 Aerial Photos Showing Drainage Tile



Lighter areas indicating tile in S portion of SW1/4NE1/4 and the N portion of the NW1/4SE1/4.

Angus Farm—Jan. 2007 Photo Showing Drainage Tile

Tile installed in area N & NW of Windbreak.



01/11/20