

REPORT SHEET

FOR

PERCOLATION AND SIX FOOT HOLE TESTING

Subdivision Name Rivermont View County Hardy

Total Number of Lots 73 Name of Applicant David Hicks

Name of Certified Installer Responsible for Testing Billy G. Hart

Installer Certification No. 54-A-87-0270 Installer Signature Billy G. Hart

	Lot No.	Percolation Test Results (Minutes Per Inch of Fall)				Average Result	Six Foot Hole Results		Date Conducted
							Depth to Water	Depth to Rock	
Class I	1	270	270	300	300	48	none	none	6-29-06
Class I	2	210	240	240	270	40	"	"	6-29-06
Class I	3	120	180	240	240	32.5	"	"	6-29-06
" I	4	210	210	240	270	38	"	"	6-29-06
" I	5	120	180	240	240	32.5	"	"	6-29-06
" I	6	240	240	270	300	43	"	"	6-29-06
" I	7	120	120	180	210	26	"	"	6-29-06
" I	8	180	210	240	240	36	none	none	6-28-06
" I	9	120	150	180	180	27	"	"	6-28-06
" I	10	150	150	180	210	28	"	"	6-28-06
" I	11	120	120	180	210	30	"	"	6-28-06
" I	12	150	150	180	180	27	"	"	6-28-06
Class I	13	240	270	270	300	46	"	"	6-28-06
" I	14	150	180	180	210	29	"	"	6-28-06
" I	15	210	210	240	240	37.5	"	"	6-27-06
" I	16	240	270	270	300	46	"	"	6-27-06
" I	17	270	270	300	330	49	"	"	6-27-06
" I	18	240	270	300	300	47	"	"	6-27-06
" I	19	210	240	270	270	41	"	"	6-27-06
Class I	20	150	150	180	180	27	"	"	6-27-06
" I	21	180	210	210	240	35	"	"	6-27-06
" I	22	180	210	240	240	36	"	"	6-26-06
" I	23	210	210	240	270	38	"	"	6-26-06
" I	24	210	240	240	270	40	"	"	6-26-06
" I	25	240	270	270	300	46	"	"	6-26-06

(Attach additional pages if needed)