

STATE OF TEXAS WELL REPORT for Tracking #422177

Owner: **Debra Anderson**

Owner Well #: **No Data**

Address: **125 CR 215B
Llano, TX 78643**

Grid #: **57-12-4**

Well Location: **.2 mi. N of CR 215 on 215B; 100' W in
pasture
Llano, TX**

Latitude: **30° 48' 32" N**

Longitude: **098° 36' 18" W**

Well County: **Llano**

Elevation: **No Data**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **5/10/2016**

Drilling End Date: **5/10/2016**

Borehole:

<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
9.5	0	43
6.75	43	44
6	44	160

Drilling Method: **Air Hammer**

Borehole Completion: **Filter Packed**

Filter Pack Intervals:

<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Filter Material</i>	<i>Size</i>
24	43	Gravel	3/8"

Annular Seal Data: **No Data**

Seal Method: **Poured**

Distance to Property Line (ft.): **No Data**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Pitless Adapter Used**

Water Level: **27 ft. below land surface on 2016-05-10**

Packers: **No Data**

Type of Pump: **Submersible**

Pump Depth (ft.): **160**

Well Tests: **Jetted** **Yield: 20 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
42	No Data
100	good (580 ppmTDS)

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**

**111 E. Grayson St.
Llano, TX 78643**

Driller Name: **James Caleb Virdell**

License Number: **59342**

Comments: **Open Hole 44-160'**

Report Amended on 5/27/2016 by Request #17938

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	2	Topsoil
2	7	Brown Clay
7	42	Metamorphic Gravel & Clay
42	160	Black & White Metamorphic w/Red Streaks

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
6		New Plastic (PVC)	sch 40	-2	34
6	Perforated or Slotted	New Plastic (PVC)		34	44

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**