TEXAS ASSOCIATION OF REALTORS®

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2018

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

								Operation plans de la company					THE PERSON NAMED IN		The state of the s			
CONCERNING THE PR	ROPI	ERT	Y A	Γ	2	90	9	CR	22	20	> /	4	Ł	10 Tx	7645	7		_
CONCERNING THE PROPERTY AT 2909 CR 726 HIGO TX 76457 THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER'S AGENTS, OR ANY OTHER AGENT.																		
Seller is is not occupying the Property. If unoccupied (by Seller), how long since Seller has occupied the Property? (approximate date) or never occupied the Property																		
Section 1. The Proper	ty h	as ti	ne it	tems	s ma	arke	d bel	ow: (Mark	Yes ((Y),	No	(N),	or l	Unknown (U).) & will not conve	<i>/</i> .		
Item	Υ	N	U	1	Ite					Y	N	U	Г	Item			NI.	
Cable TV Wiring	1	14	-	1	_		Drong	ane Gas:		V	IN	U	-		nn grinder	Y	N	U
Carbon Monoxide Det.	10			1				nity (Captiv	and the second	-	V		-	Pump: sur	np grinder	V	_	
Ceiling Fans	1				_				ve)	, /	-		-	Rain Gutters		1/	_	-
Cooktop	1				-LP on Property Hot Tub		-	7			-	Range/Stove		V	_			
Dishwasher	V				-		m Sy	ctom	\rightarrow	1	_		-	Roof/Attic Ver	nts	1	/	-
Disposal	1/	\vdash			_	crow		Stelli	-	1	_		H		4	1		-
Emergency Escape	1	\vdash					or Gri	1	-+	V			H	Smoke Detec		1/		_
Ladder(s)		~			Oi	itaoc	JI GIII				/			Smoke Detec Impaired	tor - Hearing		1	/
Exhaust Fans	1				-		eckir)			/				Spa		المد	V	
Fences	V				Pl	umbi	ng Sy	/stem		/				Trash Compa	ctor	V		/
Fire Detection Equip.	1				Po	ol					/			TV Antenna			1	
French Drain	/	V			Po	ol E	quipn	nent			V			Washer/Dryei	Hookup	V	/	
Gas Fixtures	V				Po	ol M	aint.	Accessorie	S		V			Window Scree	ens	V		/
Natural Gas Lines		V			Po	ol H	eater				/			Public Sewer	System		1	
Item			+	Y	N	U				V Section	Λ	dditi	on	al Information				
Central A/C		*****	_	1/			1/6	electric o	gas r	num			-					
Evaporative Coolers			-	-	/	+-		ber of units		Idii	IDCI	OI UI	mo	-		-		
Wall/Window AC Units					/			ber of units	Name and Address of the Owner, where		-		-			-		
Attic Fan(s)					1/	1		s, describe										
Central Heat				. /			-		jas r	num	her	of u	nite	d		-		
Other Heat				1	s/	1	- December -	s, describe		Turr	1001	Oi di	1110	-/-				
Oven				1	/		-	ber of over	_	1	1	ele	ctri	c gas of	ther:			
Fireplace & Chimney				/				vood v ga			mo	-		The second secon	be CONVI) R	10	Λ
Carport					V			ttached	not a	-	-	_		Oi. Eriro	0 C C C C C C C C C C C C C C C C C C C		- 1 -	D
Garage		-		1/			-	ittached		attached								
Garage Door Openers			+	1/				ber of units	-	number of remotes:								
Satellite Dish & Controls				1						ed from: Direct TV						-		
Security System								THE RESERVE TO THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW	eased			-	1		,		-	-
Solar Panels				1	owned leased f									- 1 (- W/C		-		
				THE REAL PROPERTY.		jas					numb	er of units:	-					
Water Softener			V	_					other:number of units:d from:								-	
Other Leased Items(s) Vifyes, describe:																		
(TAR-1406) 02-01-18 COBB PROPERTIES, 300 N 3rd Street C	cranfills				y: B	uyer		1	with Internal	d Se	eller:	ne: 972	989-5	, Fax: 972	Pa -534-1732		1 of 5	

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

Stefanie Cobb Tai Cobb Klam

Ceilings Doors Foundation / Slab(s) Interior Walls Windows Other Structural Components	Concerning the Property	at												_
Item Y N Saement Y N	Underground Lawn Sprin	kler		N	T I/a	utom	natic	manual	area	s cc	vere	ed:		
Value supply provided by:citywellMUDco-opunknownother: Value the Property built before 1978?yes/ nounknownother: (If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards). ((If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards). ((If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards). ((If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards). ((If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards). ((If yes, attach TAR-1414)) ((If yes, attach TAR-1414)) (If yes, attach TAR-1906 concerning lead-based paint hazards). ((If yes, attach TAR-1414)) ((If yes, attach TAR-1906) concerning lead-based paint hazards). ((If yes, attach TAR-1906) concerning lead-based paint or Lead-Based Pt Hazards). ((If yes, attach TAR-1906) late of the property located in 100-year Floodplain ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)). (If yes, attach TAR-1414) located in Floodway ((If yes, attach TAR-1414)).				1	if yes	s, att	tach I	nformation .	Abou	ıt O	n-Si	te Sewer Facility (TAR-1407)		
titem	Water supply provided by Was the Property built be (If yes, complete, sig Roof Type:M	r: city efore 197 n, and af f covering unknown	tach	TAF	es / no R-1906 cor ne Propert	cerr / y (sl	ning le Age: hingle	ead-based p	cove	haz ring	pla	ced over existing shingles		
Floors F	aware and No (N) if you	are no	tawa	of ar		or n	nalfu	nctions in			he f			
Basement Cellings Doors Driveways Electrical Systems Exterior Walls If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary): Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes Y in Frevious Fooding in the Structures Page 2 of Interrited Previous Flooding on the Property Interror Walls Walls / Fences Windows Other Structural Components Windows Other Structural Components Interrited Additional sheets if necessary): Condition Y in Previous Condition Y in Previous Repairs Previous Repai		Y	-	-					·	_	1	144.11		1
Condition Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes Fluming Systems Roof Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes Y) if you are aware and No (N) if you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Internitent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Previous Flooding into the Structures Previous Flooding onto the Property Previous Flooding into the Structures Previous Flooding into the Str	Basement		V	/ }		- 10	lob/s	.)	\vdash	-	1			
Doors Driveways Electrical Systems Exterior Walls If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary): Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes Vy) if you are aware and No (N) if you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Active infestation of termites or wDI Previous Flooding onto the Property Previous Flooding onto the Property Located in Historic District And Seller. Other Structural Components Other Structural Components Internit version and Seller. Other Structural Components Other Structural Components Internit version and Seller. Other Structural Components Other Structural Repairs Previous Foundation Repairs Previous Head Repairs Previous Foundation Repairs Previous Foundation Rep	Ceilings		4	1			olab(s	5)	-	-	1			/
Exterior Walls If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary): Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.) Condition Condition V N Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Improper Drainage Intermittent or Weather Springs Intermittent or Weather Springs Intermittent or Weather Springs Intermittent or Usead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Improvements encroaching on othe	Doors		1	/					-	1			1	/
Exterior Walls If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary): Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Intermittent or Weather Springs Intermittent or Weather Springs Incoachments onto the Property Improvements encroaching on others' property Improvements encroaching on others' property If yes, attach TAR-1414) Located in 100-year Floodplain (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Condition Previous Foundation Repairs Previous Gother Structural Repairs Previous Foundation Repairs Previous Foundation Repairs Previous Foundation Repairs Previous Foundation Repairs Previous Gother Structural Repairs Previous Gother Structural Repairs Previous Foundation Repairs Pre	Driveways		1						-	V	1/	Office of dottal and compositions	+	
If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary): Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees:			-			Sys	tems		-	-	1		+	\vdash
Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Initialed by: Buyer: All No. (Y) if you are aware and No (N) if you are aware and seller: Aluminum Wiring Previous Foundation Repairs Previous Gheating Previous Cherists Previous Poundation Repairs Previous Roof Repairs Previous Soundation Repairs Previous Gheating Previous Cherists Previous Soundation Repairs Previous Poundation Repairs Previous Flooding Not Previous Place Soundation Water Penetration Water Penetra	Exterior Walls		V	1						1	7			
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District (CAR 1408) C2-01-18 Initialed by: Buyer: Previous Foundation Repairs Previous Roof Repairs Previous Cother Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unnecorded Easements Unrecorded Easements Urrea-formaldehyde Insulation Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Previous Flooding onto the Property Previous Flooding onto the Property Intermited Insulation Previous Flooding onto the Property Previous Floodi	Section 3. Are you (S you are not aware.)	eller) av	vare	of a	ny of the	folio	owing			лагі	(re	s (1) Il you are aware and		
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Lead-Based Paint or Lead-Based Pt. Hazards Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAP 1406) 02.01.18 Previous Goff Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Located in Historic District TAP 1406) 02.01.18 Initialed by: Buyer: Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District Previous Flooding onto the Property Located in Historic District	Condition					Y	N					-	1	IN
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAP 1406) 02.01.18 Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Located in Historic District TAP 1406) 02.01.18 Initialed by: Buyer: Previous Roof Repairs Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Unrecord	Aluminum Wiring						14		_		_		+	+
Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAR 14060 02-01-18 Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Unrecorded Easements Urea-formaldehyde Insulation Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Finoding onto the Property Located in Historic District TAR 14060 02-01-18 Initialed by: Buyer: Previous Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Underground Storage Tanks Underground Storage Tanks Underground Storage Tanks Unrecorded Easements Unrecor							1						+	1
Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAR 1406 02-01-18 Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Located in Historic District TAR 1406 02-01-18 Initialed by: Buyer: Page 2 of 1		wilt					V			her	Stru	ctural Repairs	+	+
Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAR 1406 02-01-18 Hazardous or Toxic Waste Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Flooding onto the Property Located in Historic District TAR 1406 02-01-18 Initialed by: Buyer: Page 2 of 1	Endangered Species/H	abitat on	Pro	perty	/		1						+	1
Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires Page 2 of 1	Fault Lines					_	V						+	+
Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAR 1406) 02-01-18 Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite of, WDI damage repaired Previous Fires Page 2 of states and Seller: Page 2 of states and Seller and Seller: Page 2 of states and Seller and Seller	Hazardous or Toxic Wa	ste				_	V					or Dita	+	+
Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAR 1406) 02-01-18 Unplatted Easements Unrecorded Easements Unrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite of WDI damage repaired Previous Fires Page 2 of section of termites or WDI Previous termite of WDI damage repaired Previous Fires Page 2 of section of termites or WDI Previous termite of WDI damage repaired Previous Fires Page 2 of section of termites or WDI Previous termite of WDI damage repaired Previous Fires Page 2 of section of termites or WDI Previous termite of WDI damage repaired Previous Fires						_	V				_		+	1
Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District TAR 1406) 02-01-18 Unrecorded Easements Urea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or, WDI damage repaired Previous Fires Page 2 of section of the Property Previous Fires Page 2 of section of the Property Previous treatment for termites or WDI Previous Fires Page 2 of section of the Property Previous Fires Page 2 of section of the Property Previous treatment for termites or WDI Previous Fires Page 2 of section of the Property Previous treatment for termites or WDI Previous Fires Page 2 of section of the Property Previous treatment for termites or WDI Previous Fires Page 2 of section of the Property Previous Fires Page 2 of section of the Property Previous Fires Page 2 of section of the Property Previous treatment for termites or WDI Previous Fires Previous Fires	Intermittent or Weather	Springs				1	V						+	1
Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Urea-formaldehyde Insulation Water Penetration Wetlands on Property Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or, WDI damage repaired Previous Fires Page 2 of State of Target 14080 02-01-18 Initialed by: Buyer: Page 2 of State of Target 14080 02-01-18 Urea-formaldehyde Insulation Water Penetration Wetlands on Property Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires Page 2 of State of Target 14080 02-01-18	Landfill					_	1						+	+
Improvements encroaching on others' property Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or, WDI damage repaired Previous Fires Page 2 of State Penetration Water Penetration Wetlands on Property Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires Page 2 of State Penetration Property Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires Page 2 of State Penetration				t. Ha	zards	1	11						+	1
Located in 100-year Floodplain (If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Page 2 of State of TAR-1406 (92-01-18) Previous Fires Page 2 of State of TAR-1406 (92-01-18)	Encroachments onto the	e Prope	rty			_	1/					Insulation	+	1
(If yes, attach TAR-1414) Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Page 2 of Section 1985 (Previous Fires) Previous Fires Page 2 of Section 1985 (Previous Fires)	Improvements encroad	hing on	other	rs' pi	roperty	_	1/					-4.	+	+
Located in Floodway (If yes, attach TAR-1414) Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Page 2 of Seller: Page 2 of Seller:							1/	vvetian	as o	n Pi	ope	ity		1/
Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or, WDI damage repaired Previous Fires Page 2 of Seller: Page 2 of Seller:	(If yes, attach TAR-141	(4)				+	1	10/a a d I	7-4				+	+
(If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District (If yes, attach TAR-1414) Previous Flooding into the Structures Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Previous Fires Page 2 of Structures	Located in Floodway (I	f yes, att	ach	TAR	-1414)	+	1					Et mites or other wood	+	+
Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Previous treatment for termites or WDI Previous termite or WDI Previous termite or WDI Previous termite or WDI Previous termites or WDI Previ	Present Flood Ins. Cov (If yes, attach TAR-141	rerage 14)					/	destroy	ing i	inse	cts ((WDI)	_	
Previous Flooding onto the Property Located in Historic District Previous fermite or WDI damage repaired Previous Fires Previous Fires Previous Fires Prage 2 of and Seller:			cture	es			1/						+	
Located in Historic District Previous Fires Page 2 of Seller:							1/				e or	WDI damage repaired	+	+
Page 2 of Seller: , and Seller: Page 2 of Seller:							/	Previo	us Fi	res	1	1 00/		
			Init	ialed	by: Buyer:			and	Sell	er:	10	1 1	_	2 of

FORMS

Concerning the Property at	2909	CR L	26	HICO	TX 764.	57	
Historic Property Designation	Ann		Termite o	r WDI damage	e needing rep	air	IV
Previous Use of Premises for Ma of Methamphetamine		1		ockable Main [1
If the answer to any of the items	in Section 3 is ye	es, explain (a	ttach additio	nal sheets if n	ecessary):		
*A single blocka Section 4. Are you (Seller) aw which has not been previous	able main drain m are of any item, ly disclosed in 1	equipment,	or system i	n or on the P	Property that	is in need of	f repair,
necessary):							
Section 5. Are you (Seller) av not aware.) Y N Room additions, stru	uctural modification	ons, or other	alterations of	or repairs mad	de without ned		
unresolved permits, Homeowners' assoc	or not in compliar iations or mainter ation:	nce with build nance fees o	ding codes ir r assessmer	n effect at the nts. If yes, con	time.	owing:	
Fees or assessr Any unpaid fees	nents are: \$ or assessment for s in more than on	or the Proper	ty? yes (\$aı	nd are: ma	andatory voo	
Any common area (with others. If yes, co Any optional use		ving:					interest
Any notices of violate Property.	ions of deed rest	rictions or go	vernmental	ordinances at	ffecting the co	ondition or us	e of the
Any lawsuits or othe to: divorce, foreclosu				fecting the Pro	operty. (Includ	des, but is no	t limited
Any death on the Pr to the condition of the		those death	s caused by	r: natural caus	ses, suicide, o	or accident ur	nrelated
Any condition on the	Property which r	naterially affe	ects the heal	th or safety of	an individual		
		d-based pair ther documer	nt, urea-form ntation identi	aldehyde, or r	mold.		
Any rainwater harve water supply as an a			roperty that i	is larger than	500 gallons a	nd that uses	a public
/ The Property is locat	ed in a propane g	as system se	rvice area o	wned by a pro	pane distribut	ion system re	tailer.
Any portion of the Pr	operty that is loca	ated in a grou	undwater co	nservation dis	trict or a subs	idence distric	t.
a	Initialed by: Buyer:		and Se	(Bo	Paç FORMS	ge 3 of 5

Concerning the Pro	porty at	04 CR226	100	
				necessary):
				6
Section 6. Seller	has has no	attached a survey of the P	roperty.	
Section 7. Within regularly provide i	the last 4 years	s, have you (Seller) received	any written inspe spectors or other	ection reports from persons who rwise permitted by law to perform
Inspection Date	Туре	Name of Inspector		No. of Pages
Mark that the same of the same				
	1			
Section 8. Check	Property. A buy	rely on the above-cited reports a er should obtain inspections from on(s) which you (Seller) curre	m inspectors chose ently claim for the	en by the buyer. Property:
Homestead		Senior Citizen	<u></u> <u></u> <u></u> <u></u> <u></u> <u></u>	isabled
vviidilfe ivian Other:	1.5	Agricultural		isabled Veteran nknown
		ever filed a claim for d	amage to the	Property with any insurance
provider? yes _i Section 10. Have y insurance claim or	no you (Seller) eve	r received proceeds for a cla	aim for damage t	Property with any insurance to the Property (for example, an proceeds to make the repairs for
provider? yes _i Section 10. Have y insurance claim or	no you (Seller) eve	r received proceeds for a cla award in a legal proceeding)	aim for damage t	to the Property (for example, an proceeds to make the repairs for
provider? yes _i Section 10. Have y insurance claim or	no you (Seller) eve	r received proceeds for a cla award in a legal proceeding)	aim for damage t	to the Property (for example, an proceeds to make the repairs for
provider? yes _ Section 10. Have y insurance claim or which the claim was	no you (Seller) eve r a settlement or as made?ye he Property ha hapter 766 of th	r received proceeds for a classification and legal proceeding) in o If yes, explain: ve working smoke detectors e Health and Safety Code?*	aim for damage t and not used the installed in acco	to the Property (for example, an proceeds to make the repairs for
Section 10. Have y insurance claim or which the claim was section 11. Does to requirements of C (Attach additional statements) *Chapter 766 of installed in account including performance including performance including performance including including performance i	he Property ha hapter 766 of the Health and Scordance with the ormance, location,	r received proceeds for a classification and legal proceeding) in o If yes, explain: ve working smoke detectors e Health and Safety Code?*	installed in acco	proceeds to make the repairs for example, an a proceeds to make the repairs for example, an a proceeds to make the repairs for example, an a proceeds to make the repairs for example, an a proceeds to make the smoke detector yes. If no or unknown, explain. It have working smoke detectors in which the dwelling is located, the building code requirements in
Section 10. Have y insurance claim or which the claim was section 11. Does to requirements of C (Attach additional slab) *Chapter 766 of installed in account including perform of the seller to installer to instal	no rou (Seller) ever a settlement or as made?yes the Property hat hapter 766 of the Health and Secondance with the ormance, location, area, you may check the equire a seller to in a licensed physistall smoke detect	received proceeds for a classification of the control of the contr	installed in account wo-family dwellings to the area of you do not know the call building official for grimpaired if: (1) the layer gives the seller to effective date, the benefices the locations	proceeds to make the repairs for example, an proceeds to make the repairs for example and proceeds to make the repairs for example and proceeds to make the repairs for yes. If no or unknown, explain. It is to have working smoke detectors in which the dwelling is located, the building code requirements in the remove information. It is to the proceeds to make the requirements in the proceeds of the buyer's the written evidence of the hearing output makes a written request for the for installation. The parties may
Section 10. Have y insurance claim or which the claim was section 11. Does to requirements of C (Attach additional slandled in account including performance of the seller to in agree who will seller acknowledge.	no rou (Seller) ever a settlement of as made?yes the Property hat hapter 766 of the Health and Secondance with the formance, location, area, you may check equire a seller to in a licensed physicatall smoke detect bear the cost of insects that the statement of the statement	received proceeds for a classification of the hearing impaired and specially in the large in the hearing impaired and specially in the hearing in t	installed in account wo-family dwellings to the area of you do not know the cal building official for a grimpaired if: (1) the layer gives the seller are effective date, the benefices the locations of brand of smoke determined to the seller's	proceeds to make the repairs for example, an proceeds to make the repairs for example and proceeds to make the repairs for example and proceeds to make the repairs for yes. If no or unknown, explain. It is have working smoke detectors in which the dwelling is located, the building code requirements in a more information. It is to have working smoke detectors in which the dwelling is located, the building code requirements in a more information. It is to the proceeds to make the repairs for more information. The parties may extectors to install. It is to the proceeds to make the repairs for installation. The parties may extectors to install.
Section 10. Have y insurance claim or which the claim was section 11. Does to requirements of C (Attach additional slandled in account including performance of the seller to in agree who will seller acknowledge the broker(s), has in a clauding a clauding the seller to in agree who will seller acknowledge the broker(s), has in a clauding a clauding the seller to the seller to in agree who will seller acknowledge the broker(s), has in a clauding the seller to th	he Property ha hapter 766 of the Health and Scordance with the ormance, location, rea, you may check the licensed physicatall smoke detect bear the cost of install smoke detect bear the statement or influence or i	received proceeds for a classical award in a legal proceeding) in o If yes, explain: re working smoke detectors e Health and Safety Code?* y): afety Code requires one-family or trequirements of the building code is and power source requirements. If a unknown above or contact your located smoke detectors for the hearing lling is hearing-impaired; (2) the botain; and (3) within 10 days after the coars for the hearing-impaired and spotalling the smoke detectors and while the inceed Seller to provide inaccurate.	installed in account of a more and not used the installed in account of a more and a mor	proceeds to make the repairs for example, an proceeds to make the repairs for example and proceeds to make the repairs for example and proceeds to make the repairs for yes. If no or unknown, explain. It is have working smoke detectors in which the dwelling is located, the building code requirements in a more information. It is to have working smoke detectors in which the dwelling is located, the building code requirements in a more information. It is to the proceeds to make the repairs for more information. The parties may extectors to install. It is to the proceeds to make the repairs for installation. The parties may extectors to install.
Section 10. Have y insurance claim or which the claim was section 11. Does to requirements of C (Attach additional slawled in account including performance of the seller to in agree who will seller acknowledge.	he Property ha hapter 766 of the Health and Scordance with the ormance, location, rea, you may check the licensed physicatall smoke detect bear the cost of install smoke detect bear the statement or influence or i	received proceeds for a classical award in a legal proceeding) in o If yes, explain: re working smoke detectors e Health and Safety Code?* y): afety Code requires one-family or trequirements of the building code is and power source requirements. If a unknown above or contact your located smoke detectors for the hearing lling is hearing-impaired; (2) the botain; and (3) within 10 days after the coars for the hearing-impaired and spotalling the smoke detectors and while the inceed Seller to provide inaccurate.	installed in account wo-family dwellings to the area of you do not know the cal building official for a grimpaired if: (1) the layer gives the seller are effective date, the benefices the locations of brand of smoke determined to the seller's	proceeds to make the repairs for example, an proceeds to make the repairs for example and proceeds to make the repairs for example and proceeds to make the repairs for yes. If no or unknown, explain. It is have working smoke detectors in which the dwelling is located, the building code requirements in a more information. It is to have working smoke detectors in which the dwelling is located, the building code requirements in a more information. It is to the proceeds to make the repairs for more information. The parties may extectors to install. It is to the proceeds to make the repairs for installation. The parties may extectors to install.
Section 10. Have y insurance claim or which the claim was section 11. Does to requirements of C (Attach additional slandled in account including performance of the seller to in agree who will seller acknowledge the broker(s), has in a clauding a clauding the seller to in agree who will seller acknowledge the broker(s), has in a clauding a clauding the seller to the seller to in agree who will seller acknowledge the broker(s), has in a clauding the seller to th	he Property ha hapter 766 of the Health and Scordance with the ormance, location, rea, you may check the licensed physicatall smoke detect bear the cost of install smoke detect bear the statement or influence or i	received proceeds for a classical award in a legal proceeding) ye working smoke detectors to Health and Safety Code?* y): afety Code requires one-family or the requirements of the building code is and power source requirements. If the unknown above or contact your located smoke detectors for the hearing liling is hearing-impaired; (2) the both constant of the smoke detectors and white the s	installed in account of a more and not used the installed in account of a more and a mor	to the Property (for example, an proceeds to make the repairs for yes. If no or unknown, explain. It have working smoke detectors in which the dwelling is located, the building code requirements in reproduce of the buyer's rewritten evidence of the hearing proceeding to the parties may refer to installation. The parties may refer to install. It is to the Property (for example, and proceeds to the sample of the sectors in which the smoke detectors in which the dwelling is located, and the support of the buyer's refer to installation. The parties may refer to install. It is to the Property (for example, and proceeds to make the repairs for which the smoke detectors in which the dwelling is located, are building to the buyer's repairs for installation. The parties may refer to install.

Signature of Buyer

Printed Name:

(TAR-1406) 02-01-18

2989 CR 226

Hicolx

Date

Page 5 of 5

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TAR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

(6)	The following providers currently provide service to the Property:		
	Electric: /witeb ro-op	phone #:	965-3153
	Sewer:	phone #:	
	Water: Drilles DALton Drilling	phone #:	386-3915
	Cable: Direct TV, WIFI PENTURY LINE	phone #:	
	Trash: AUAILAble	phone #:	
	Natural Gas:	phone #:	
	Phone Company:	phone #:	4 2.1
	Propane:	phone #:	9.65-2384
	Internet: Link	phone #:	* /
(7)	This Seller's Disclosure Notice was completed by Seller as of the date as true and correct and have no reason to believe it to be false or ins AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.		
The	undersigned Buyer acknowledges receipt of the foregoing notice.		

Date Signature of Buyer

Initialed by: Buyer:

Printed Name:



TEXAS ASSOCIATION OF REALTORS®

INFORMATION ABOUT ON-SITE SEWER FACILITY

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS® IS NOT AUTHORIZED.

©Texas Association of REALTORS®, Inc., 2004

CC	INCERNING THE PROPERTY AT 2909 C/2 226, HICO, Tx	76457
	DESCRIPTION OF ON-SITE SEWER FACILITY ON PROPERTY:	
	(1) Type of Treatment System: Septic Tank Aerobic Treatment	Unknown
	(2) Type of Distribution System: LAtenal Lines	Unknown
	(3) Approximate Location of Drain Field or Distribution System: WSW of Home	Unknown
	(4) Installer:	Unknown
	(5) Approximate Age:	Unknown
B.	MAINTENANCE INFORMATION:	
	(1) Is Seller aware of any maintenance contract in effect for the on-site sewer facility? If yes, name of maintenance contractor: Phone: Contract expiration date: Maintenance contracts must be in effect to operate aerobic treatment and certain non-sessewer facilities.)	Yes No
	(2) Approximate date any tanks were last pumped?	
	(3) Is Seller aware of any defect or malfunction in the on-site sewer facility? If yes, explain:	☐Yes √No
	(4) Does Seller have manufacturer or warranty information available for review?	Yes No
G.	PLANNING MATERIALS, PERMITS, AND CONTRACTS: (1) The following items concerning the on-site sewer facility are attached: planning materials permit for original installation final inspection when OSS maintenance contract manufacturer information warranty information	SF was installed
	(2) "Planning materials" are the supporting materials that describe the on-site sewer submitted to the permitting authority in order to obtain a permit to install the on-site sewer	facility that are er facility.
	(3) It may be necessary for a buyer to have the permit to operate an on-site transferred to the buyer.	sewer facility
(TA	R-1407) 1-7-04 Initialed for Identification by Buyer, and Seller,	Page 1 of 2
COBE	B PROPERTIES, 300 N 3rd Street Cranfills Gap TX 76637 Phone: 972-989-5220 Fax: 972-534-173	32 FORMS

D. INFORMATION FROM GOVERNMENTAL AGENCIES: Pamphlets describing on-site sewer facilities are available from the Texas Agricultural Extension Service. Information in the following table was obtained from Texas Commission on Environmental Quality (TCEQ) on 10/24/2002. The table estimates daily wastewater usage rates. Actual water usage data or other methods for calculating may be used if accurate and acceptable to TCEQ.

Facility	Usage (gal/day) without water- saving devices	with water-
Single family dwelling (1-2 bedrooms; less than 1,500 sf)	225	180
Single family dwelling (3 bedrooms; less than 2,500 sf)	300	240
Single family dwelling (4 bedrooms; less than 3,500 sf)	375	300
Single family dwelling (5 bedrooms; less than 4,500 sf)	450	360
Single family dwelling (6 bedrooms; less than 5,500 sf)	525	420
Mobile home, condo, or townhouse (1-2 bedroom)	225	180
Mobile home, condo, or townhouse (each add'l bedroom)	75	60

This document is not a substitute for any inspections or warranties. This document was completed to the best of Seller's knowledge and belief on the date signed. Seller and real estate agents are not experts about on-site sewer facilities. Buyer is encouraged to have the on-site sewer facility inspected by an inspector of Buyer's choice.

Signature of Seller	5-/3-/9 Date	Seluda), Signature of Seller	Callaway 5-13-1 Date
Receipt acknowledged by:			
Signature of Buyer	Date	Signature of Buyer	Date