SS 177 Revised I-71

WEST VIRGINIA SEPTIC TANK INSPECTION FORM

Hampshire County Health Department Installation Permit No. 57-14-77-246
Name of Owner KNODEL, ADOLPH
Address HILLSBORD ROAD, PURGITSVILLE MARY LAN
Property Address TWIN RIDGE SUB-DIVISION-LOT NO.3:7MILES SOUT
Type Facility Served TRAILER No. Water Closets Lot Size 67-ACRES Lot Size 67-ACRES Source of Water Supply WELL No. Lavatories
No. Bedrooms No. Showers or Tubs No. Baths
No. Garbage Grinders No. Automatic Washers
SEPTIC TANK
Material CONCReTeLength x Width x Depth = cubic feet
Liquid Depth ft. Liquid Capacity gal. Distance to: Dwelling 50 Water Supply 100 Nearest Property Line 300 Plu
SOIL ABSORPTION SYSTEM
Type Drain Line Material $P/AsT/c$ Trench Width $36 \approx 1$ Inches
Trench Depth 30 Inches Total Absorption area in Trench Bottom 600 sq. ft.
Diameter of Drain Line 4 Inches Type Filter Media 9RAVC/
No. of Drain Lines 2 Depth Filter Media Under Drain Line 6 Inches
Length of Each Line 100,100, , ft. Depth Filter Media Over Drain Line 2 in
Distance of Disposal Field to: (a) Dwelling Zo
(b) Water Supply 120' (c) Nearest Property Line 300' PLU 5
An inspection of the septic tank system described herein disclosed that said system (MEETS, DOBS NEET) the minimum standards established by the West Virginia State Department of Health. Nov 15 1977 Sanitarian Sanita

SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.