

Well #1 on Ranch

STATE OF TEXAS WELL REPORT for Tracking #79041

Owner:	Carlton Hagelstein	Owner Well #:	No Data
Address:	906 hagelstein Blanco, TX 78606	Grid #:	57-61-5
Well Location:	906 Hagelstein same, TX 78606	Latitude:	30° 02' 36" N
Well County:	Blanco	Longitude:	098° 27' 09" W
		Elevation:	No Data
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Start Date: **3/20/2006**

Drilling End Date: **3/23/2006**

Borehole:

Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
8.75	0	50
8	50	500

Drilling Method: **Air Rotary**

Borehole Completion:

Annular Seal Data:

Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
0	50	8 cement

Seal Method: **Gravity**

Distance to Property Line (ft.): **1000**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **500**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **visual**

Surface Completion: **Pitless Adapter Used**

Water Level: **240 ft. below land surface on 2006-03-23** Measurement Method: **Unknown**

Packers: **rubber 50,300**

Type of Pump: **Submersible** Pump Depth (ft.): **440**

Well Tests: **Jetted** **Yield: 15 GPM after 1 hours, no drawdown specified**

Water Quality:

Strata Depth (ft.)

380-440

Water Type

Lower glenrose

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Martinez Water Well**

**1146 Crown Dr.
Bulverde, TX 78163**

Driller Name: **Jose V Martinez**

License Number: **2872**

Comments: **No Data**

Lithology:

DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:

BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	160	Tan lime
160	240	Lt.gray lime shale st.
240	320	Lt.gray lime
320	380	Lt.gray lime very few intermittent frac.
380	440	Lt.gray lime few intermittent frac.
440	500	Lt.gray lime

Dia. (in.)	New/Used	Type	Setting From/To (ft.)
5	new	sdr-21 plastic	0-320 blank
320-500	.030		

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**

Well #2

STATE OF TEXAS WELL REPORT for Tracking #77953

Owner:	Carlton Hagelstein	Owner Well #:	No Data
Address:	1484 Hagelstein Blanco, TX 78606	Grid #:	57-61-5
Well Location:	1484 Hagelstein same, TX 78606	Latitude:	30° 02' 54" N
Well County:	Blanco	Longitude:	098° 26' 44" W
		Elevation:	No Data
Type of Work: New Well		Proposed Use: Domestic	

Drilling Start Date: **3/2/2006**Drilling End Date: **3/7/2006**

Borehole:

<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
8.75	0	50
8	50	600
6.75	600	780

Drilling Method: **Air Rotary**

Borehole Completion:

Annular Seal Data:

<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
0	50	5cement

Seal Method: **Gravity**Sealed By: **Driller**Distance to Property Line (ft.): **1000**Distance to Septic Field or other
concentrated contamination (ft.): **1000**Distance to Septic Tank (ft.): **No Data**Method of Verification: **visual**Surface Completion: **Pitless Adapter Used**Water Level: **405 ft. below land surface on 2006-03-07** Measurement Method: **Unknown**Packers: **rubber 50,400**Type of Pump: **Submersible**Pump Depth (ft.): **580**Well Tests: **Jetted****Yield: 14 GPM after 1 hours, no drawdown specified**

Water Quality:

Strata Depth (ft.)	Water Type
660-700	Lower Glenrose

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Martinez Water Well**
1146 Crown Dr.
Bulverde, TX 78163

Driller Name: **Jose V Martinez**

License Number: **2872**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	107	Tan lime
107	360	Lt.gray lime few shale st.
360	415	Lt.gray lime
415	440	Lt.gray lime few intermitten frac.
440	490	Lt.gray lime
490	520	Lt.gray lime few intermitten frac.
520	660	Lt.gray lime
660	700	Lt.gray lime few intermitten frac.
700	780	Lt.gray lime

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia. (in.)	New/Used	Type	Setting From/To (ft.)
5	new	plastic sch.40	0-400 blank
400-760	.030		
760-780	blank		