Man age

WV STATE DEPARTMENT OF HEALTH Office of Environmental Health Services ENVIRONMENTAL ENGINEERING DIVISION

SW258

WELL COMPLETION REPORT

Date(s) 5/20/96 Co	ounty HA	Ampshire Permit #: DW-14-04-96-209
Town:Ar	ea Name/Locatio	tion Mt Top Oxoperties Lot 5
Well Owner: John & Mayrine	Mazze	ED Address: 6519 40th Ave
Telephone Number: 927 - 59:		
Well Driller: B. Mark SMO	th	Address: HC 86 Box 2-A
Telephone Number: 822-4786		
WELL LOG		*)
DEPTH IN FEET FORMATIONS: KIND, THICKNESS, AND IF W	ATER BEARING	REMARKS:
0-4 Soil + Boulders		Type of Well: Nome Drilling Method: Art Hammac
5-17 hard white Sandrock		Well Diameter: 6/18" Casing O.D.: 5/8"
18-70 Juft yellow Shale		Well Depth: 510 Date Completed: 5/20/96
71-197 hard red Shale		CASING: Length 84 Feet Height above ground Feet
198- Week 1460	92)	Steel Plastic Cast Iron
199-484 hard gray Sar	rdoved	Other
US/ 18/19/25 OF	= red	Туре
Shale		SCREEN
485 Water		None Installed
486-510 hard black Sand		Type Diameter
tock.		Slot/Gauge Length
		Set Between Ft. and Ft.
PUMPING OR BAILING TEST		WELL HEAD
DETAILS #1	#2 #3	Pitless Adapter: Type, Make, Etc.
Static Water Level (Ft. Below Grade)	st	Well Cap: Type, Make, Etc. Standard
Pumping Rate (GPM) 40)	Well Seal: Type, Make, Etc.
Pumping Level (Ft Below Grade) 46	0	Well Platform:
Duration of Test (In Hours)		Length Width Thickness
Recovery Time to Static Level (In Hours)	2	Grouting: Tes D No All Public Water Supplies must be grouted. Pressure
hereby certify that this well was drilled and const s true to the best of my knowledge and belief.	ructed under my	B. Mark Suth #00/ Negge. W. Sm. th WII Drilling Certification No.
		Registered Business Name Signed Number South 5/20/96 Date

Virginia State Department of Health.

SS-177 Revised 1-71 WEST VIRGINIA SEPTIC TANK INSPECTION FORM Health Department Installation Permit No. 57-14-96-363 Name of Owner Address 65/9 Property Address > DESCRIPTION & NUMBER OF UNITS SERVED Type Facility Served Mo. Water Closets Lot Size 20 sq. ft. Area suitable for sewage disposal installation ____ sq.ft. Source of Water Supply 118 No. Lavatories No. Bedrooms 3 No. Showers or Tubs ____ No. Baths _ No. Garbage Grinders O No. Automatic Washers / SEPTIC TANK Material Contrete Length ___ x Width ___ x Depth ___ = ___ cubic feet Liquid Depth ____ ft. Liquid Capacity ____ /000 ___ gal. Distance to: Dwelling 20' Water Supply 100'+ Nearest Property Line 100'+ SOIL ABSORPTION SYSTEM Type Drain Line Material Moullow Trench Width 24 Inches Trench Depth 30 Inches Total Absorption area in Trench Bottom 900 sq. ft. Diameter of Drain Line 10 Inches Type Filter Media No. of Drain Lines 3 Depth Filter Media Under Drain Line Length of Each Line /00,/00, /00, ft. Depth Filter Media Over Drain Line ____in. Distance of Disposal Field to: (a) Dwelling 50' (b) Water Supply 100' + (c) Nearest Property Line 100' + An inspection of the septic tank system described herein disclosed that said system (MEETS, DOES NOT MEET) the minimum standards established by the West

SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.

