

TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 * PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Cartificate of Campliance

WPI-8	
Date of Construction: 12-01-2004	
Application ID: 391570 Certificate Number: 33	1021
Occupancy Type: Residential Building Type: He	ouse
Certificate Type:	
Certificate Detail:	
Certificate Date:	
Appointed Qualified Inspector/TDI Inspector:	
New New (Entire Building) December 13, 2005 A	ppointed Qualified Inspector REVISED
CERTIFICATE	
Location of Property to be Insured:	
Street:	
Lot:	
Block: Tract or Addition:	
39 LA BUENA VIDA DRIVE	
City:	
County:	
State: ARANSAS PASS ARANSAS TEXAS	
Outside City Limits Inland I - INLAND I - 2000 IRC Intl Resid	dential Code

2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.