SS-177 Revised 1-71

## WEST VIRGINIA SEPTIC TANK INSPECTION FORM

	Nampaline (Aunty Health Department Installation Permit No. 5/14-11-130
	Name of Owner John Koupp
	Address 37/3 M. Abbe Rd. Onlington, VA 22267
	Property Address Quasings Lot # 45
	DESCRIPTION & NUMBER OF UNITS SERVED
	Type Facility Served No. Water Closets
	Lot Size sq. ft. Area suitable for sewage disposal installation sq.ft
	Source of Water Supply No. Lavatories
	No. Bedrooms No. Showers or Tubs No. Baths
	No. Garbage Grinders No. Automatic Washers
	SEPTIC TANK
	Material Concrete Length x Width x Depth = cubic feet
	Liquid Depth ft. Liquid Capacity gal.
	Distance to: Dwelling // Water Supply // Nearest Property Line
	SOIL ABSORPTION SYSTEM
	Type Drain Line Material Trench Width Inches
	Trench Depth 22-24 Inches Total Absorption area in Trench Bottom 20 sq. ft.
	Diameter of Drain Line 10 Inches Type Filter Media
	No. of Drain Lines Depth Filter Media Under Drain Line Inches
	Length of Each Line /00,/00,/00, ft. Depth Filter Media Over Drain Linein
	Distance of Disposal Field to: (a) Dwelling
	(b) Water Supply _/OO (c) Nearest Property Line/O
	An inspection of the septic tank system described herein disclosed that said system (MEETS, DOES NOT MEET) the minimum standards established by the West Virginia State Department of Health.
9	9-10-92 Lee Dara
	Date Sanitarian

## SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.

Capon River