

87 Acres

STATE OF TEXAS WELL REPORT for Tracking #521994

Owner:	Randall Jones	Owner Well #:	No Data
Address:	3702 Bobby Jones Way Round Rock, TX 78664	Grid #:	56-06-7
Well Location:	see cordinates Mason, TX	Latitude:	30° 53' 45.53" N
Well County:	Mason	Longitude:	099° 20' 52.33" W
		Elevation:	No Data
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Start Date: **8/12/2019** Drilling End Date: **8/12/2019**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	9	0	18
	6.25	18	485

Drilling Method: **Air Hammer; Air Rotary**

Borehole Completion: **Open Hole**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	-5	18	Bentonite 2 Bags/Sacks
	-5	-2	Cement 1 Bags/Sacks

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **50+**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **190 ft. below land surface on 2019-08-12** Measurement Method: **Steel Tape**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Jetted** **Yield: 50+ GPM**

	<i>Strata Depth (ft.)</i>	<i>Water Type</i>
Water Quality:	405 - 485	No Data
		Chemical Analysis Made: No
	Did the driller knowingly penetrate any strata which contained injurious constituents?: No	

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill** License Number: **4168**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	1	Topsoil
1	22	White Limestone
22	90	Gray Limestone
90	485	Red & Tan Sandstone

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
6	Blank	New Plastic (PVC)	40	-2	18

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540